

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 20 S. T. S. R. 11 W R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

~~1/4~~ Corner Sections 24 and 25. T20-12W  
Set on line between the Sec. Cors. & at the proportioned dist.  
~~1/4~~ Corner is a 1" brass capped pipe witnessed by:  
5" Alder S. 5° W., 9.0 ft.  
Spruce Stump N.85°E., 12.0 ft.

~~CS 1/4~~ Center of Section 24. Should be T20-12W  
1" Brass capped pipe witnessed by:  
36" Doug. Fir N.28°E. 29.0 ft.  
48" Doug. Fir S.27°W. 4.0 ft.

Center of Section 18, T20-11W. 27  
Marked by an 1" iron pipe with bell filled with lead &  
witnessed by a: 64" Spruce Stump S.12 1/2°W. 43.35 ft.  
60" Spruce stump N.29 1/2°W. 14.7 ft.  
(as shown in field notes of previous survey)  
I mark: 6" Spruce S.66°W., 21.8 ft.  
This corner is about 100 ft. East of the County Road.

~~1/4~~ Corner to Sections 7 and 18. 28  
I establish from the stump of the Orig. BT. S.83°W. <sup>#78</sup> 27.06 ft.  
The BT. S.18 1/2°E., 31.02 ft. is gone. The corner lays on the  
cut slope of a cat road in a clear cut area. The stumps to  
the North are too rotten to hold a scribe.  
The corner point is marked with a 1" brass capped pipe.

~~Section Corner to Sections 24 and 25 only, T20-12W. #214 29  
This corner lays 40 ft. East of a small creek and 37 ft. South of  
a logging road up the S. side of Perkins Creek. The corner  
is witnessed by the stumps of the original spruce tree to  
the East, which were: 40" Spruce N.15°E., 25.08 ft.  
24" Spruce S.35°E., 38.28 ft.  
I set a new corner with a 1" brass capped pipe.~~

~~1/4~~ Section Corner betwn. Sections 5 and 6. 30  
At this corner I find the bearing tree described as a 12" Fir  
bearing East 9 links showing original marks. 85  
Set - Cedar Post 4 x 4" mkd: C S and mkd new BT's. as follows:  
18" Fir mkd. C S B T bears N.33°W. 12.9 ft.  
16" Fir mkd. C S B T bears S.12 1/2°E. 16.3 ft.  
18" Fir which seems to have been marked as a bearing tree  
bears N.75°W. 8.6 ft.

~~1/4~~ Section Corner on the South Bdy. of Sec. 32, T19S R11W. <sup>#170</sup> 31  
At this corner I find an iron pipe, in order to verify  
this pipe I chopped outh the marks of the bearing tree described  
as a 6" Fir, now 30" Fir, and found the original marks.  
From said Iron Pipe this tree bears N.51°E. 73 lks.  
Find no trace of Alder bearing Tree.

Township Corner Secs. 1-6-36-31, T19 & T20S., R's. 11 & 12W. 32  
Found - 36" D. Fir N.49 1/2°E. 7.3 ft., cut open & fd. good scribing, "T19SR".  
Remnant of Alder stump N.47°W. 24.4 ft., small fragment of  
reverse scribing on overgrowth of old face.  
No trace of S. E. or S. W. Bearing Trees.  
Set - Brass Cap at Cor. Mkd: Co. Surveyor's Office, 1964  
Blaze & Rescribe - 36" D. Fir N.49 1/2°E. 7.3 ft. Mkd:  
T19S R11W S31 CS BT.  
New BT's: 26" D. Fir S.50°E. 11.0 ft. Mkd: T20S R11W S6 CS BT.  
36" D. Fir S.35°W. 14.0 ft. Mkd: T20S R12W S1 CS BT.  
No. tree available to N.W. - Twp. Corner is on nose of small, very steep,  
spur, sloping N.E.

Warren D. Hootman  
For Crown Zellerbach Corp.  
January 30, 1963  
C. S. File No. 51/249 Map File M 22 - 36

Warren D. Hootman  
1/30/63  
C.S. 51/249  
M 22 - 36

G. H. Waggoner, Deputy Co. Surv.  
Lane County  
Wit: C. Johnson & Wm. Gibson  
April 16, 1934  
C. S. File No. 53/1

Milo E. Godfrey & Crew  
Doug. Co. Park Dept.  
Aug. 17, 1964  
C. S. File No. 53/65

FD. OK 5/27/80  
S. AURAND  
C.S. 6/1/6