

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 20 S. T. S. R. 11 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Vernon "Ray" Tracy  
Jack Heritage & E. West  
March, 1967  
C.S. File No. 54/1

45

Closing Township Corner.  
Found-Orig. 40"?, now 22" Fir stump, N. 6° E. 21.1 ft., shows "SR11WS" on opened blaze, probably 14" when mkd. Ring count 60+ years.  
Orig. 40", now 48" Fir, tipped-out stump laying face down, N. 43° W. 20.5 ft.  
No trace of S. E. BT.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1967 T 20 S CC R12W S 31 R11W T 21 S S 6  
New BT: 30" D. Fir Stump S. 20° E. 6.3 ft. mkd. T21S R11W S6 CC CS BT.  
No other stumps or trees close.  
Note - This corner lies on very steep, NE slope, approx. 195 ft. S. of Township Corner of T. 20 & T. 21 S., R. 12 W., see below.  
Brass Cap set on East Side & under 30" Log. # 224

46

Township Corner - T 20 S R12W S 36 R11W T 21 S S 1  
Found - Orig. 15", now approx. 30" Fir, N. 5 1/2° E. 28.4 ft., now shattered stump with "T20S 11W 31 BT" scribe revealed.  
Orig. 15", now 30" Fir 20' high snag, S. 85° W. 40.9 ft., shows scar.  
Orig. 12", now 18" badly decayed Fir stump with frag. reverse scribe marks, N. 8 1/2° W. 31.7 ft. No trace of BT.  
Unrecorded 40" Fir Stump bears N. 48° E. 40.1 ft. mkd. "S31 BT". # 225  
New BT: 24" Hemlock N. 15 1/2° E. 30.1 ft. mkd. "T20S R11W S31 CS BT."  
No other trees close.  
Note - This corner lies on moderate SE slope approx. 100 ft. S. of top of ridge. C.C., see above, bears S. about 195 ft. This area logged in recent years.

MICROFILM TO HERE 10/67

47

Section Corner to Secs. 19 & 30, T20-10W. & Secs. 24 & 25, T20-11W.  
Found - Orig. 40", now 48" Fir, badly decayed stub, N. 76° E. 9.2 ft., no scribe found.  
Orig. 12", now 38" Fir, alive, S. 3° E. 69.3 ft., old scar, opened previously, about 8" to false face.  
Orig. 7", now 34" Fir, alive, S. 61 1/2° W. 29.0 ft., opened & find, "T20" scribe & reverse under 70+ rings.  
Orig. 8", now 40" Fir, alive, N. 2° W. 70.6 ft. We do not open.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 R T20S R 11 S 24 S 19 10 W S 25 S 30 W  
New BT's: 7" D. Fir S. 83° W. 21.7 ft. mkd. T20S R11W S25 CS BT.  
12" D. Fir N. 29° W. 27.8 ft. mkd. T20S R11W S24 CS BT.  
14" Maple N. 4° E. 24.6 ft. mkd. T20S R10W S19 CS BT.  
14" Maple S. 62° E. 26.5 ft. mkd. T20S R10W S30 CS BT.  
Note - Corner lies 30 ft. east of spur, sloping north.

FDOK PER STUTZNER M 109-13 OCT 1989

48

Township Corner: T20S & T21S. - R10 & 11W.  
Found - 3/4" I. Pipe & BT's. as shown in Ren. #2, T20-10W. & Ren. #21, T20-11W.  
20", now 28" Maple, alive, N. 14° W. 15.2 ft., shows good scar. Do not open.  
4", now 40" Fir, alive, S. 77° E. 42.9 ft., faint scar. # 209  
(Rescribed: "T21S R10W S6 CS BT")  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 T20S 11 S 36 S 31 10 T21S W S 1 S 6 W  
(Deposit old pipe alongside)  
New BT: 14" D. Fir N. 80° E. 83.6 ft. mkd. T20S R10W S31 CS BT.  
This corner lies on very steep S. slope about 300 ft. N. of Smith River Rd.

RENEWED CORNER NO. 209

49

Sec. Cor. to Secs. 13 & 24, T20-11W.  
Found - Unrecorded 1 1/4" I. Pipe at corner point.  
Orig. 36", now 48" Fir, alive, S. 81° W. 9.9 ft., shows bark scribe in poor condition. Rescribe: "T20S R11W S24 CS BT". # 118  
Orig. 15", now 30" Fir, N. 74° W. 8.6 ft., alive, shows good scar. Do not Open.  
No trace of Orig. Corner Tree nor other Orig. BT's. T 20 S  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 R S 13 R 11W S 24 10W  
New BT: 15" Cedar N. 56° W. 25.6 ft. mkd. T20S R11W S13 CS BT.  
Note - This corner lies on steep E. slope about 100 ft. above creek, course N. & 99.3 ft. N. 3 1/2° E. of C.C. to Secs. 18 & 19, T20-10W, See Ren. #50.

RENEWED CORNER NO. 118

Vernon "Ray" Tracy  
Jack Heritage & V. Perron  
March & April, 1968  
C.S. File No. 53/66