

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 11 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

50

Closing Corner to Sections 18 and 19, T20-10W.
Found - 1/2" I. Pipe on N.-S. line, unrecorded, not at point for Closing Cor.
Orig. 6", now 18" Maple, alive, N. 85° E. 39.6 ft. Open & find frag. scribe.
on decayed axe blaze. Rescribe: "CC S18 CS BT".
Orig. 6", now 14" Chittam decayed stub, hollow center, S. 76° E. 26.4 ft. C.S.
No scribe. No trace of other Orig. BT's. F
Set - Brass Cap at Cor. Mkd: County Surveyor's R C | S18 R I
Office, 1968 11W C | S19 10W L
New BT: 28" Maple S. 21° E. 41.7 ft. mkd. T20S R10W S19 CC CS BT. E
Note - This corner lies 99.3 ft. S. 3 1/2° W. of Secs. 13 & 24, T20-11W. 53/66
1/2" I.P. bears N. 85° E. 6.2 ft., creek course N. about 125 ft.
east of closing corner.

4/12/68

Closing Corner for Sections 7 and 18, T20-10W. 51
Found - 24"x20"x10" S.S. mkd. "CC+" & 2 notches on N. edge and
4 notches on south edge, firmly set and in place.
Orig. 18", now 46" Fir, alive, S. 10° E. 10.6 ft., shows good scar.
We Rescribe: "T20S R10W S18 CC CS BT".
Orig. 10", now 28" Fir, alive, N. 36° W. 29.0 ft., shows faint scar.
We Rescribe: "CC CS BT".

Set - Brass Cap in place of Rock & Mkd: R T 20 S R
County Surveyor's 11 CC | S 7 10
Office, 1968 W | S 18 W
New BT: 8" Hemlock N. 45° E. 39.2 ft. mkd. T20S R10 W S 7 CC CS BT.
Note - This corner lies on top of spur ridge, sloping N., approx.
495 ft. S. of corner of secs. 12 & 1e, T20-11W., see below.

52

Witness Corner to Sections 12 and 13, T20-11W.
Found - Orig. 18", now 26" Fir Corner Tree, now dead Snag, leaning
badly with very poor bark scribe.
Orig. 30", now 60" Fir, alive, S. 71 1/2° E. 9.9 ft., shows fair
bark scribing.
Orig. 30", now 64" Cedar, Alive, S. 34 1/2° W. 41.6 ft., shows
faint scar. We do not open.
Orig. 12", now 16" Cedar, 5' high Stub, N. 82° W. 14.5 ft.,
blazes rotted out, no scribing found.
Set - Wit. Cor. 10 ft. W. of True Cor. Mkd: R T 20 S R
County Surveyor's 11 | S 12 | 10
Office, 1968 W | S 13 | W
Wit. Cor. 10' E. to Corner
New BT: 40" Cedar N. 26° W. 18.5 ft. mkd. WC T20S R11W S12 CS BT.
64" Cedar (Orig. BT) S. 29 1/2° W. 35.9 ft. mkd. W.C. T20S R11W S13 CS BT.
Note - This cor. lies on steep N. slope, approx. 100' E. & 150' S. of
creek, course N.E. & approx. 495' N. of CC. Secs. 7 & 18, See above.

53

Section Corner to Sections 14 - 15 - 22 - 23.
Found - 30" D. Fir, now stump, N. 85° E. 12.5 ft., burnt face,
"BT" visible, opened more for other scribe.
36" D. Fir, now stump, N. 41° W. 9.2 ft., shows scar.
Also call on spring branch of 66.0 ft. S. of corner fits very good. #117
Set - Brass Cap at Cor. Mkd: County Surveyor's T 20 S R 11 W
Office 1968 S 15 | S 14
S 22 | S 23
New BT: 60" D. Fir Stump N. 6 1/2° E. 46.8 ft. mkd: T20S R11W
S14 CS BT.
Note - This corner lies in clear cut unit.
66.0 ft. North of Spring Branch.
West to Spring Branch.
330.0 ft. approximately west of ridge top.
All Stumps tagged on top and side.

9/17/68

Vernon "Ray" Tracy
Jack Heritage & V. Perron
May, 1968
C. S. File No. 53/66

RE-RENEWED CORNER