

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 11 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91881

66

1/4 Corner to Sections 8 and 17.
Found - 1923 2" Iron Pipe very badly rusted, Ren. #13.
26", now 26" Alder, S. 55° E. 46.8 ft., scribe visible.
9", now 13" Alder, N. 29° E. 13.7 ft., scribe visible.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 20 S R 11 W
Office 1/4 S 8
1969 S 17
New BT's: 13" Hemlock S. 85° W. 16.7 ft. mkd: "1/4 S17 CS BT".
14" Spruce N. 77° W. 49.0 ft. mkd: "1/4 S 8 CS BT".

9/23/69

67

1/4 Corner to Sections 17 and 18.
Found - 1 1/2" Iron Pipe at 1/4 Corner, See Ren. #15.
10" Hemlock, now stump, S. 4° E. 39.3 ft., scribe visible.
26" D. Fir, now stump, S. 79° W. 19.9 ft., scribe visible.
New BT: 9" Hemlock S. 21° E. 58.0 ft. mkd: "1/4 S17 CS BT".
No other trees available.
This corner lies about 50' south & 50' west of ravine.

9/22/69

68

Section Corner to Sections 16 - 17 - 20 - 21.
Found - No record of any corner monument, See Ren. #16.
24" Hemlock, now stump, S. 34° E. 28.5 ft., scribe visible.
18" Cedar, now stump, S. 73° W. (Rec. S60W) 69.2 ft., scribe visible.
16" Maple, now down, N. 41° E. 34.3 ft.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 20 S R 11 W
Office S 17 | S 16
1969 S 20 | S 21

New Bearing Stump: 30" Hmlock Stump N. 72° E. 45.7 ft. scribed "T20S R11W
S16 CS BT". Stump is on top small ridge running N.
This corner lies in clear-cut on very steep N.W. slope, about 50' E. ravine.

9/24/69

69

1/4 Corner to Sections 10 and 15.
Found - Orig. 30" D. Fir, now stump, N. 58° W. 29.0 ft., faint bark scribe.
No trace of Alder Bearing Tree.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 20 S R 11 W
(Steel Fence Post alongside) Office 1/4 S 10
1969 S 15

New BT's: 48" D. Fir N. 88° E. 178.8 ft. mkd: "1/4 S10 CS BT".
48" D. Fir S. 64° E. 184.0 ft. mkd: "1/4 S15 CS BT".

This corner lies in fairly flat area in old unit.

Tom McCullough, Apr. '70 (Set a fence post with sign ± 5 ft. N. facing W. (55/148) 9//25/69

70

Section Corner to Sections 9 - 10 - 15 - 16.
Found - No trace of 2" Iron Pipe set by Cole as corner falls in deep
cut of skid road, See Ren. #6.
8" Hemlock, now rotten stump, S. 62° W. 9.9 ft., found reverse scribe.
3 other Alder Bearing Trees not found.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 20 S R 11 W
Office S 9 | S 10
1969 S 16 | S 15

New BT's: 4" Hemlock S. 29° W. 14.4 ft. mkd: "S16 CS BT".
4" Hemlock N. 76° E. 13.0 ft. mkd: "S10 CS BT".
4" Hemlock N. 53° W. 9.4 ft. mkd: "S 9 CS BT".
No other trees available in area.

This corner lies about 50 ft. N. of ridge & 250 ft. S. of draw running E-W.
Also in skid road running N - S. ± 5' N. facing E.) C.S. 55/148 9/25/69

Tom McCullough, Apr. '70 (Set two fence posts with signs ± 5' W. facing S.)

71

1/4 Corner to Sections 16 and 17.
Found - No trace of Iron Pipe or 16" Hemlock West 13.7 ft., See Ren. #17.
36" D. Fir, now stump, N. 85° E. 20.0 ft., opened for scribe.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 20 S R 11 W
Office, 1969 1/4 S 17 | S 16

New BT: 12" Hemlock N. 29° E. 23.6 ft. mkd: "1/4 S16 CS BT".
No other trees available.

This corner lies in clear-cut unit about 70 ft. N. of ravine on steep
south slope. 9/24/69

John M. Powell
Frank Jones & W. Penley
September, 1969
C.S. File No. 53/66

RE-RENEWED, SEE CORNER NO. #213