

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 11 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21891

85

1/4 Corner to Sections 5 and 6.
Found - Unrecorded 1 1/4" Steel Shaft set for Cor. with 4"x4" white painted cedar post & BT's., as follows:
Orig. 12", now 28" Fir, badly decayed, East 5.9 ft., scribe marks visible.
18", now 24" Fir, 20 ft. high snag, N. 33° W. 12.9 ft., shows scar.
16", now 26" Fir Stump, S. 12 1/2° E. 16.3 ft., shows scar.) See Ren. #30
A Stump N. 75° W. 8.6 ft., but is not a Bearing Tree.)
WE DO NOT SET BRASS CAP.
New BT's: 9" Alder N. 45° W. 16.0 ft. mkd: "1/4 S6 CS BT" (on bark)
8" Alder S. 26° W. 13.9 ft. mkd: "1/4 S6 CS BT" (in wood)
7" Alder S. 70° E. 11.1 ft. mkd: "1/4 S5 CS BT" (in wood)
5" Alder N. 34° E. 14.5 ft. mkd: "1/4 S5 CS BT" (on bark)

FR 12/23/67
D. BAKER
M 105-40

2/25/70

86

Section Corner to Sections 4 - 5 - 8 - 9.
Found - Cedar Post, in place, & BT's. as follows: (See Ren. #10)
22", now 24" D. Fir, alive, N. 4° E. (Rec. N6E) 74.5 ft., scribe visible on nearly healed blaze.
21", now 23" Alder, alive, S. 60 1/2° W. 31.5 ft. scribe visible on healing blaze.
14", now 17" Cedar, alive, S. 28° E. (Rec. S32E) 42.5 ft., nearly healed blaze.
N.W. Alder Bearing Tree gone.
Orig. 36" Cedar BT to N.W. still in evidence.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 20 S R 11 W
(Reset Cedar Post alongside) Office S 5 | S 4
1970 S 8 | S 9

#134

No suitable trees to N.W. for New BT.
Corner lies on steep N.E. slope 66 ft. N. of top of spur sloping E. & 40 ft. S. of canyon, course East. (C.S. 55/148)
4/1970 - Set fence post with signs + 5 ft. west facing north. 2/24/70

Vernon "Ray" Tracy
Jack Heritage & V. Perron
February, 1970
C.S. File No. 53/66

87

Section Corner to Sections 5 - 6 - 7 - 8.
Found - Orig. 8", now 30" Fir Stump, S. 43° W. 8.6 ft., prev. opened & rehealed. We tag on top.
Orig. 7", now 30" Fir Stump, S. 16° E. 6.6 ft., prev. opened nearly rehealed. We tag on top.
Orig. 6", now 18" Fir, Snag 12 ft. high, N. 69 1/2° E. 13.9 ft., find reverse scribe on piece of reverse blaze from inside.
No trace of Alder Orig. BT. to N.W.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 20 S R 11 W
Office S 6 | S 5
1970 S 7 | S 8

#135

New BT's: 24" Spruce N. 48° E. 28.8 ft. mkd: "T20S R11W S 5 CSBT".
20" Alder N. 23° W. 36.0 ft. mkd: "T20S R11W S 6 CS BT".
No trees to S.E. or S.W. This corner lies on top of spur, sloping N. 3/31/70

88

Section Corner to Sections 2 - 3 - 10 - 11.
Found - Corner Stone, in place, mkd. with 5 notches on S. & 2 notches on E. edges.
Orig. BT's. as mkd. by F.W. Rase in 1916 when surveying R.F.S. #190.
Orig. 10", now 19" Fir, alive, S. 36 1/2° E. 25.1 ft., shows good scar, we tag.
Orig. 10", now 25" Fir, alive, N. 19 1/2° W. 10.6 ft., shows good scar, we tag.
Orig. BT's. to N.E. & S.W. down & decaying.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 20 S R 11 W
Office S 3 | S 2
1970 S 10 | S 11

#172

Mark New BT. out of area to be clear cut:
36" D. Fir S. 88° W. 59.0 ft. mkd: "T20S R11W S10 CS BT".
This corner lies on N.W. slope approx. 30 ft. south & 40 ft. west of top of spur ridge sloping N.W. No trace of Orig. Alder BT's.
4/1/70