

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. E. 11 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

94

Renew Corner # 4, H. E. S. 190.
Found - Remains of old cedar Corner Post, badly decayed, in place.
Orig. 10", now 16" Maple, down-badly decayed, S. 78° E. 9.2 ft., We
open & find edge of axe blaze with possible reverse scribe.
Orig. 24", now 34" Fir, alive, N. 84° E. 41.6 ft., shows good scar, we tag.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 20 S R 11 W
Office, 1970 #4 HES 190
New BT: 15" Maple S. 53° E. 9.2 ft. mkd: "4 HES 190
CS BT".
This corner lies on very steep northerly slope 225 ft. W. of creek.

95

Renew Corner #5 of H. E. S. 190.
Found - Mound of Stone, probable Corner Stone, in place, no marks found.
Orig. 8", now 8" Dead Fir Snag, badly decayed, S. 68 1/4° W. 17.2 ft.,
scribe "X5 HES 190 BT" visible on unhealed blaze.
Orig. 12", now 12" Dead Fir, S. 20 1/2° W. 15.2 ft., scribe "X5 HES 190 BT"
visible on unhealed blaze.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 20 S R 11 W
Office # 5 HES 190
1970
New BT's: 16" D. Fir N. 88° E. 32.4 ft. mkd: "5 HES 190 CS BT"
16" D. Fir N. 14° E. 29.1 ft. mkd: "5 HES 190 CS BT".
This corner lies on point of spur, sloping N.W.

96

Renew Corner #6 of H. E. S. 190 - N. 1/16 S10.
Found - Remains of old Cedar Post, in place,
Orig. 12", now 20" Fir, alive, N. 65° E. 31.7 ft., shows old scar &
some more recent chopping, we tag.
Orig. 8", now 14" Fir, down, N. 50 1/4° W. 11.2 ft., open & scribe visible
on open blaze.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 20 S R 11 W
Office N 1/16 Cor. #6 HES 190
1970 Sec. 10
New BT's: 24" Spruce S. 36° W. 27.0 ft. mkd: "6 HES 190 N 1/16 S10 CS BT".
14" D. Fir N. 50° W. 33.8 ft. mkd: "6 HES 190 N 1/16 S10 CS BT".
This corner lies on very steep N.E. slope, approx. 50 ft. W. of small
ravine, course north.

97

1/4 Corner to Sections 29 and 32.
No evidence of Original survey found. - Prorated corner.
Set - 2"x30" galvanized iron pipe with a brass cap, 24" in the ground
mkd: 1/4 Cor.
I stamped the disk . . . T20S R11W
1/4 S 29
1/4 S 32
1970 LS 536
From the pipe monument, I marked new BT's:
23" Hemlock bears S. 3° W. 22.4 ft.
21" Hemlock bears N. 25° 30' E. 44.3 ft.

98

1/4 Corner to Section 1 only.
No evidence of original corner found.
At the properly proportioned position I placed a 3" x 36" galv. I.P.,
flanged at the bottom and capped with a bronze disk welded on top,
The monument projects 6" above ground. I filled in around the
pipe monument with stone and packed earth.
I stamped the disk: 1/4 S1
1971
4185
I established new bearing trees as follows. Each bearing tree has a
scribed face and a U.S.F.S. bearing tree sign breast high and facing
the monument.
Set: a 16" fir bears N 82° W 31.00 feet.
an 18" fir bears N 57° W 42.18 feet.

Vernon "Ray" Tracy
Jack Heritage & V. Perron
April 11, 1970 C.S. File No. 53/66

Stuslaw Nat'l. Forest
Glenn S. Baughman
April 11, 1970
C.S. 55/147 M 39-48

MARCH 71
James W. Prochnau
For U.S. Forest Service
May 1971 Rev. Aug. 1971
C.S. File 55/201
Map File 41 - 77
Revised M 43 - 56

RENEWED TELEPHONE #115

Jan. 1973