Douglas County Surveyor's Record of Government Corners Renewed

T 20 S. T.S. R. 12 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21981

CONTINUED:
New BTs- 10" Fir stump, "X" chop, tag, bears N.08°E. 3.52 ft. 125
18" Fir stump, "X" chop, tag, bears S.85°W. 15.40 ft.
Set Bearing Object - 4 ft. aluminum post bears N.23°E 2.0 ft.
Set - 3/4" x 30" iron rod, set inside iron pipe, with 2" alum. cap marked: ¼
S15 | S14
1992
LS 1342

¼ Corner for Sections 10 and 15. 126
Found - 1½" inside diameter rusted iron pipe. Ren. # 113.
36" rotten original Spruce stump bears N.21°W. 15.0 ft.
16" Spruce, dbl. trunk with pk nail, bears N.01°E. 16.0 ft.
24" rotten Fir stump, no tag or marks, bears N.79°30'E. 24.9 ft.
11" Fir with pk nail, "X" chop at breast height, tag, bears S.81°E. 9.6 ft. to pk nail.
14" Hemlock with pk nail, "X" chop at breast height, tag bears S.25°30'E. 2.85 ft. to pk nail.
24" rotten Orig. Fir stump, no marks or tags, bears S.65°E. 13.2'
12" Fir stump with pk nail in center bears S.53°30'W. 10.55 ft. to pk nail.
Set - 3/4" x 30" iron rod w/2" alum. cap marked: ¼
S10
S15
1992
LS 1342

Stuntzner Engr. & Forestry
Ronald Stuntzner
November 15, 1992
M 116 - 32

¼ Corner for Sections 10 and 11. 127
Found - 1½" inside dia. iron pipe. Ren. #68.
46" rotten Orig. Spruce stump with visible scribe bears S.16°E. 10'
22" Hemlock with healed face & tag bears S.81°30'E. 15.35 ft.
12" Fir with healed face & tag bears S. 51°30'W. 18.4 ft.
Set - 3/4" x 30" iron rod (set inside iron pipe) with 2" alum. cap marked: ¼
S10 | S11
1992
LS 1342

CORNER REPORT ONLY. 128
Section Corner for Sections 1,2,11, and 12.
Found - 3½" alum. cap on 2" inside dia. alum. pipe per BLM. Ren. 114.
74" Spruce, visible scribe in rotten face, tag, bears N.88°W. 130.73 ft.
14" rotten Spruce stump, visible scribe, tag, bears S.05°W. 69.04 ft. (M8-38, S05°E. 68.1 ft.).
15" Spruce with healed face, tag, bears S.04°W. 50.66 ft.
16" Spruce with healed face, tag, bears S.07°E. 59.6 ft.
A stumb that is possible remnants of a 10" Spruce, now 6" stub, bears S.40°E. 40.81 ft.
Found BO's-1½" inside dia. iron pipe bears S.30°E. 19.7 ft.
Power pole, visible scribe "S1 RE 4079 BP", bears N.24°E. 25.0 ft.

Closing Corner for Sections 18 and 19 T20S R11W only. West side. 129
Found - 1½" iron pipe 5.5' above ground. Ren. No. 35
30" Doug. fir N 20°E 52.8' (Org. unkown)
24" Doug fir N 36°W 55.0' (Org unknown)
1½" iron pipe N 9°W 36.4' (Org. unknown)

John Minor
For: Menasha Corp.
Feb 1993
M 116 - 56

2/93