Douglas County Surveyor's Record of Government Corners Renewed

T 20 S T. S. R 12 W R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21091

Robert Ward, L.S. #1091
For: Suislaw National Forest &
Tahkenitch Tree Farm Partnership
April 1995
M 122 - 3 A & B & M 122 - 4

149

Meander Corner North of Cor. Secs. 15, 16, 21, & 22
Found - 2" Rusted pipe set by Corbitt (Ren. # 83)
12" Rotted Spruce stump, bears N.27°W. 13.2' to face vis. scribing.
40" Rotted Spruce stump, bars N.5°E., 9.0' to face, no scribing.
Set - 8'x3/4" aluminum rod with 3" Alum. cap into center of 2" rusted pipe, cap mkd:

T20S R12W
S16 | S15
MC
1994
LS 1091

BTs - 12" Spruce, bears N.35¼°W., 31.7', scribed: "T20S R12W S16 MC BT".
24" Hemlock, bears N.51½°E., 56.4', scribed: "T20S R12W S15 MC BT".
Both BTs have brass washer stamped "LS 896" nailed to center of lower face on New BTs.

150

Cor. Secs. 33, 34 & 3, & 4 T21-12
Found - 30" Rotted Spruce mound with a pitched slab scribed "BT" with chaining notch below (Rec. N.43°W., 25.1')
50" D.Fir, stump with what appears to be a X chopped across the healed blaze, I did not open (Rec. S.30°W., 16.5')
Set - At intersection of record distances as determined from where the orig. face would have been, I set a 2½"x30" Aluminum corner monument w/cap stamped:

T20S R12W
S33 | S34
S 4 | S 3
T21S
1994
LS 1091

BTs - 30" Rotted spruce mound, bears N.46¼°W., 27.7'
50" D.Fir stump, bears S.27¼°W., 16.9'
22" Hemlock stump, bears N.47½°E., 22.9'
16" D.Fir stump, bears S.48¼°E., 8.7'
Note - I drove a 5/8"x30" rebar with cap marked LS 1091 into the center of each stump.