

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 12 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97401

Closing Corner to Sections 7 and 18, T20-11W
Found - 1 1/2" Iron Pipe & BT's., as called for in Ren. #9., T20-11W.
48", now 54" Fir, alive, N. 52° W. 108.0 ft., shows good scar, we tag.
7", now 9" Spruce, dead & decaying, S. 60° W. 10.2 ft. scribe visible.
Orig. 16" Alder snag, N. 69° E. 23.3 ft., scribe visible by #399.
S.E. bearing tree gone.
New BT's: 22" Spruce N. 43° E. 31.4 ft., mkd: "T20S R11W S7 CC CS BT".
20" Spruce S. 63° E. 62.5 ft. mkd: "T20S R11W S18CC CS BT".
This closing corner lies on E. edge of clear cut which extends north
to corner of secs. 12 & 13, Ren. #82, T20-11W.

RE-RENEWED, SEE CORNER NO. #111

40

Vernon "Ray" Tracy
Jack Heritage & V. Perron
March, 1970 C.S. 53/66

East 1/4 Corner to Section 12 only, T20-12W.
Found - Old 1" Bolt, badly rusted & BT's. by Lecklider, See Ren. #6.
38", now 40" Fir, alive, N. 72° W. 65.2 ft., lower blaze healed,
upper blaze, nearly healed.
6", now 12" Hemlock, alive, south 69.4 ft., blazes healed.
Set - Brass Cap at Cor. Mkd: County Surveyor's T20S R12S R11W
(Reset Old Bolt alongside) Office, 1970 1/4 S12
This cor. lies 20 ft. N. of creek bottom approx. 350 ft. E. of very
old, unusable logging road.
Found only badly decayed remains of stump of Orig. BT.

Fd. ok
7/88 D.B. Baker
M. 106-67

41

Section Corner to Sections 4, 3, 9, and 10.
Found - 1902 ? 24" Hemlock down burnt S60°E. 11.9 ft.
16" Hemlock down burnt S40°W. 17.6 ft. Old burnt axe marks
old face.
1943, 1 1/2" Iron pipe set at Section corner. See C.S. 52/91
60" Spruce stump, S2°W. 71.9 ft. No nail found.
72" Spruce stump, N30°E. 65.7 ft. No nail found.
Set - Brass Cap along side 1 1/2" I. Pipe, marked:
County Surveyor's T20S R12W
Office, 1971 S4 | S3
S9 | S10
New BT's: 14" D. Fir, S83°W. 7.6 ft. Scribed T20S R12W, S9 CS BT.
7" Cedar, N11°W. 3.1 ft. Scribed T20S R12W S4 CS BT.
10" D. Fir, N60°E. 12.7 ft. Scribed T20S R12W S3 CS BT.
8" Hemlock, S12° E. 20.8 ft. Scribed T20S R12W S10 CS BT.

FDOK
BY R. W. G. 4/95
M. 122-4

3/30/70

42

MARCH 71

1/4 Corner to Sections 3 and 10, T20S. R12W.
Found - 1943 trees and 1 1/2" I. pipe set by Corbitt. See C.S. 52/91
Cedar snag, S. 4 1/2° W. 27.3 ft. Nail in face.
Cedar stump, N. 16° E. 37.3 ft. Nail in face.
No trace of any original trees.
New BT's: 12" Spruce, S. 25° W. 17.9 ft. scribed S10 CS BT.
7" Alder, N. 34° E. 9.0 ft. scribed S3 CS BT.

RE-RENEWED, SEE CORNER NO. 50

43

John M. Powell
J. Heritage
June, 1971
C.S. File 53/66

1/4 Corner to Sections 20 and 21.
Found - 1 1/2" I. pipe at 1/4 Cor. Badly rusted. See C.S. 52/91
36" Spruce, not D. Fir Stump, S. 73° W. 5.3 ft. Previously
open scribe found part of "B".
24" Spruce, now 4' stob, N. 10° E. 11.2 ft. As noted 7.8 ft.
to boat spike in boot of tree. Set 1943 by W.G. Corbitt

AA
(Ren. #77)

Call of 1 chain, north to top of ridge, hits good.
Set - Brass cap at 1/4 corner along side I. pipe marked:
County Surveyor's T20S R12W
Office, 1971 S20 | S21

RE-RENEWED, SEE CORNER NO. 106

New BT's: 6" D. Fir, S. 87° E. 30.5 ft. scribed S21 CS BT.
16" Spruce, S. 58° W. scribed S20 CS BT.
Note: Also found, 1 1/2" I. pipe N52° E 39.0 ft.
Note: Best way to reach corner, good luck. Run south from Crown
Zellerbach gate.

6/16/71