

Douglas County Surveyor's Record of  
Government Corners Renewed

T 20

T. S.

R 12

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21891

51

Witness Corner, Sections 23 and 24.

Found - BT's at W.C. called for at 59.75 chains. As bearing & dist. to BT's did not check & no corner stone fd., I relocated W.C. on solid rock in Creek making Cross 1" deep 6" long with nail at intersection covered same with 5 rocks, top one mkd: W.C. 1943 from X bears:

Orig. 100" Spruce (really only 5 ft. DBH above spreading roots) S.3°W., 17.82 to old blazed face, 18.00 ft. to nail above blaze. Scribed face partly rotted away only marks V left which maybe part of W.C.:

Orig. 12" Alder, now 18" rotten snag with hole where scribe marks might have been., N.18°E., 50 ft. to nail in base of tree.

A sq. stake crayon mkd: 1/16 S stands N.E. about 80 ft. from W.C.

I left 1 1/2" I.P. with this stake on line N. of W.C.

3/30/43

1/4 Corner for Sections 14 and 13.

Found - Orig. BT's at 1/4 corner and relocated the corner based on dist. as bearings did not check.

Set - 1 1/2" I.P. and 2" x 3" x 4' Spruce post crayon mkd. #108 S14/S13 1943, from which:

Orig. 48" Spruce (really a 1/4S double tree 24" & 18" dead snag) N.77°30'E., 26.4 ft. to nail scribed 1/4 S BT.

Orig. 30" Spruce now 40" N.43°30'W., 21.1 ft. to nail. Scribe marks remain covered.

The 14" Hemlock BT for old corner bears N.88°E., about 70 ft.

Krugur did not find correct corner when he blazed line, 1941.

3/29/43

Section Corner for Secs. 11, 12, 13 and 14. (SEE ALSO REN. #1) ?

Set - 1 1/2" I.Pipe in place of old rotten post mkd. by Frey, 1936, & in it set 2"x2"x5' Spruce post from which:

Orig. Spruce, now 18", S.43°30'W., to nail, 11.3 ft. scribed S14 T20R12W.

Orig. Spruce now 14" snag N.46°30'E., 9.9 ft. to nail scribed S12T20R12W.

Orig. Spruce, now 48", S.59°E., 15.5' slope 51%=13.8' to nail. Blazed face covered with overgrowth.

Corner stands on NW slope about 80 ft. east of gulch.

3/29/43

Section Corner for Secs. 1,2,11,12. (SEE ALSO-REN.#3)

Found - Square Alder stake without marks, standing, presumable for corner. To preserve position of this marker, right or wrong,

I set - 1 1/2" I.P. in ground where stake stood, from which bears:

10" Maple S.30°E., 19.6 ft. scribed S12, rest rotted away. #114

32" Hemlock stump N.17°E., 15.5 ft. to 1 1/2" pipe in center of the stump. 15.2' to face of old blaze showing scribe marks / 1.

Most of inscription has been destroyed when Hemlock was cut down.

I left a 2"x2"x4 ft. cedar post here. As there is a questionable set of notes given for this corner in the line run E. btwn. 2 and 11, further info. should be obtained.

10/23/41

Section Corner for Secs. 27,26,34,35.

Found - Orig. BT's.

Set - 1 1/2" I.P. from which bears:

60" Spruce stump, N.61°W., 37 ft. marks covered.

40" Spruce stub, N.89°W., 68 ft. scribed S34 T20S R.

50" Spruce stump, S.64°E., 11.2 ft. scribed. Cruiser's mks. LB.

2/3/41

1/4 Corner for Secs. 34 and 35.

Found - Orig. BT's.

Set - 1 1/2" I.P. 2' west of 14" Spruce snag which stands for 1/4 corner from which:

Spruce snag bears: 48" Spruce stump N.45°E., 2.0 ft.

Rotten stump S.60°W., 28.5 ft.

2/4/41

W. C. Corbitt  
B Senn, Paul Krugur, N. Seethoff  
for: Crown Zellerbach  
1941 - 1943  
C.S 52/91

FD. OK  
P. Foy  
m 84-71

RE-RENEWED, SEE CORNER NO. #108  
RE-RENEWED, SEE CORNER NO. #123  
RE-RENEWED, SEE CORNER NO. #114

55

56

57

58

59