

Douglas County Surveyor's Record of  
Government Corners Renewed

T 20 T. S. R 12 R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21881

SEE REN. #81 For Additional 60  
information

Meander Corner, Sections 26 and 35.  
Found - Orig. 30" Spruce BT after cutting through 14" of overgrowth.  
From this BT. relocated the corner as the Alder was missing.  
Set - 1 1/2" I.P. and 2"x2"x5' Fir post crayon mkd: S26 M.C. 1943.  
From which: S35  
Orig. 30" Spruce, now 7' Stump, bears S.18°E., 22.44 ft to  
nail scribed R12, rest covered.  
This corner stands on steep slope 30 ft. above water.  
Note - The compass needle was not swinging freely. Bearing from pipe  
to BT should be checked with good compass.  
4/29/43

RE-RENEWED SEE CORNER NO. 132

Meander Corner, Sections 27 and 26. 61  
Relocated M.C. from tree described as 5" Spruce.  
Set - 1 1/2" I.P. and 4"x4"x5' Spruce post crayon mkd. MC 27/26 1943.  
From which bears:  
Orig. 5" Spruce, in reality a 15" Hemlock now 30" dead, S.37°E.,  
6.60 ft. to nail scribed R12 rest covered ✓  
Orig. 48" Spruce, now 6' leaner, N.55°W., 12.4 ft. to nail  
in overgrowth crayon mkd: RPBT.  
Corner is on Spruce root notched for pipe 10 ft. above water.  
4/29/43

1/4 Corner for Secs. 23 and 26. See also Ren. #15 62  
Ran east (Var.21°30'E) from Lake Tahkenitch and at 2601 ft. found a  
stake set for 1/4 cor.  
I set - 1 1/2" I.P. for corner from which:  
2"x2"x5' post - Orig. 36" Spruce (really a 44" D. Fir) S.25°W.,  
16.50 ft. to nail scribed 1/4 S. Ring count checked for orig.  
survey.

The orig. 36" Alder no longer exists therefore I mkd:  
new BT- 24" Spruce N.63°E., 29.5 ft. crayon mkd.: 1/4 S23 RP BT.  
This corner stands at head of gulch 60 ft. E. of N. & S. ridge on  
W-E-S from this corner. Cruiser's marks NE X = = ✓  
3/25/43

Meander Corner, Secs. 23 and 26 63  
Found - Orig. BT's at M.C. called for at 70.52 chains using dist.  
called for in notes. I relocated M.C. and  
Set - 1 1/2" I.P. at water's edge & 2"x3"x7' Spruce post crayon  
mkd: M.C. S23 1943 from which bears:  
S 26  
BTs - Orig. 30" Spruce, now 4' rotten stub, broken off S.80°E.,  
6.6 ft. (6.2 ft. to nail) scribed S26 T20S R12W, rest covered.  
Orig. 36" Spruce, now 5' rotten snag BF high, N.74°E., 23.76 ft.  
to nail scribed S23 T20S R12W.  
I blazed 3 ft. Hemlock S.31°E., 31.4 ft. slope 43%=28.8 ft. to nail,  
crayon mkd: S26 RP MC BT.  
I find large "B" on Spruce stump whcih I believe is the mark of Gen.  
W.H. Byers who made resurvey 1905. Timber has been logged around this  
corner. Only a few hemlock trees standing along Lake shore.  
3/25/43

Meander Corner, Sections 22 and 23. (SEE ALSO-REN. #8) 64  
Found - Rotten stumps of 2 spruce trees which fit the position of  
BT's called for in field notes. From these I relocated the  
M.C.  
Set - 1 1/2" I.P. & 2"x2"x5' Spruce post crayon mkd: Approx. M.C.  
S22-S23 1943, from which  
BT's - Orig. 30" Spruce, now only rotten stub & roots without blazes  
or scribe marks E. 40.9 ft. to stake. Set where face of  
trees was assumed to have been.  
Orig. 30" Spruce, now rotten stub & roots without blazes or  
scribe marks S.19°W., 9.90 ft. to where face of tree assumed  
to have been.  
I marked - 4' Spruce stump S.69°E., 70.5 ft. to nail set in large opening  
1 1/2" I.P. in top of this stump.  
About 8 ft. SE of this stump is 8' Spruce stump. This corner in swamp  
& sumberged when water high in lake.  
5/3/43

W.C. Corbitt  
B Senn, Paul Krugur, N. Seethoff, J.K Elliott  
for: Crown Zellerbach  
1941-43  
C.S. 52/91