

Douglas County Surveyor's Record of
Government Corners Renewed

T 20

T. S.

R 12

R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Meander Corner, Secs. 14 and 23. *(SEE ALSO - REN. # 13)*
Found - Both BT's at M.C. called for at 3415 chs.. Using dist. given in notes, the corner was relocated with:

Set - 1 1/2" I.P. & 2"x2"x5' Spruce post crayon mkd: MC $\frac{S14}{S23}$ 1943

From which bears:

Orig. 24" Fir, now(?) S23 dead, S.56°E., 3.3 ft. to nail scribed S23 T20S R12W BT cov.

Orig. 24" Fir, now dead snag, N.77°30'E., 3.96 ft. to nail scribed S14 T20S R12W BT. remains covered.

Corner stands in thick patch of Huckleberry.

3/30/43

65

1/4 Corner for Secs. 14 and 23. *(SEE ALSO - REN. # 14)*

W.G. Corbitt & J.K. Elliott measured East 390 ft. from MC. 14/23 and set 2"x2"x5' Spruce post in apprx. location of 1/4 corner 14-23 as the orig.

18" Fir BT has been pushed over in logging and moved from its orig. position, although the depression where it stood still remains. From this post bears:

30" Spruce stump N.61°E., 30.9 ft. to nail mkd: RP 1 1/2" Pipe in top of stump.

48" Spruce stump S.81°W., 15.9 ft. to spike mkd: R.P. *133*

The 18" Fir snag BT shows scribe mks. 1/4 S BT. I put nail in face of blaze.

The E. & W. blazed line seems to run South of M. C.

4/10/43

66

1/4 Corner for Secs. 15 and 14.

Found - Orig. BT's at 1/4 Corner.

Set - 1 1/2" I.P. U 3"x3"x6' Fir post from which bears: *# 125*

Orig. 30" Fir (stump) N.70°E., 1.98 ft. scribed face has been burnt out but overgrowth scar shows where BT scribe should be.

Mkd:

Orig. Spruce 24", N.19°W., 14.5 ft. has only portion of rotten stump left in ground. No marks visible

I blazed - 24" Spruce stump N.79°W., 23.1 ft. to nail, crayon mkd: BT 1/4 S15.

Old blazed line N. to road about 400 ft. 428 ft. to ridge NE & SW.

10/28/41

67

1/4 Corner for Secs. 10 and 11. *(SEE ALSO - REN. # 29)*

Found - Stumps of the orig. BT's at 1/4 Cor. showing scribe marks. As bearings and distances would not check exactly, I relocated corner as near as possible.

Set - 1 1/2" I.P. & 2"x4"x5' Fir post from which bears: *# 127*

Orig. 36" Spruce stump S.16°E., 8.5 ft. to nail scribed 1/. Rest burnt off.

Orig. 15" Spruce stump N.30°W., 15.7 ft. scribed BT. Stump rotten and burnt.

I blazed - 24" Spruce stump N.27°W., 27.4 ft. to nail crayon mkd: 1/4 S10 BT.

This corner stands on SW slope of ridge about 4-0 ft. E. of N & S truck road to Harmony Bay. The phone line to Booth passes close to corner.

10/30/41

68

Meander Corner for Secs. 10 and 11.

Found - Orig. 26" Spruce BT for MC. at 61.00 chs. and from it relocated the MC as Alder is missing.

Set - 1 1/2" I.P. & 2"x4"x5' Fir post crayon mkd: S10/S11 M.C. 1943 from which bears:

BT's - Orig. 26" Spruce stump, now 5 ft. burnt & rotten, S.8°W., 35.64 ft. to nail scribed BT. The rest remained covered.

5" Alder N.31°45' E., 10.7 ft. to nail, crayon mkd: M.C. RP BT.

The MC on N. side of Harmony Bay bears N.0°30'W. The 1 1/2" I.P. in top of 3 ft. Fir stump BT to MC N.1°W. Left 1 1/2" I.P. in top of 5 ft. BT stump.

This MC stands on N. side of 3 ft. Spruce log 3 ft. above water level of Lake at this date.

4/16/43

69

W. G. Corbitt
B. Senn
for: Crown Zellerbach
1941 - 43
C.S. 52/91