

Douglas County Surveyor's Record of
Government Corners Renewed

T 20 T. S. R 12 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

93

1/4 Corner for Secs 32 and 33
Set - 1 1/2" I.P. and 2x2x5 Spruce post at point 2654.5 ft. from
Cor. of 32.33,5 and 4.
From which bears:
24" Hemlock S.48 1/2°W., 8.5 ft. RP 26+54.5.
5" Spruce N.11°E., 75.2 ft. RP 26+54.5.
Other post for approx 1/4 S N.20 1/2°E., 88.5 ft.
Edge of logging 107-31=102.2 East from 27+37.2 to pipe and post mdk.
1/4 S 32/33 1243' E of 1/16 Cor.
Orig. Corner or BT's not found. Did find blazes on 8" Spruce made in 1922.
7/29/43

W. G. Corbitt
H. Hendrickson
for Crown Zellerbach
1941-43
C.S. 52/91

94

1/4 Corner for Sec. 32; and Sec. 5 of T21-12.
At 2+97 west of W.C. Set:
1 1/2" I.P. and 2x3x4 Fir Post crayon mkd. 2+97 W of W.C. S32, S5
Aug. 4, 1943 W.G. Corbitt,
From which bears:
8' Fir, N.65°W., 11.5 ft. crayon mkd. RP 35 ft. W of Creek course 5 W.
Field notes call for ridge SW at 23+10.
8/4/43

95

W.C. for 1/4 Cor. Sec. 32; and Sec. 5 of T21-12.
Field notes call for W.C. at 23.43
Found - Fir BT's at W.C. and from them relocated W. Corner as best I
Could considering distances did not check exactly.
Set - 1 1/2" I.P. and 2x2x4 Fir post crayon mkd. WC S32 S 5 Aug. 4, 1943.
From which bears:
Orig. 36" Fir, now 5', N.65W (Rec. S65°W.), 25.08 ft. Slope -39%
=23.38 to base of nail crayon mkd. RP BT W.C. S5. Evidently
the orig. scribe marks were put on bark of tree and these were destroyed
when someone cut through blaze to solid wood in 1922.
Orig. 24" Fir now dead snag without back, N.77°W., 13.0 ft. to nail.
Old blazed face on bark indicates scribe marks were put there.
6' Spruce N.65°E., 26.8 ft. 147.5 ft. -%=24.22 Crayon mark RP
BT W.C. S32.
8/4/43

96

Meander Corner for Secs. 1 and 12. See also Ren. #5
Found - 5/8" Rebar.
Set - Spike in scribed 16" Doug. Fir, N.34°27'W., 14.18 ft. to head
of spike.
Set - Spike in center line road S.3°45'20"W., 23.76 ft. to spike.
4/24/75

FND. 3/01
C.S. 63/70
FND 7/02
M115-42

Robert A. Manseth
For: R. E. Chapman
April 24, 1975
C.S. 58/116

~~Section Corner for Secs. 4 and 3; and 33 and 34 of T20-11
Found - 1964 Doug. Co. Surveyors Brass cap set 12" above ground on 1"
pipe properly marked. Ren. #29
A Fir, uprooted and down, approx. 54" bears N.55°W., 31.0 ft.
Both scars visible.
A Fir stump, 48" now 42" bears S.25°E., 12.3 ft. (Rec. 11.9 ft.)
A Fir, 48" now 50" bears S.55°W. 19.8 ft. to well healed blaze,
20.8 ft. to opened blaze with visible "B" scribe mark.
A 9" Hemlock now 16" bears S.58°E., 26.4 ft. (Rec. 27.4 ft.)
with well healed double blaze.
A D. Fir snag, 36" now 34" bears N.17°W., 50.0 ft. double
blazed partial healed with trace scribing visible.
New BT - A 11" Hemlock measured below fork bears N.1°E., 29.7 ft. double
blazed and marked T20S R11 W S34 CS BT.
6/16/77~~

1/4 Corner for Sec. 4 and Sec. 33 of T20-11.
Found - A 1" Iron pipe at 1/4 Corner as proportioned by Stuntzner per
Ren. #

JUN 78
1/07