

Douglas County Surveyor's Record of
Government Corners Renewed

21 T. S. 4 R. W. W. M.

KOFE-CHAPMAN CO., EUGENE, ORE. 97195

Vol. 2, Page 261-263

Chas. C. Bayles - July 1953
Vol. 41 Env. 183

B. H. McGillicuddy
July 1953
Drawer 41-Env. 182

$\frac{1}{4}$ sec. betw. secs. 2 and 11. *SEE ALSO #115*
Set a cedar post, from which a fir 20" dia. bears
N. 44° E. 25 lks. distant. **16**
A cedar 12" dia. bears S. 2° E. 32 lks distant.
Jan. 25. 1899. In presence of D. Perini and Co. Surveyor
C.M. Collier, found only one stump of one original B.T.
part of letters still visible.

$\frac{1}{4}$ sec. cor. betw. secs. 10 and 11. *SEE ALSO #116*
Set a cedar post, from which a fir 40" diam. bears
S. 45° W. 61 lks distant. **17**
Present Alex Wright and J. A. Tramel.
The N. E. original B. T. still standing, but marks
obliterated, I remark the same; the other B.T. had fallen
down.

Cor. of secs. 11, 12, 13 and 14. **18**
Set a cedar post, from which a cedar 8" in diam. bears
S. 71° W. 46 lks distant. No other trees within distance.
Present Alex Wright and Geo. Tramel. I run from
 $\frac{1}{4}$ sec. cor. betw. secs 11 and 12 South to $\frac{1}{4}$ sec. cor. betw.
secs. 13 and 14.
Then begin at a large stone set by Co. Surveyor Collier
for $\frac{1}{4}$ sec. cor. betw. secs. 12 and 13 and W. to $\frac{1}{4}$ sec. cor.
between secs. 11 and 14. 28 Dec. 1899.

Section corner sec's 15, 16, 21, and 22.
Found fir 18" N. 36° W., 8 lks., now 48". **19**
Blown over, scribing burned out.
Set Cedar post. *RE-RENEWED, SEE CORNER NO. #126*

Section corner 9, 10, 15, and 16. **20**
Corner destroyed by road construction. Found orig. fir 80"
N. 69° E., 50 lks. dist. blasted out. from stump hole
set red stake at corner. - 1964 - SEE C.S. 54/14 V.R.T.

$\frac{1}{4}$ corner between secs 21 and 20. **21**
No trace of corner or orig. B.T.s - Set fir post. *RE-RENEWED, SEE CORNER NO. #85*

Corner 20, 21, 28, 29. **22**
Found stump of fir 8" (now 24") N. 46° W., 46 lks. plainly scribed. No
other B.Ts.
Set $\frac{3}{4}$ " X 2 ft. Galv. iron pipe & marked "H" on:
Fir 13" N. 9° E., 31.5 feet.
Fir 14" N. 17° W., 31.2 feet.

$\frac{1}{4}$ corner between secs 30 and 31. *SEE ALSO V. 2 Pg. 258 & Vol. 1 Pg 191-2*
Set $1\frac{1}{2}$ inch X 27 inch iron pin and post in right of way clearing. No **23**
bearing trees. *FOUND ? - V.R.T. APRIL 1969 C.S. 54/14*

Northwest corner of section 31. *SEE COR # 14*
This point falls in Pass Creek at a point 20.5 feet south of the **24**
original witness corner of ~~secs 30, and 31, T 21 S,~~ *#77*
R 485 W.
Witness coner set and represented by a $1\frac{1}{2}$ inch pipe.
New 10" maple set marked CS S36 Tp 20 S, R 5 W. - S 66° E., 65.2 feet.