

Douglas County Surveyor's Record of
Government Corners Renewed

21 T. S. 4 R. W. W. M.

ROSE-CHAPMAN CO., EUGENE, ORE. 97196

1/4 corner to secs. 23 and 26.
Set a stake 4" x 4" x 3" halfway between section corners
from which

14 inch D. Fir bears S. 12 1/2° E., 10.0 feet, marked 1/4 S BT.
No other trees available. - 11-1964 - M.E.G. - SEE NOTE IN FILE C. S. 42/31

#125
25

Section corner to secs. 25, 26, 35, and 36.
Set at proportionate distance.

Marked new bearing trees:

10 inch D. Fir, S. 30° W., 13.8 feet marked S 35 BT.
10 inch D. Fir, S. 8° E., 29.2 feet marked S 36 BT.
10 inch D. Fir, S. 72° E., 13.9 feet marked S 25 BT.
10 inch D. Fir, N. 62° W., 6.6 feet marked S 26 BT.

RENEWED, SEE CORNER NO. #159

26

1/4 corner to secs. 26 and 35.

Set a 2 inch iron pipe half way between section corners.

Marked 2 new BTs:

14 inch I. Cedar, N. 50 1/2° E., 35.0 feet.
24 inch I. Cedar, S. 80° W., 110.6 feet, marked 1/4 S B T.

27

Section corner to secs. 19, 20, 29 and 30.

Found S. W. and S. E. BTs as recorded in County Surveyors office in Roseburg. - See Cor. No. 12

Set 3/4 x 30" gal. pipe from calls, 6" below surface of road.

Rev #13
28

1/4 Section Corner to Section 34 & 35.

Found - Original 8" now 6" snag, partly rotted Fir S. 87° W. 7.9 ft.
Has open face good scribing "1 S"

I can find no trace of Orig. N. E. BT.

Set 3/4" Iron Rod at Corner.

New BTs: 12" W. Fir bears N. 29° W. 27.0 ft. scribed 1/4 S34 CS BT.
17" Cedar bears N. 80 1/2° E. 57.5 ft. scribed 1/4 S35 CS BT.

RENEWED, SEE CORNER NO. #144

29

1/4 Section Corner to Sections 19 & 30.

Beginning at 1/4 S post on line between Sec. 19 & 30, T21S, R4W, Var. 20° E.
Set new corner marked post 1/4 S C.S. from which made new BTs, old ones badly decayed.

Fir 10 in. diam. bears S. 35 1/2° E. 15 lks. dist.
Fir 12 in. diam. bears N. 40° W. 30 lks. dist.

RENEWED, SEE CORNER NO. 45

30

Section Corner to Sections 17, 18, 19, & 20.

Found - 3/4" Shaft at Fence Corner set by Theil, 1943. (See Sketch in File)
Also find stump hole & parts of rotted Fir that checks bearing & distance for Orig. N.W. BT. - Fo. O.K. 10/9/64 - M.E.G.

Find base of old stump that checks Orig. S. W. BT.

I do not Set Brass Cap at Corner.

New BTs: 6" R. Fir bears S. 65° E. 17.8 ft. scribed S20 T21S R4W CS BT.
10" R. Fir bears N. 84° E. 27.0 ft. scribed S17 T21S R4W CS BT.
18" Double Laurel N. 71° W. 119.0 ft. scribed S18 T21S R4W CS BT.
No trees near in S.W.

RENEWED, SEE CORNER NO. 99

31

Section Corner to Sections 19 & 30 T21S R4W & Secs. 24 & 25 T21S R5W.

Found - 2 Orig. BTs. now stumps only, good scribing visible.

N.E. & S.W. BTs. check bearing & distance.

Also find 12" x 8" x 6" Stone with chisled + on top at corner.

Corner in N.S. Fence Line, set by Banlau, Oct. 13, 1895.

New BTs: 10" R. Fir bears S. 79° E. 9.0 ft. scribed S30 T21S R4W CS BT.
22" R. Fir bears N. 68° E. 27.0 ft. scribed S19 T21S R4W CS BT.
8" R. Fir bears N. 85° W. 67.8 ft. scribed S24 T21S R5W CS BT.
12" R. Fir bears S. 63° W. 32.4 ft. scribed S25 T21S R5W CS BT.

32

Gilbert A. Gardner
Done on survey for W. A. Woodard Lumber Co.
July - December, 1955.
See C. S. File 42/131 and See M 2 - 16
for tracing.

Follett and
Ford
November,
1950.
C. S. File
No. 40/289.

James W. Byron
M. Godfrey
S. Blouw
Dec. 4, 1957
C. S. File # 49/42

W.F. Briggs
For Robert Analof
Nov. 3, 1891
Old survey book
No. 1, page 191

James W. Byron, Deputy County Surveyor
M. Godfrey
S. Blouw
March 10, 1958
C. S. File 49/68