

Douglas County Surveyor's Record of
Government Corners Renewed

21 T. S. 4 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21801

33

Section Corner to Sections 21, 22, 27, & 28.

Found - Orig. 10", now 34" R. Fir N.68°E., record N.68°W. 5.9 ft.

I open this BT., find good scribing (scribed high 4.5 ft. above ground) "T21S", checks for ring count. This BT. has been rescribed by Theil (bark scribed) "22 BT".

Clump of Maples that checks bearing & distance for Orig. S.W. BT. No trace of other BT's. found.

Also find large flat stone with + Cross at old fence post.

Stone bears S.11°W. 3.4 ft. from Section Corner.

Set Brass Cap at Corner Mkd: $\frac{S21}{S28} | \frac{S22}{S27}$ T21S R4W County Surveyor's Office, 1958

New BT's: 4" R. Fir bears N.71½°W. 18.0 ft. scribed S21 CS BT.

17" W. Fir bears N.50°E. 8.6 ft. scribed S22 T21S R4W CS BT.

10" Maple bears S.28½°W. 36.2 ft. scribed S28 T21S R4W CS BT.

19" W. Fir bears S.60°E. 38.8 ft. scribed S27 T21S R4W CS BT.

*Fnd. OK by W. EIMSTAD OCT. 1981 MB9-25
FD. OK 11/93 R. DOLAN MILK-A*

James W. Byron, Deputy County Surveyor
M. Godfrey
S. Bilow
June 26, 1958
C. S. File No. 49/68

34

Section Corner to Sections 27, 28, 33, & 34.

Found - Orig. 24", now 42" R. Fir N.40°W. 13.2. ^{NEW STUMP ONLY} I open near base & find good scribing "BT". I also find base of Large Fir that checks bearing & distance for Orig. S. W. BT.

No trace of other BT's Found.

Set Brass Cap at Corner Mkd: $\frac{S28}{S33} | \frac{S27}{S34}$ T21S R4W County Surveyor's Office, 1958

Note - Theil has bark scribed the Orig. N. W. BT. "W BT."

New BT's: 12" R. Fir bears S.74°W. 7.6 ft. scribed

6" R. Fir bears N.71°E. 21.0 ft. scribed S27 CS BT.

8" R. Fir bears S.49°E. 55.3 ft. scribed S34 T21S R4W CS BT.

9" D. Fir N.61°W. 28.0 ft., not recorded. Fd. Oct. 1964, M.E.G.

James W. Byron
Milo Godfrey
S. A. Bilow
August 1, 1958
Filed 4/24/59
C.S. File No. 49/68

35

¼ Section Corner to Sections 15 & 22.

Found - Orig. 18", now 36" partly rotted Cedar Stump. I open & find good scribing "BT" N.47°E. 28.4 ft.

18" Cedar Stump, now partly rotted that has possible scribe marks that face to S.W. from Corner Stump bears S.25°E. 29.0 ft., record S.53°E. 31.0 ft.

Note - The Compass needle indicates magnetic attraction in this area. To known East, I read S.55°E.

Set Brass Cap at Wit. Corner which is determined by Orig. BT. to N.E.

Mark Brass Cap ¼ $\frac{S15}{S22}$ T21S W. R4W County Surveyor's Office, 1958

Witness Corner 7 ft. East.

Fnd. OK by W. EIMSTAD OCT. '81 MB9-25

James W. Byron
Milo Godfrey
S. A. Bilow
August 1, 1958
Filed 4/24/59
C.S. File No. 49/68

36

Corner to Sections 32 & 33, T21-4W. & Secs. 4 & 5, T22-4W.

Stake badly decayed, original BT. down and destroyed except the Yew Tree and it was down, marks visible.

Set New Post, Yew, 4 x 4 inches square 3½' long from which:

6" Fir bears N.7½°E. 23 lks.

6" Fir bears N.37½°W. 21 lks.

5" Fir bears S.32°E. 21 lks.

No tree near in S. W.

75

¼ Section Corner between Sections 32 and 33.

The original BT. destroyed by fire.

Set New Post 4 x 4 inches square 3½ ft. long from which:

6" Fir bears N.48°E. 10 lks.

40" Fir bears S.33°S. 9 lks.

73

37

Section Corner to Sections 28, 29, 32, and 33.

The original BT. gone, post hole visible, made new post, to wit: A Fir 4 x 4 inches square 3½ ft. long from which:

18" Fir bears S.7½°W. 23 lks.

16" Fir bears N.45½°W. 55 lks.

20" Fir bears N.67°E. 103 lks.

24" Fir bears S.71°E. 194 lks.

Old bearing trees destroyed by fire!!!

72

38

W. F. Briggs
Witnessed by Pet Matchatte & S. Tonalee
March 16 - 18, 1901
Recorded in Volume 2,
Pages 263 & Pg. 107