

Douglas County Surveyor's Record of
Government Corners Renewed

T. 21 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO. EUGENE, ORE. 21881

(continued)

New BT's: 10" Fir N.27°E. 32.9 ft., added "W" Nail & Plate.
3" Fir S.29°E. 9.6 ft., added "W" Nail & Plate.
6" Fir N. 6°W. 21.3 ft. " " " "
10" Fir N.74°W. 16.2 ft. " " " "

C. S. File No. 53/104
Page 2.

91
1/4 Corner to Sec. 6, T21-4W. & Sec. 31, T20-4W.
Found - 3/4" Iron Pipe, See C. S. File No. 53/103.
60" Fir Stump N.61°W. 81.8 ft., possible bark scribing visible.
Rotten Fir Snag S. 7 1/2° W. 56.8 ft., no marks visible.
Apparently new BT., 16" D. Fir N.72°E. 6.5 ft., scars grown over.
3" Brass Disc. with "Reg. Eng. 4413" mkd. on a 98
22" Fir N. 18°W. 13.3 ft.
60" Fir S. 36° W. 51.8 ft.
Weyerhaeuser Tags, dated 1958 on above two trees.

Milo E. Godfrey
and Crew
Nov. 5, 1966
C. S. File No. 49/68

92
TOWNSHIP CORNER
T20S
R5W S 36 | S 31 R4W
S 1 | S 6
T21S

Found - Old 3/4" I. Pipe 19" long & Broken Stone 20"x9"x6" mkd. 160
"20 R5 S36", firmly set.
Orig. 8", now 23" R. Fir Stump N.50°W. 5.3 ft. Open & find
"T R5 BT", scribe, reverse.
Orig. 8", now 26" R. Fir Stump N.75°E. 6.6 ft., no scribe fd.
8", now 14" R. Fir Stump S.15°W. 5.9 ft., find reverse "B"
scribe.
No trace S.E. BT. All BT's. badly rotted, measurements taken from face.

Set - Brass Cap at Cor. Mkd: Doug. County Surveyor's Office, 1965

T20S
R5W S 36 | S 31 R4W
S 1 | S 6
T21S

New BT's: 7" D. Fir S.46°W. 4.5 ft. Mkd: T21S R5W S1 DCS BT.
8" D. Fir N.4° W. 7.0 ft. Mkd: T20S R5W S36 DCS BT.
7" D. Fir East 17.3 ft. Mkd: T20S R4W S31 DCS BT.
8" D. Fir S.21°E. 23.2 ft. Mkd: T21S R5W S6 DCS BT.

Vernon "Ray" Tracy
Mike Stone
Terry Connell
Sept. 8, 1965
C. S. File No. 54/14

93
Section Corner to Sections 4 - 5 - 8 - 9.
Found - Sandstone 10"x10"x18", firmly set, recorded as Basalt, Ren#90.
Orig. 12", now 16" Fir S. 12° E. 11.2 ft., frag. scribe on upper scar, now burned. "BT" scribe visible on prev. opened lower scar.

Weyerhaeuser BT's. alive & in good condition.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1966
T 21 S R 4 W
S 5 | S 4
S 8 | S 9

Mark Existing Weyerhaeuser BT's:

6" D. Fir S. 29° E. 9.6 ft. mkd. T21S R4W S9 CS BT.
12" D. Fir N. 27° E. 32.9 ft. mkd. T21S R4W S4 CS BT.
9" D. Fir N. 6° W. 21.3 ft. mkd. T21S R4W S5 CS BT.
8" Laurel S. 47° W. 26.4 ft. mkd. T21S R4W S8 CS BT.

Vernon "Ray" Tracy
Joe Brady & Jack Heritage
Tom Watts, BLM
July 26, 1966
C. S. File No. 54/14

94
1/4 Corner to Sections 8 and 9.
Found - 2" Iron Pipe, unrecorded & BT's. as recorded in Ren. #9.
36" Fir, now badly rotted stump, N. 43° W. 22.4 ft., prev. opened & shows "BT" scribe.
36", now 46" Fir S. 57° E. 70.1 ft., now burned stump, possible frag. scribe on Burned faces. Someone chopped an "X" on lower face.

DO NOT SET BRASS CAP.

New BT's: 8" Chinq. West 3.0 ft. mkd. 1/4 S8 CS BT.
13" D. Fir S. 26° E. 30.7 ft. mkd. 1/4 S9 CS BT.

Note - Corner lies 50 ft. west of very old logging road, course N-S.

FD OK 5/96
By Bracey - M/23-76