

Douglas County Surveyor's Record of
Government Corners Renewed

T. 21 S. T. S. R. 4 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

FD OK PER PEEL
M 110-2 4-90

95

Vernon "Ray"
Tracy
&
Crew
7/26/66
C.S. File
No. 54/14

$\frac{1}{4}$ Corner to Sections 4 and 9.
Found - 1" Aluminum Pipe & Weyerhaeuser BT's. & Stumps of BT's.
as recorded in Ren. #3 by Cole, 1914, as follows:
15", now 30" Cedar Stump, S. 60° E. 71.9 ft. Open & find
"T" scribe & reverse.
24", now 30" Fir, badly rotted stump, N. 34° E. 35.6 ft. no scribe fd.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office T 21 S R 4 W
(alongside alum. Pipe) 1966 $\frac{1}{4}$ $\frac{S 4}{S 9}$
Scribe Weyerhaeuser Trees: 18" D. Fir N. 20° W. 13.1 ft. mkd. $\frac{1}{4}$ S4 CS BT.
16" D. Fir S. 19° W. 38.3 ft. mkd. $\frac{1}{4}$ S9 CS BT.

MICROFILM TO HERE 10/67

FD. CAR. OK 5
w/1971 Blm
B.C. W. Guike
M 100-68
2/27/87

96

Vernon "Ray"
Tracy &
Crew
12/12/67
C.S. File
No. 54/14

$\frac{1}{4}$ corner to Sec. 2, T21-4W. & Sec. 35, T20-4W.
Found - 1 $\frac{1}{2}$ " Iron Pipe, See Ren. #89.
Orig. 17" Fir, now snag, N.17°W. 24.4 ft., scribe visible, same BT.
called for in 1900 reestablishment.
Orig. 10" Fir, face down, S. 36° E. 39.6 ft. "W" BT.
Orig. 21" Fir Stump, in place, decaying, S.30°E. 19.1 ft., no scribe fd.
New BT's: 13" D. Fir N. 4° W. 30.0 ft. mkd. $\frac{1}{4}$ S35 DCS BT."
4" D. Fir S. 53° W. 9.4 ft. mkd. $\frac{1}{4}$ S2 DCS BT."
Note - This corner lies 90 ft. E. of old road on Lane-Douglas Co. Line.
ED OK 10/94 M 120-70 12/12/67

SEPT. 68

FND. OK 11-92 BY ROBERTS
M 116-48

Section Corner to Secs. 31 & 32, T20-4 and Secs. 6 & 5, T21-4W.
Found - Unrecorded 2" Cast Iron Pipe at corner which apparently
was set many years ago from Orig. BT's.
Orig. 12", now 14" Fir, badly decayed snag, S.14°E. 40.3 ft. (slope dist.)
fragmentary scribe on upper blaze & most of "T" on lower open blaze.
Orig. 20" Fir, now 26" badly decayed stump, S.43°W. 57.4 ft., shows
old axe marks, no scribe found.
Orig. N. E. BT., find only stump hole at location.
No trace of Orig. N.W. BT.
Set - Brass Cap at Cor. Mkd: Doug County Surveyor's Office, 1968 T20S R4W S 31 | S 32
T21S R4W S 6 | S 5
New BT's: 15" D. Fir S.28°E. 45. 8 ft. mkd: T21S R4W S5 DCS BT.
11" D. Fir S.45°W. 42.1 ft. mkd: T21S R4W S6 DCS BT.
24" D. Fir N. 7° W. 19.5 ft. mkd: T20S R4W S31 DCS BT.
No trees close to N.E.
Corner lies in fence line course N.30°E. - S.30°W. on N.E. slope.
12/31/69

Vernon "Ray" Tracy
Frank Jones & V. Perron
December, 1968
C. S. File No. 54/14

$\frac{1}{4}$ Corner to Sec. 31, T20-4W. & Sec. 6, T21-4W.
Found - Very old 3/4" I.P. at corner point, unrecorded.
Orig. 30" Fir, now 60" Stump, N.61°W. 81.8 ft., find "T" bark scribe.
Orig. 28" Fir, now 40" Snag, S.7 $\frac{1}{2}$ °W. 56.8 ft., prev. chopped open,
decayed, no scribe.
Weyerhaeuse Method BT's., See C.S. 53/103; SEE REN. #91
26" D. Fir, N.18°W. 13.3 ft., "W" nail & brass disc at base.
65" D. Fir S.36°W. 51.8 ft., brass disc barely visible at base.
Set - Brass Cap at Cor. Mkd: Doug County Surveyor's Office, 1968 T20S R4W $\frac{1}{4}$ S 31
T21S R4W S 6
Reset I. P. alongside Brass Cap - Corner lies in fence corner -N. & E.
New BT's: 17" D. Fir N.35°W. 16.0 ft. mkd: $\frac{1}{4}$ S31 DCS BT.
12" D. Fir S.54 $\frac{1}{2}$ °W. 55.5 ft. mkd: $\frac{1}{4}$ S6 DCS BT.

Section Corner to Sections 17 - 18 - 19 - 20.
Found - 3/4" Shaft at Fence Corner & BT's. as recorded in Ren. #31.
6", now 15" R. Fir, alive, S.65°E. 17.8 ft., healed blaze.
10", now 18" R. Fir, alive, N.84°E. 27.0 ft.
Rescribed: "T21S R4WS17 CS BT" over old scar.
18", now 24" double Laurel, alive, N.71°W. 119.0 ft., scribe marks
visible on nearly healed blaze.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1968 T 21 S R 4 W
S 18 | S 17
S 19 | S 20
New BT: 10" D. Fir S.44°W. 52.0 ft. mkd: T21S R4W S19 CSBT.
Note - Reset Shaft alongside Brass Cap, fences N. - S. and E. - W.
12/30/68

RE-RENEWED

NO. # 153

NO. # 134

98

99