

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 21 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

100

Most Northerly N. W. Corner D. L. C. #37.

Found - 1" I. Pipe & Alumn. Sleeve, mkd: "C37" & BT's., See Ren. #84.  
9", now 11" I. Cedar, alive, N.45 $\frac{1}{2}$ °W. 71.0 ft., scribe  
marks visible on healing blaze.  
10", now 11" I. Cedar, alive, S.64°W. 29.0 ft., scribe  
marks visible on healing blaze.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 21 S R 4 W  
Office, 1968 N.W. D.L.C. /37

Reset old pipe alongside Brass Cap. Also remains of  
old cedar corner post. This cor. lies at fence corner, fences E-W & S.

*Fd. OK 1/4/89  
L. ROBERTS  
C.S. 63/85*

FD OK 4/96 101

Section Corner to Sections 2 - 3 - 10 - 11. *Les Roberts M123-56*  
Found - Very old 4x4x48" Cedar Post at corner, no marks.  
Orig. 70" Fir, now 72" sawed stump, N.30°W. 5.9 ft., no scribe.  
Orig. 10", now 32" Fir, turned out, S.70°E. 28.4 ft., Open and  
find scribe.

Hole where Orig. N.E. BT. would have been. - No trace S.W. Orig. BT.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 21 S R 4 W  
Office, 1969 S 3 | S 2  
S 10 | S 11

*FD OK 10-90 M110-72  
FD OK 10-79 M120-70*

New BT's: 10" R. Fir S.22°W. 19.3 ft. mkd: T21S R4W S10 CS BT.  
7" D. Fir S.30 $\frac{1}{2}$ °E. 17.0 ft. mkd: T21S R4WS11 CS BT.  
5" D. Fir N.83°W. 11.5 ft. mkd: S 3 CS BT.  
18" I. Cedar N.55°E. 54.9 ft. mkd: T21S R4W S2 CS BT.

This corner lies on moderate S.E. slope in dense brush.

102

Sec. Cor. To Secs. 18 & 19, T21-4W and Secs. 13 & 24, T21-5W.  
Found - 3/4" I.P., bent over & BT's. as recorded in Ren. #87. *#123*  
27" D. Fir, alive, S.32 $\frac{1}{2}$ °E. 37.4 ft., scribe visible on pitched blz.  
12" D. Fir, alive, N.69°W. 133.2 ft., scribe visible on pitched  
& healing blaze.

Orig. BT. to S.E. alive, & Orig. N.W. BT. stump in place  
and shows scribe.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 21 S R  
(Reset old I.P. alongside) Office 5 S 13 | S 18 4  
1968 W S 24 | S 19 W

New BT: 6" D. Fir N. 1 $\frac{1}{2}$ ° E. 34.1 ft. mkd: T21S R4W S18 CS BT.  
This corner lies 1 ft. S. of E-W. fence. No trees available to S.W.

Vernon "Ray" Tracy  
Frank Jones & V. Perron  
December and January 1969  
C. S. File No. 54/14

103

Section Corner to Secs. 31 & 32, T21-4W. and Secs. 5 & 6, T22-4W.  
Found - 1962 C. S. Brass Cap, properly mkd. & firmly set, Ren. #51.  
14", now 15" W. Fir, alive, N.32°E. 18.0 ft., nearly healed  
blaze, scribing visible.  
18", now 19" D. Fir, alive, N.50°W. 15.3 ft., nearly healed blaze.  
13", now 14" D. Fir, alive, S.17°W. 58.4 ft., blaze healed.  
S. E. Bearing Tree Down.

New BT: 13" R. Fir S.71°E. 91.4 ft. mkd: T22S R4W S5 CS BT.  
Probable Original Bearing Tree stump still in place.  
This corner lies N.65°E. 4.5 ft. from fence corner, fences E - W & S.

*FD OK  
Les Roberts  
12/94 M121-24*

104

Section Corner to Secs. 3 & 2, T21-4 and Secs. 34 & 35, T20-4W.  
Found - Monel Pipe & old Mound of Stone at corner.  
Orig. 8" Fir, now 40" sawed stump, S.20°E. 137.3 ft., no scribe.  
Orig. 8" Fir, now 38" Snag, N.61°E. 46.9 ft., Open & find scribe. *FD.*  
No trace of other Original Bearing Trees.

Set - Brass Cap at Cor. Mkd: Doug. County Surveyor T20S R4W S 34 | S 35  
(Reset Pipe alongside) Office, 1969 T21S R4W S 3 | S 2

New BT's: 12" D. Fir S.25°W. 11.0 ft. mkd: T21S R4W S3 DCS BT ("W" nail)  
13" D. Fir N.71°W. 11.6 ft. mkd: T20S R4W S3 DCS BT ("W" Nail)  
8" D. Fir N.35°E. 9.8 ft. mkd: T20S R4W S35 DCS BT.  
15" D. Fir S.60°E. 17.9 ft. mkd: T21S R4W S 2 DCS BT. ("W" nail)

This corner found & recorded in C.S. 54/14, renewed by Weyerhaeuser.  
1/6/69

*Cor. OK  
2/27/87  
C.W. GUILLE  
M103-68  
C.S. 63/45  
FD OK 10/6/94  
M120-70  
C.W. Guille*