

Douglas County Surveyor's Record of
Government Corners Renewed

T. 21 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

105

Vernon "Ray" Tracy
Frank Jones & V. Perron
March 21, 1969
C. S. File No. 54/14

Section Corner to Sections 32 & 33, T20-4W. & Secs. 4 & 5, T21-4W.

Found - Orig. 50" R. Fir, now 52" Stump, N. 70° E. 16.5 ft., shows no face or scribe, good bearing & distance.

Orig. 10" R. Fir, now 16" Stob, S. 58° W. 54.8 ft., has been opened & shows scribe, frag. scribing on upper & lower faces, shows to be right age by approx. ring count.

Orig. 12" Cedar, now 16" Windfall, S. 60° E. 42.2 ft., opened & found scribe "W 4" and show to be right age by approximate ring count.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1969
T20S R4W S 32 | S 33
T21S S 5 | S 4
Doug. Co.

New BT's: 10" Chinquapin N. 24° E. 21.1 ft. scribed T20S R4W S33 DCS BT.

12" D. Fir N. 54° W. 28.9 ft. mkd: T20S R4W S32 DCS BT.

12" Chinquapin S. 57° W. 47.2 ft. mkd: T21S R4WS5 DCS BT.

12" D. Fir S. 79° E. 47.9 ft. scribed T21S R4W S4 DCS BT.

Note - "W" nails in all new bearing trees. This corner lies on East slope. 3/21/69

1/4 Corner to Section 17 and 18.

Found - Orig. 8", now 22" Fir, down & badly decayed, N. 60° W. 27.1 ft., we open & find scribe marks. BT. was chopped open many years ago.

Orig. 9", now 24" Cedar (Redwood), now snag, S. 48° E. 19.8 ft., we open & find "1/4 S T", Rescribe under 50 years overgrowth, opening deeper we find center decayed & overgrowth curled around inside.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1969
T 21 S R 4 W
1/4 S 17 | S 18

New BT's: 9" Hemlock S. 23° W. 14.4 ft. mkd: "1/4 S18 CS BT".

10" Hemlock S. 18° E. 9.1 ft. mkd: "1/4 S17 CS BT".

This corner lies in dry gulley, we did not find creek 2 lks. wide, course E., at 41 chains as called for in field notes.

Section Corner to Sections 7 - 8 - 17 - 18.

Found - Unrecorded 1" x 1" I. Bolt. & Orig. BT., See Ren. #7.

Orig. 30", now 53" Fir, alive, S. 20° W. 12.5 ft., prev. opened, face burned.

40" Fir, down, burned, badly decayed, N. 72° 20' E. 56.6 ft.

48" Fir, now sawed stump, S. 67° 30' E. 63.0 ft., scribe visible on unhealed blaze, partly burned.

No trace other bearing tree called for in renewal.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1969
(Reset Bolt alongside Brass Cap)
T 21 S R 4 W
S 7 | S 8
S 18 | S 17

New BT's: 10" D. Fir N. 44° E. 21.0 ft. mkd: "T21S R4W S8 CS BT".

9" D. Fir S. 33° E. 17.7 ft. mkd: "T21S R4W S17 CS BT".

8" D. Fir S. 85° W. 7.8 ft. mkd: "T21S R4W S18 CS BT".

8" D. Fir N. 74° W. 9.6 ft. mkd: "T21S R4W S7 CS BT".

This corner lies on moderate easterly slope in dense D. Fir reproduction, logging estimated about 1920 to 1930.

1/4 Corner to Sections 7 and 8.

Found - Old Remains of Cedar Post with scribe "S8", See Ren. #8.

Orig. 12", now 20" Fir, badly decayed & burned Snag, N. 49° 40' E. 38.0 ft. Snag 10 ft. high, find "CS B" on burned blazes.

Badly decayed remains of Orig. N. W. BT., no scribe found.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1969
T 21 S R 4 W
1/4 S 7 | S 8

New BT's: 9" D. Fir N. 66° W. 10.4 ft. mkd: "1/4 S7 CS BT".

16" D. Fir S. 87° E. 5.8 ft. mkd: "1/4 S8 CS BT".

This corner lies in dense brush and 25 to 30 year old Fir reproduction approximately 80 ft. S. of ridge top, course N.E. & S.W.

- - - - -

- - - - -

- - - - -

- - - - -

- - - - -

- - - - -

- - - - -

- - - - -

- - - - -

- - - - -

- - - - -

- - - - -

- - - - -

FD OK PER GUILLE
NOV. 1986, M 103-9

106

Vernon "Ray" Tracy
J. Heritage & V. Perron
April, 1969
C.S. File No. 54/14

107

Section Corner to Sections 7 - 8 - 17 - 18.

Found - Unrecorded 1" x 1" I. Bolt. & Orig. BT., See Ren. #7.

Orig. 30", now 53" Fir, alive, S. 20° W. 12.5 ft., prev. opened, face burned.

40" Fir, down, burned, badly decayed, N. 72° 20' E. 56.6 ft.

48" Fir, now sawed stump, S. 67° 30' E. 63.0 ft., scribe visible on unhealed blaze, partly burned.

No trace other bearing tree called for in renewal.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1969
(Reset Bolt alongside Brass Cap)
T 21 S R 4 W
S 7 | S 8
S 18 | S 17

New BT's: 10" D. Fir N. 44° E. 21.0 ft. mkd: "T21S R4W S8 CS BT".

9" D. Fir S. 33° E. 17.7 ft. mkd: "T21S R4W S17 CS BT".

8" D. Fir S. 85° W. 7.8 ft. mkd: "T21S R4W S18 CS BT".

8" D. Fir N. 74° W. 9.6 ft. mkd: "T21S R4W S7 CS BT".

This corner lies on moderate easterly slope in dense D. Fir reproduction, logging estimated about 1920 to 1930.

1/4 Corner to Sections 7 and 8.

Found - Old Remains of Cedar Post with scribe "S8", See Ren. #8.

Orig. 12", now 20" Fir, badly decayed & burned Snag, N. 49° 40' E. 38.0 ft. Snag 10 ft. high, find "CS B" on burned blazes.

Badly decayed remains of Orig. N. W. BT., no scribe found.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1969
T 21 S R 4 W
1/4 S 7 | S 8

New BT's: 9" D. Fir N. 66° W. 10.4 ft. mkd: "1/4 S7 CS BT".

16" D. Fir S. 87° E. 5.8 ft. mkd: "1/4 S8 CS BT".

This corner lies in dense brush and 25 to 30 year old Fir reproduction approximately 80 ft. S. of ridge top, course N.E. & S.W.

- - - - -

- - - - -

- - - - -

- - - - -

- - - - -

- - - - -

- - - - -

- - - - -

- - - - -

- - - - -

- - - - -

- - - - -

- - - - -

FD OK, 5/96 By BRADSBY - M123-76

108

Fd. 6/80
BLM Admin.
SURVEY-SEC
"GIS" FILE

RE-RECORDED NO. #133