

Douglas County Surveyor's Record of
Government Corners Renewed

T. 21 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner to Sections 3 - 4 - 9 - 10. By ^{FD OK JUNE 16, 86} JOHNSON, M 102-14 **109**
Found - Old Charred few wood Post, See Ren. #4.

Orig. 8", now 24" Cedar burned stump, N.68°W. 2.0 ft., "BT" scribe visible on open blaze.

Orig. 10", now 48" Fir Snag, injured & hollow, S.12°W. 24.4 ft., no scribe found. No trace other Orig. BT's.

Cole's 18", now 24" Fir sawed Stump, S.20°E. 46.5 ft., too low for scribe. No trace of Cole's other bearing trees.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office
T 21 S R 4 W
S 4 S 3
S 9 S 10

New BT's: 8" D. Fir N.84°E. 37.2 ft. mkd: "T21S R4W S3 CS BT".

8" Chinquapin S.60°W. 22.0 ft. mkd: "T21S R4W S9 CS BT".

8" Chinquapin N.54°W. 30.4 ft. mkd: "T21S R4W S4 CS BT".

No suitable tree in section 10.

Vernon "Ray" Tracy
J. Heritage & V. Perron
April, 1969
C. S. File No. 54/14

1/4 Corner to Sections 3 and 4.

Found - Mound of Stone as recorded in Ren. #6.

Orig. 8", now 24" Cedar, dead & burned out, N.47°W. 23.8 ft., find indications of bottom of old blaze, no scribe.

Cole's 24", now 28" Fir, now badly decayed remains of stump, no scribe.

Do not find any trace of Cedar Post called for.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1969
T 21 S R 4 W
1/4 S 4 S 3

New BT's: 9" D. Fir S.55°W. 12.9 ft. mkd: "1/4 S4 CS BT".

9" D. Fir N.11°E. 15.1 ft. mkd: "1/4 S3 CS BT".

Steel Fence Post bears N.28°E. 7.7 ft. mkd: "Approximate 1/4 Corner".

Reset Rock Mound around Brass Cap. This corner lies on nearly flat East slope in dense brush & reproduction.

1/4 Corner to Sections 8 and 17.

Found - Orig. 30" Fir, now approx. 48" burned stump, S.74°W. 83.2 ft., opened by D.L. Daniels, BLM, to face with "BT" scribe.

A hole evident in approx. location of other Orig. BT.

Corner would fall at old fence corner, fence E. & S., nearly gone.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1969
T 21 S R 4 W
1/4 S 8 S 17

New BT's: 15" D. Fir S.30°W. 32.8 ft. mkd: "1/4 S17 CS BT".

18" D. Fir N.66°E. 25.4 ft. mkd: "1/4 S 8 CS BT".

This corner lies on very steep, S.W. slope in bottom of dry ravine, course S.W.

12/4/69

1/4 Corner to Sections 6 and 7.

Found - Orig. 10" Fir, now remains of stump, N.10°E. 48.2 ft., burned, Scribe "BT" under overgrowth. No trace other Orig. BT.

Unrecorded BT: 24" Fir Stump S.37°E. 23.3 ft., found by

D.L. Daniels, BLM, shows "BT" scribe, possibly marked by Thiel.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1969
T 21 S R 4 W
S 6 S 7

New BT's: 6" D. Fir N.47°E. 6.6 ft. mkd: "1/4 S 6 CS BT".

16" W. Fir S.76°W. 19.7 ft. mkd: "1/4 S 7 CS BT".

This corner lies in the approximate location of old fence corner, now almost destroyed with only a few posts remaining.

12/4/69

Township Corner
R S 36 S 31 R
5 S 1 S 6 4
W T 22 S W

113

Found - 3/4" I. Pipe & a 4"x4" Post with scribing visible lying beside the iron pipe. See Ren. #19, T21-4W.

30" D. Fir, face visible, bears S.25 1/2°E. 6.0 ft. (Record 5.0 ft.)

34" D. Fir, face visible, bears N.42 1/2°E. 27.8 ft. (Record 26.4 ft.)

34" D. Fir BT, face visible bears N.9 1/2°W. 52.5 ft. (Record 51.7 ft.)

28" D. Fir BT, scribes vis. bears S.21 1/4°W. 60.7 ft.

40" Orig. D. Fir, burned stub, bears S.11 1/2°W. 132.0 ft.

Set-Brass Cap Mkd: T21S, T22S, R5W, R4W, S36, S31, S1, S6, 1972

8/30/72

U. S. B. L.M.
Bruce A. Shaner
Map File M 42 - 68

JAN 1973

RE-RENEWED, SEE CORNER NO. #147

FD 6/90
M110-29

MARCH 71