

Douglas County Surveyor's Record of
Government Corners Renewed

21 T. S. 5 R. W. W. M.

ROSE-CHAPMAN CO. EUGENE, ORE. BYRON

F. C. Frear F. J. Cole Dep.
P. D. Wolford R. Haven
B. W. Perkin Geo. Pesker
Witness
Feb 15, 1938 Oct. 18, 1916
1913 P. 176 &
1913 P. 176 &
1913 P. 176 &

CORNER TO SECS. 32, 33, 4, 5 ON TOWNSHIP LINE
Renew cor. from remains of original trees. Set oak post.
from which
Fir 30 in dia., N. 42° E. 11 ft.
Fir 36 in. dia., S. 63° W. 88 ft.
Fir 24 in. dia., S. 50° W. 82 ft.
Fir 16 in. dia., N. 68° W. 45 ft.
Set Iron pipe 1 1/2" x 40" also. Jan 4, 1924 J. W. Cole

RE-RENEWED, SEE CORNER NO. 53 1

Ben B. Irving D. C. S.
J. S. Snider
Harvey Eppstein Jr. Witness
Elwood Nelson
June 17, 1938
1913 P. 176 &
1913 P. 176 &
1913 P. 176 &

CORNER BET. SEC. 27 & 34
Reset per old P. T. s Drove rail angle iron in for corner.
from which
12" Red Fir N. 49° E. 18.3 ft.
18" Red Fir S. 49° W. 15.3 ft.

RE-RENEWED, SEE CORNER NO. 55 2

CORNER SEC. 33, 34, 4, 3 S. B. D.
Location identified from stump O. B. T. S. 15° E. Scribe marks
clear & legible & O. B. T. N. 80° W. 309 lks. (Not Chopped out)
Set 2" x 48" iron pipe 12" in ground (could not drive further
due to solid rock) in field O. B. T. 44" Fir N. 80° W. 228
feet remarked
12" Chinquipin N. 10° E. 271.5 feet.
24" Fir N. 40° W. 104.0 feet
8" Alder S. 30° E. 244.1 feet

RE-RENEWED, SEE CORNER NO. 62 3

SEC. CORNER 33-34
Location identified by distance from Sec. Cor. Distance from
small creek. O. B. T. S. 60° W. 98 lks. blazed & previously
chopped out. All scribe marks obliterated. Stump O. B. T.
rotted & no scribe marks. Set 12" Red Fir Cor. on
sandstone 8" x 10" x 18" 12" in ground labeled on top
& S. C. S. Marked new P. T.
Fir 12" dia., N. 60° W. 49.7 feet
Oak 12" dia., S. 10° E. 2.5 feet
Blazed & scribed S. C. S. B. T.

RE-RENEWED, SEE CORNER NO. 50 4

CORNER SECS. 21, 22, 27, 28
I re-established this corner from stump of the N.W. & S.W.
bearing trees, old marks found on stump of N.W. tree, S.W. badly
badly decayed. Other trees destroyed. Set a cedar post
properly marked, drove a galvanized iron pipe 1/2 inch by 36
inches long alongside, from which I marked
A Fir 15" in diam., bears S. 81° W. 12.2 ft.
Marked T. 21 S. R. 5 W. Sec. 28. C. 3.
A Fir 15" in diam., bears N. 63° W. 11.8 ft.
Marked T. 21 S. R. 5 W. Sec. 27. C. 3.
A Fir 24" in diam., bears S. 24° E. 42.2 ft.
Marked T. 21 S. R. 5 W. Sec. 22. C. 3.
A Fir 8" in diam., bears N. 79° E. 23.1 ft.
T. 21 S. R. 5 W. Sec. 21. C. 3.

RE-RENEWED, SEE CORNER NO. 86 5

SEC. CORNER BETWEEN SECTION 28, 29
Original bearing trees dead. N.W. bearing tree standing &
marks found. Other tree destroyed. I set a cedar post
properly marked & drove a gal. pipe 1/2" x 30" long, 24" in
the ground alongside the post & marked
A Cedar 20" in diam. bears N. 73° W. 35.3 ft.
Marked T. 3. B. T. C. 3.
A Fir 24" in diam., bears N. 18° 30' E. 19.1 ft.
Marked T. 3. B. T. C. 3.

RE-RENEWED, SEE CORNER NO. 85 6

NE CORNER OF THE ELIJAH T. ESTES D. L. C. NO. 37
Location identified from the stump of original bearing tree
which I chopped out and found the BT scribe marks in good
condition 40" fir S. 80° E. 63 lks.
Original Bearing tree 40" Fir S. 2° W. 612 lks. in good shape,
bark blazed and has been remarked.
For the corner blazed and rescribed a fir 30" diam. at the
corner of property fence.

RE-RENEWED, SEE CORNER NO. 108 7

O. F. Thiel, Surveyor
Dr. Penj. DeVore
Byron DeVore
V. 16 E. 55 #
1940 (as 14/55) SEE C.S. 61/55
P. F. Irving
N. E. Richardson
April 23, 1941
C. S. 53/87