

Douglas County Surveyor's Record of
Government Corners Renewed

T. 21 S. T. S. R. 5 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97101

108

N. E. Corner D. L. C. No. 37.
Found - 40" D. Fir Mkd. by Irving, 1941 for Corner. (See Ren. #7)

(bark scribing visible "B" & "S",
Old Rotten Fir Stump S.80°E. 41.6 ft., no marks visible. #154
70" Fir Stump S.2°W. 404 ft., old flattened area on bark,
but no scribing.

Set - Witness Corner 10 ft. N. of Corner.

Brass Cap Mkd: County Surveyor's Office, 1964
T21S R5W W.C. N.E. DLC 37 10 ft. S. to Corner.

New BT's: 12" W.Oak S.42°E. 26.0 ft. Mkd: "WC NE DLC 37 CS BT.
25" W.Oak N.48°W. 94.0 ft. Mkd: "WC NE DLC 37 CS BT.

Note - Corner Tree is in fence corner, fences South & West.

109

S. E. Corner D. L. C. No. 37.

Found - Iron Bar set by Irving, 1941, Ren. #10. *FD-2/81 E. Kimberling 1179-43*
Cedar N.42°W. 59.1 ft. This is now a snag approx. 15 ft. high,
good scribing visible in not completely healed scar.
34" Cedar S.75°E. 27.1 ft., some scribing visible, portion of
face chopped away, remainder of face & scribing good.

DID NOT SET BRASS CAP.

New BT: 7" Hemlock S.27°W. 16.6 ft. Mkd: SE DLC 37 CS BT.

110

Sec. Cor. to Secs. 34 & 35, T21-5W. *FD. OK 9-93 BY BAKER M118-10*
and Sec. 3 & 2, T22-5W.

Found - Orig. 30" Fir, now stump, S.33, E. 17.2 ft.,
scribing visible.
Orig. 14" Fir, down, N.54, W., chopped out, fd. scribe.
14", now 19" W. Fir N.21, E. 31.3 ft., scribing visible.
28" Fir N.21, W. 9.0 ft., scribing visible.) *SEE F.B. H-114* Ren. #18
46" Fir S.22, W. 44.2 ft., scribe visible.)
Squared Stake at Corner.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965
T21S
S 34 | S 35 R5W
S 3 | S 2
T22S

111

1/4 Corner to Sec. 5, T21-5W. & Sec. 32, T20-5W.

Found - Orig. 20" Fir, now 28" stump, S.17°E. 18.5 ft., shows good
bark scribe "S".

(BLM opened the base of this stump to a face, no scribing visible)
Orig. 8" Hemlock, now partly rotted stump, N.17°W. 23.1 ft.,
chopped out piece from inside showing good scribing "1/4".

Set - Brass Cap at Cor. Mkd: Douglas County Surveyor's Office, 1965

T 20 S 1/4 S 32 R5W
T 21 S 1/4 S 5

New BT's: 12" Cedar S.21°W. 19.2 ft. Mkd: 1/4 S 5 CS BT. *FD. OK 12/94 BY ROBERTS M121-30*
4" D. Fir N.48°W. 20.7 ft. Mkd: 1/4 S32 CS BT.

112

Sec. Cor. to Secs. 32 & 33, T20-5W & Secs. 5 & 4, T21-5W.

Found - Orig. 8" D. Fir, now 20", S.71°W. 42.9 ft., Tree has been prev.
opened, scribing visible ("W" & other marks.)

No trace of other BT's.

There is a large Fir in the N.E. Quad. with a BLM tag. Tree
doesn't fit bearing. We cut open but find nothing.

Set - Brass Cap at Cor. Mkd: Doug. Co. Surveyor's Office, 1965

T20S R5W S 32 | S 33
T21S S 5 | S 4

New BT's: 5" D. Fir N12°W. 9.6 ft. Mkd: T20S R5W S32 CS BT.
12" Hemlock N.63°E. 31.3 ft. Mkd: T20S R5W S33 CS BT.
8" Hemlock S.50°E. 22.7 ft. Mkd: T21S R5W S 4 CS BT.

Milo E. Godfrey, Deputy
Wm. Stoffel & Mike Stone
December 1964
C. S. File No. 49/68

Bruce R. Rogers,
Deputy
Wm. Stoffel
& M. Stone
May 19,
1965
C. S. File
No. 53/101

Bruce R. Rogers, Deputy Co. Surveyor
Mike Stone
June 1965
C. S. File No. 53/101