

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T 21      T. S.      R 5      R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

172

1/4 Corner for Sections 11 and 12  
NO CORNER MONUMENT FOUND. Corner re-established from 2 1854 BTs:  
Found - 26" cedar stump, S.76°W., 48.2 ft. No marks.  
          48" Fir snag, N.42°E., 100.3 ft. No marks.  
Set - Using face measurement from found BTs, Set 5/8" iron pin with  
          yellow plastic cap mkd. "Roberts P.L.S. 1039".  
New BTs - 9" fir, S.09°W., 14.8 ft. scribed/painted red.  
          14" fir, N.82°E., 17.4 ft. scribed/painted red.

173

Les Roberts  
L.S. 1039  
For: Seneca  
Timber Co.  
June 1990  
M 110 - 25

1/4 Corner for Section 12; and Sec. 7, T.21-4  
NO CORNER MONUMENT FOUND. Could not find 1971 BLM cap.  
Found - 3/4" iron pipe down hill 20 ft.  
Reset - 3/4" iron pipe using 1971 BLM bearing trees.  
Found - 48" fir stump, N.16°E., 25.8 ft. no marks, unknown origin.  
          10" fir, S.23°W., 13.2 ft. scar visible. 1971 BT.  
          15" Fir, N.56°E., 19.1 ft. scar visible. 1971 BT.

174

Center 1/4 Corner for Section 12  
Set - 5/8" x 36" iron pin with yellow plastic cap mkd. "Roberts  
          P.L.S. 1039".  
New BTs - 9" fir, S.15°W., 7.7 ft. scribed/painted red.  
          11" fir, S.84°E., 7.2 ft. scribed/painted red.  
          17" fir, N.50°W., 9.5 ft. scribed/painted red.  
          22" fir, N.24°E., 27.9 ft. scribed/painted red.

6/1990

Les Roberts  
L.S. 1039  
Oct. 1990  
C.S. 63 / 104

1/4 Corner for Sections 25 and 36.  
Found - 18" Fir stump, S.10°W., 16.5 ft. (scribing 1/4 S visible)  
          1855 original B.T., N.E. bearing tree could not be found.  
Set - 5/8" X 30" I.R. w/cap mkd. "Roberts P.L.S. 1039".  
New BTs.- 13" Fir, N.49°W., 42.9 ft. Scribed/painted red.  
          24" Fir, N.86 1/2°E., 24.1 ft. scribed/painted red.

175

Douglas County Surveyors Office  
Randall Smith - Stephen Flause  
October 29, 1991  
.C.S. File 64/21

Section Corner for 7 and 18; and 12 & 13 of T.21-6  
Found - A 1961 DCSO on a 1 1/4" O.D. Iron pipe protruding 10" above  
          ground. Ren. #69  
          18" now 29" dia. Cedar with a previously opened burnt blaze,  
          no marks visible, bears N.75°W., 23.1 ft. Orig. BT.  
          35" now 33" dia. 8 ft. high rotted D. Fir stump with cruiser  
          axe marks on bark, bears N.47°E., 6.3 ft. (Rec. 5.3 FT.)  
          (Rec. distance is a possible face measurement) Orig. BT.  
          27" now 30" dia. 5 ft. high rotted D. Fir stump with a  
          previously opened blaze, scribing visible "S18 T21S B", bears  
          S.61 1/2°E., 9.4 ft. (Rec. S.54°E., 9.4 ft.) Orig. BT.  
          7" now 8" dia. dead Chinquapin with a previously opened rotted  
          blaze, scribing visible "T21S R5W" bears N.78°E., 19.9 ft.  
          (agree w/record) Ren. No. 131  
          16" now 27" dia. D. Fir with a fully healed Double blaze bears  
          S.21°E., 47.1 ft. (Rec. S.19°E., 47.1 ft) Ren. #69  
          36" now 31" dia. barked 6 ft. high D.Fir stump with a galv. steel  
          cap on top and a healed blaze, bears S.65°W., 30.2 ft. (agrees  
          W/record) Ren. No. 69  
          24" now 21" dia. barked 7 fjt. high D. Fir stump with a galv.  
          steel cap on top and a healed blaze, bears West 42.0 ft.  
          (agree w/record) Ren. No. 69  
New BTs - 7" dia. D.Fir double blazed & scribed "T21S R5W S7 CSBT" bears  
          N.87 3/4° E., 23.3 ft.  
          7" dia. Hemlock double blazed and scribed "T21S R6W S12 CS BT"  
          bears N.73 1/2°W., 13.4 ft.

176

Corner lies near the East edge of clear-cut.

10/29/91

Section corner for 19, 20, 29 and 30  
Found - 1970 DCSO brass cap on a 1 1/4" O.D. Iron pipe protrudes 7"  
          above ground. Ren. No. 170/10  
          A Stone measuring 8" x 6" protruding 5" above ground is found  
          along East side of BC/IP. No marks visible. (Rec. 2 ft. x 6 x 8  
          (1880 survey)

177

Cont. Next Page - - -