

Douglas County Surveyor's Record of
Government Corners Renewed

T. 21 T. S. R. 5 R. W. W. M.

FORE-CHAPMAN CO., EUGENE, ORE., 21881

C O N T. - -

Douglas County Surveyor's Office
R.W. Smith S.J. Flause
Nov. 7, 1991
C.S. 64/21

- 8" now 17" dia. rotted D. Fir stump, no blazes or scribing visible, bears N.72°W., 7.0 ft. agrees w/ BLM record (orig. BT) 177
7" now rotted D. Fir stump of indeterminate size, no blazes or scribing visible, bears S.15°W., 5.9 ft. agrees w/rec.(orig. BT)
8" now 12" dia. 7 ft. high D. Fir stump, with a fully healed double blaze, bears N.4°W., 7.0 ft. agrees w/renewal no.119.
7" now 7" dia. 30' high D. Fir snag with a fully healed double blaze, bears S.44½°W., 4.5 ft. (agrees with BLM bearing and renewal no. 119. dist.)
7" now 10" dia. D. Fir with a fully healed double blaze, bears S.88°E., 17.2 ft. (rec. is east in renewal no. 119 and N.85½°E., by BLM, dist. 17.3 ft. agrees.)
8" now 9" dia. D. Fir with a fully healed double blaze bears S.23°E., 23.1 ft. (rec. S.21°E., ren. no. 119 and S.20½°E by BLM, dist. 23.2 ft agrees with rec.)

New Accessories -

- 17" dia. D. Fir double blazed and scribed "T21SR5W S1 CS BT" bears S. 72½°W., 21.3 ft.
11" dia D. Fir double blazed and scribed "T20SR5W S36 CS BT" bears N.17½°W., 81.1 ft.

Note - Corner lies approx. 35 ft. south of a gravel road.
12/4/91

Section Corner for Secs. 3 and 4; 33 and 34 of T.20-5 178A

Found - A 3¼" BLM brass cap on a 2½" O.D. iron pipe protrudes 3" above ground. (1967 BLM)

All evidence of original BTs are gone. 178A

20" dia. 2 ft. high D.Fir stump, no marks visible, bears N.77°W., 21.4 ft. (Rec. N.73°W., 21.4 ft.) Per 1967 BLM

25" now 28" dia. D.Fir with a fully healed double blaze bears S.86°E., 19.8 ft. (agrees w/BLM record)

20" now 22" dia. tipped out of ground on face, D.Fir root hole bears S.14°E., 44.2 ft. (agrees w/1967 BLM record)

30" now 30" dia. 4½ ft. high D.Fir stump with a fully healed single blaze, bears S.32°W., 58.7 ft. (Rec. S.33 3/4°W., 58.7 ft.) 1967 BLM

25" now 24" dia. 4 ft. high D.Fir stump with a fully healed single blaze and a gal. metal cap on top, bears N.25°W., 108.9 ft. (Rec. N.23°W., 108.9 ft.) 1967 BLM

New BTs - 8" dia. Hemlock double blazed and scribed "T21S R5W S4 CS BT" bears S.59½°E., 38.7 ft.

6" dia. D.Fir double blazed and scribed "T20S R5W S34 CS BT" bears N.3°E., 55.7 ft.

No other reasonable trees. Corner lies approx. 30 ft. East of a dirt skid road.
11/12/91

1/4 Corner for Sec. 33; and Sec. 4 of T.22-5 179A

Found - 3¼" dia. 1981 BLM brass cap on a 2½" O.D. Iron pipe protruding 1" above ground.

3/4" Iron pipe from 1924 not seen. Ren. #10

30" now 28" dia. 5 ft. high rotted D.Fir stump with bark scribing visible "31/5" bears N.47°W., 67.8 ft. (Record N.47°W., 66.8 ft. dist. possible face measurement) Ren. No. 10 (1981 BLM record brg. and Dist. to wrong stump.

10" now 37" dia. W.Oak with a fully healed single blaze, bears S.47 3/4°W., 149.2 ft. (agrees w/record) Ren. No. 10

20" now 29" dia. D.Fir with a fully healed single blaze bears S.66°W., 30.0 ft. (agrees w/record) Ren. No. 100

38" now 38" dia. 4 ft. high d.Fir stump with a fully healed single blaze, bears N.28°W., 20.0 ft. (agrees with rec) Ren. 98

New BTs - 9" D.Fir double blazed and scribed "¼ S4 CS BT" bears S.77°E., 78.2 ft.

9" D.Fir double blazed and scribed "¼ S4 CS BT" bears S.43°E., 41.6 ft.

Corner is approx. 20 ft. North easterly of dirt road.

FD OK 1095 D.BAKER M119-77

2/4/92

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
November 12, 1991
C.S. File 64/21

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
Feb. 4, 1992
C.S. File 64/23