

Douglas County Surveyor's Record of  
Government Corners Renewed

21 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97196

42

Northeast Corner Section 10.

Set Lot Marker: Found: 8" Stub N.52°W. 7.26 ft. (scribed)  
SEE #39  
60" Stump S.51°E. 13.86 ft.  
70" Stump S.72°W. 8.58 ft.  
50" Stump N.41°30'E. 29.7 ft.  
Scribed: 8" Madrone S.36°W. 25.5 ft. 121  
10" Fir N.81°40'W. 8.9 ft.  
6" Chinq. S.73°E. 25.3 ft.

Wilford N. Haines  
For Harold Woolley  
Dec., 1957  
M. 7 - 64

North 1/4 Corner to Section 10.

Set Lot Marker: Scribed: 18" Fir N.27°E. 39.0 ft. 43  
SEE #39 20" Fir S.47°W. 42.6 ft. 147

Northwest Corner to Section 10.

Set Lot Marker: Found: 30" Fir N.65°W. 25 lks. 146 44  
SEE #39 12" Fir S.49°W. 61 lks.  
Scribed: 36" Fir N.01°E. 15.0 ft.  
30" Fir S.05'W. 7.5 ft.

West 1/4 Corner Section 10.

Set Lot Marker: Scribed: 20" Cedar N.61°E. 41.5 ft. 45  
(1"x1"x36" T-IRON W/B. CAP #23) 30" Cedar Stub N.61°E. 12.0 ft. 130  
INSCRIBED WILFORD HAINES #23

FD OK Les Roberts 7-96 M125-47

46

Section Corner to Sections 24 & 25 T21S R5W & Secs. 19 & 30 T21S R4W.  
Found - 2 Original BTs. now stumps only, good scribing visible.

N. E. & S.W. BTs. check bearing & distance.

Also find 12" x 8" x 6" Stone with chisled + on top at corner,  
in N. S. Fence Line, Set by Banlau, Oct. 13, 1895.

New BTs: 10" R. Fir bears S.79°E. 9.0 ft. scribed S30 T21S R4W CS BT.  
22" R. Fir bears N.68°E. 27.0 ft. scribed S19 T21S R4W CS BT.  
8" R. Fir bears N.85°W. 67.8 ft. scribed S24 T21S R5W CS BT.  
12" R. Fir bears S.63°W. 32.4 ft. scribed S25 T21S R5W CS BT.

James W. Byron  
S. Bilow  
March 10, 1958  
C. S. File No. 49/68

~~Section Corner to Sections 6 & 7, T21S, R5W, Sec. 1 & 12, T21S, R6W.  
Found - BT's. as recorded by Kerr, 1955.~~

~~Set Brass Cap at Corner Mkd: R6W S 1/3 6 R5W, T21S County Surveyor's  
S12 | S 7 Office, 1958~~

~~RESET - SEE COR. NO. 34 - C.S. FILE 49/89  
SEE COR. NO. 34~~

Section Corner to Secs. <sup>R6W</sup> S36 | S31 <sup>R5W</sup> T.20S  
S 1 | S 6 T. 21S. #161 48

Found- Orig. 30", now 54" Cedar N.36°E. 69.3 ft. I do not open.  
Orig. 20", now 40" Stump, good scribing visible "S" N.87°W. 79.2".  
Orig. 20", Now 42" Stump, shows scar. I do not open. S.82°W.  
Orig. S. E. BT. would be in Roadway.

Set Brass Cap at Corner Mkd: Doug. Co. Surveyor's S36 | S31 R5W./ 58.7 ft.  
Office, 1958 R.6W. S 1 | S 6 T21S. Co.

Note: Corner on South edge of Logging Road.

New BT's: 18" Laurel N. 13°W. 105.0 ft. scribed S36 T20S R6W CS BT.  
14" R. Fir S. 78°E. 24.5 ft. scribed S 6 T21S R5W CS BT.  
19" Cedar S. 75°W. 97.0 ft. scribed S 1 T21S R6W CS BT.  
14" R. Fir N.45°E. 32.4 ft. scribed S31 T20S R5W CS BT.

James W. Byron, Deputy County Surveyor  
M. Godfrey  
S. Bilow  
June 18, 1958  
C. S. File 49/89

1/4 Section Corner to Sec. 6, T21S, R5W, & Sec. 1, T21S, R6W. 49

Found - Rotted Snag S.83°E. 5.3 ft., now approx. 15" diam. Found old  
scars and after chopping in, find evidence of old faces,  
(definitely made by axe) but no sign of any scribing.

FDOK PER GEISLER  
MAY-87 M104-14

Fir Tree, now 22" diam. N.37°W. 7.3 ft. This tree had been  
chopped open previously (upper blaze), and the face burned  
so badly that nothing could be seen on it. Cut open lower  
blaze - found old face definitely made by axe, but only  
one straight scribe mark. Cut open top of upper blaze and  
found partial scribe marks above burned portion. Ring  
Count shows face to have been made approx. 100 yrs. ago.

Set Iron Pipe with Brass Cap at Corner Mkd: 1/4 S 1/3 6 T21S County  
1958 R6W R5W Surveyor's Office

New BT's: 4" D. Fir bears S.54 1/2°E. 16 ft.  
22" D. Fir bears N.32°W. 17 ft.

FD O.K. 6-1965  
PLUS 2.547 275.  
C.B. 83/101