

Douglas County Surveyor's Record of
Government Corners Renewed

T. 21 S. T. S. R 5 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21001

89
 $\frac{1}{4}$ Corner for Sec. 18, T21-5W. & Sec. 13, T21-6W.
 Found - 33" D.Fir S.19°E. 31.0 ft., chopped open & found good scribing - portion of "S".
 42" D.Fir S.17°W. 22.4 ft., partially opened, previously, but not deep enough to expose scribing.
 Set - Brass Cap at Cor. Mkd: County Surveyor's. T21S R6W S13/S18 R5W Office, 1962.
 New BT's: 33" D.Fir S.19°E. 31.0 ft. Mkd: $\frac{1}{4}$ S18 CS BT. (rescribed)
 42" D.Fir S.17°W. 22.4 ft. Mkd: $\frac{1}{4}$ S13 CS BT.
 Corner lies on W. Slope of spur running South from ridge top.
 Corner approx. 60 ft. West of top of spur.

April 17, 1962
 C.S. 49/143

pd. 7/189
 D. Peet
 M 108-55

Possible
 1945 Thiel
 Monument
 their
 Book #1
 Pg 11

90
 $\frac{1}{4}$ Corner to Sections 28 and 27.
 Found - 1 $\frac{1}{2}$ " Iron Pipe in Fence Line (approx. N. & S.
 16" I. Cedar Mkd. by Gardiner in 1955 S.6°E. 92.0 ft. Mkd: $\frac{1}{4}$ S BT", scar not closed.
 Cedar Stump 6 ft. high N.55°W. 81.5 ft., 2" X 6" board nailed to stump scribed " $\frac{1}{4}$ S BT".
 DO NOT SET BRASS CAP. Fence corner on S. side Sand Creek Road bears N. 6°E. 62.0 ft.
 New BT: 8" W.Fir S.14°W. 92.4 ft. Mkd: " $\frac{1}{4}$ S28 US BT".

FOI P.
 1/19/64
 T. Peet
 M 98-35

91
 Section Corner to Sections 28 - 27 - 33 - 34.
 Found - I. Cedar, now 22", scribing visible, "T2 R5 S33" scribed 50 to 55 yrs. ago. From characteristics of scribing, I believe it was marked by Oscar Thiel.
 Gardiner, 1955, found scribed stake at corner-Cedar tree was S.40°W. 32.5 ft. (See Map File M 16 - 6)
 Set - Brass Cap, at point where stake stood (stake no longer in existence)
 Mkd: County Surveyor's

S28	S27
S33	S34

 T21S R5W Office, 1962
 New BT's: 27" W.Fir S.38 $\frac{1}{2}$ °W. 22.5 ft. Mkd: T21S R5W S33 CS BT.
 24" D.Fir N.16°W. 25.4 ft. Mkd: T21S R5W S28 CS BT.
 8" W.Fir N.21°E. 37.0 ft. Mkd: T21S R5W S27 CS BT.
 11" D.Fir S.37°E. 44.8 ft. (one scar) Mkd: T21S R5W S34 CS BT.
 No trace of Original Trees found.

Milo E. Godfrey
 V. Tracy and C. Putnam
 May 1962
 C. S. File No. 49/143

1086 FDOZ BY HAINES
 M102-56

92
 $\frac{1}{4}$ Corner to Sections 2 and 1.
 Found - Partly rotted Fir Stump, now 30", N.78°E. 20.5 ft., chopped open & found good scribing "BT". This stump had been rescribed " $\frac{1}{4}$ S" shortly before it was cut.
 Fragments of rotted Fir Stump, in place, S.23°W. 22.4 ft. Portions of scribing visible on small sliver.
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962
 T.21S: R.5W. $\frac{1}{4}$ S2/S1
 New BT's: 7" D.Fir N.33°E. 6.3 ft. Mkd: $\frac{1}{4}$ S1 CS BT.
 19" Hemlock S.75°W. 26.8 ft. Mkd: $\frac{1}{4}$ S2 CS BT.

93
 North $\frac{1}{4}$ Corner to Section 6, T21S-R5W.
 Found - No trace of Orig. $\frac{1}{4}$ Corner.
 Set - 1" x 1" x 36" T. Iron & Scribed:
 18" D.Fir S.72°E. 27.5 feet.
 18" D.Fir N.36°W. 2.5 ft.

Wilford N. Haines
 For Woolley Logging Co.
 October 1962
 Map M 24 - 30

94
 Center $\frac{1}{4}$ Corner for Section 6.
 Set - 1" x 1" x 36" T. Iron
 Scribed - 10" Fir S.18°E. 12.2 feet.
 10" Fir N. 01°E. 17.2 feet.