

Douglas County Surveyor's Record of
Government Corners Renewed

T 21 T.S. R 6 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97401

Dale Marx L.S.2196
For: Western Pacific
Timber, Inc.
April/May 1987
M 105 - 45

1/4 Corner for Sections 4 and 5
(Searched for not found - Corner set established by single proportion)
Set - 5/8" x 30" iron rod with yellow plastic cap marked
"MARX ASSOCS."

RE-RENEWED, SEE CORNER NO. #141 140

4/87

Douglas County
Surveyors Office
R. Smith
S. J. Flause
March 1, 1988
C.S. 62/50

1/4 Corner for Sections 4 and 5
Found - A 5/8" iron rod with plastic cap marked "Marx & Assocs."
firmly set and protruding 5 in. above ground. Ren. #140
(A limited search was made for original corner and bearing trees. None
were found.)

141

Set - A DCSO 2 1/2" brass cap on a 1 1/2" O.D. x 31" I.P. was set at
referenced position of 5/8" I.R. Cap & Pipe protrudes 3"
above ground. Cap mkd. "Douglas County Surveyors T21S
1/4 S5/S4 R6W 1988". Cap/pipe perpetuates Marx's point.
5/8" I.R. set along northeast edge of DCSO cap, protruding 2"
above ground.

New BTs - 7" dia. Hemlock double blazed and scribed "1/4 S5 CS BT" bears
N.54°W., 22.1 ft.
22" dia. D. fir double blazed and scribed "1/4 S5 CS BT" bears
S.15 1/2°W., 12.3 ft.
5" dia. D. fir double blazed and scribed "X BT" bears N.42°E.,
40.7 ft.
6" dia. D. fir double blazed and scribed "1/4 S4 CS BT" bears
N.80°E., 35.8 ft.

RE-RENEWED, SEE CORNER NO. #159

Corner lies on a steep north slope approx. 500 ft. north of an east-west
ridge and approx. 200 ft. southwest of the convergence of two gullies.

3/1/88

Closing Corner for Sections 5 and 4
Found - No evidence of original monument found.

142

Douglas County
Surveyors Office
S. J. Flause
R. W. Smith
C.S. 62/50
Feb. 19, 1988

A 3/4" "T" iron with a 1" brass washer attached to top is
firmly set and protrudes approx. 2" above ground. Ren. #4
No evidence found of original bearing trees.
12" Fir now 23" DBH D. fir with a fully healed single blaze
bears S.04 3/4°E., 103.3 ft. (Rec. S.02°E., 103.3 ft.) Ren. #4
18" now 29" DBH D. fir with a fully healed single blaze bears
S.80°W., 15.3 ft. as per record. Ren. #4

We perpetuate corner position established in Haines survey and recorded in
Renewal #4 by adding a new bearing tree as follows:

A 5" DBH D. fir scribed "X BT" bearing S.77°E., 8.5 ft. distant.
Monument is on wide low bench near foot of steep easterly slope.

FD OK 10/94 M121-24 A4B

2/19/88

Section Corner for 12 and 13; 7 & 18 of T.21-5

143

Found - A 1961 DCSO brass cap on a 1 1/2" O.D. Iron pipe protruding 10"
above ground. Ren. #81

18" now 29" dia. Cedar with a previously opened burnt blaze
no marks visible, bears N175°W., 23.1 ft. Orig. BT.

35" now 33" dia. 8 ft. high rotted D. Fir stump with cruiser
axe marks on bark, bears N.57°E., 6.3 ft. (Rec. 5.3 ft.)
(Rec. dist. is a possible face measurement) Orig. BT.

27" now 30" dia. 5 ft. high rotted D. Fir stump with a previously
opened blaze, scribing visible "S18 T21S B" bears S.61 1/2°E.,
9.4 ft. (Rec. S.54°E., 9.4 ft.) Orig. BT.

7" now 8" dia. dead Chinquapin with a previously opened rotted
blaze, scribing visible "T21S R5W" bears N.78°E., 19.9 ft.
(agrees w/record) Ren. No.114

16" now 27" dia. D.Fir with a fully healed double blaze bears
S.21°E., 47.1 ft. (Rec. S.19°E., 47.1 ft.) Ren. No. 81

36" now 31" dia. barked 6 ft. high D.Fir stump with a galv. steel
cap on top & a healed blaze, bears S.65°W., 30.2 ft.

24" now 21" dia. barked 7 ft. high D.Fir stump with a galv. steel
cap on top & a healed blaze, bears West 42.0 ft.

New BTs - 7" dia. D.Fir double blazed & scribed "T21S R5W S7 CSBT" bears
N.87 3/4° E., 23.3 ft.

7" dia. Hemlock double blazed and scribed "T21S R6W S12 CS BT"
bears N.73 1/2°W., 13.4 ft.

Corner lies near the East edge of clear-cut.

10/29/91

Douglas County Surveyors Office
Randall Smith - Stephen Flause
October 29, 1991
C.S. File 64/21