

Douglas County Surveyor's Record of
Government Corners Renewed

21

T. S.

06

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97101

161

Steven Ness
For: Weyerhaeuser
M121-24 A&B
Oct. 14, 94

NE cor. sec. 4 - Cond. report.
Monuments FD. - 3 1/4" BLM brass cap on 2 1/4" i.p.
1" "T" iron with 1" brass cap washer, N.1°07'23"W. 17.53'
from BLM mon. (N0°34'W. .265 chs.)
Accessories FD. - 53" D.fir, N.51°16'E. 15.6', healed face, face points to
the Haines mon.
6" D.fir snag, S.43°08'E. 41.9', two small healed blazes,
lower blaze has been damaged by beaver. (S.43°E. 63
lks.).
34" D.Fir stump, S.29°17'W. 38.8', face opened, partial
scribing visible, rest of face is burned. (no rec.)
20" D.Fir, N.37°09'W. 10.6', healed face. (no rec.)

Harvey Christensen
N.W. Timberland Con.
Nov. 10, 1994
M 121 - 21

1/4 Sec. Cor of 36 & 31 of T21-5 - Cond. Report Only
Monuments FD. - 1961 DCSO 2 1/4" B.C.
Accessories FD. - 6" W.Oak, N.20°W. 19.1', healed face
8" W.Oak, S.62°E. 4.9', snag, scribing visible
24" W.Oak, N.79°W. 69.1', healed face, snag
30" W.Oak, (S.51°E. 106.9'), down, rotted, out of position

162

Les Roberts
For: Seneca Jones
Timber Co.
Dec. 1994
M 121-163

SW Township Cor. T21-6 (SW Cor. sec. 31)
CONDITION REPORT ONLY
Found - 1986 BLM iron pipe & brass cap.
28" Fir snag, N.59°E., 37.0' (scribe vis), 1855 BT.
1966 Douglas County brass cap, 0.55' south of 1986 BLM iron pipe
& brass cap. (Ren. #163)
14" Hemlock, N.26°W., 13.2' (scribe vis.), 1966 BT.
15" Hemlock, N.80°E., 25.0' (scribe vis.), 1966 BT.
30" Hemlock, S.61°E., 30.0' (scribe vis.), 1966 BT.

163

1/9/95

DOUGLAS COUNTY
RANDALL SMITH
STEPHEN FLAUSE
11/2/90
CS 64/58

Twship. SE cor. sec. 36
Monuments Fd. - 14"x14"x7" stone with a probable "+" mkd. on side, stone
appears to have been tipped over and is in two
pieces. stone was found 1 ft. below ground. (set by
Haines in 1943 see Ren # 60.)
Accessories Fd. - 40" now 47" dia. D.Fir, with a fully healed single blaze,
bears S.21°E. 31' (agrees w/ rec.) ren. # 60.
8" now 21" dia., D.Fir, with a fully healed double blaze,
bears N.72°E. 56' (agrees w/ rec.) Ren. #60.
10" now 15" dia., B.Oak, with a fully healed double blaze,
bears S.28°W. 18.8' (agrees w/ rec.).
8" now 12" dia., W.Oak, with a fully healed sing blaze,
bears N.2°W. 10' (agrees w/ rec.) Ren. #60.
24" now 24" dia., 14" high rotted oak stump w/ axle marks
visible, bears S.13°W 138.6' (agrees w/ rec.) OBT.
20" now 40" dia., W.Oak with a fully healed blaze, bears
S.7 1/2°E. 97.9' (rec. S.7 1/2°E, 95.7') OBT.
Monument Set A DCSO 2 3/8" dia., brass cap on a 1 1/4" O.D. by 31" long
i.p. is set flush with ground, with corner stone
reset upright along east edge of BC/IP 3" below
ground.

164

DOUGLAS COUNTY SURVEYORS

R T 21 S R
6 S36 | S31 5
W S01 | S06 W
T 22 S

OFFICE 1990

corner lies in middle of old gravel road at north - south fence crossing
Note: This renewal was lost from 11/2/90 to 1/95.

RE-RENEWED. SEE CORNER NO. #145