

Douglas County Surveyor's Record of
Government Corners Renewed

21 T. S. 6 R. W. W. M.

~~Section Corner to Secs. 6 & 7, T21S, R5W, & Sec. 1 & 12, T21S, R6W.
Found - BT's as recorded by Kerr, 1955.~~

28

~~Set Brass Cap at Corner Mkd: R6W S 1 S 6 R5W, T21S County Surveyor's
S12 S 7 Office, 1958~~

~~VOID SEE CORNER NO. 34 - RESET 12/22/59~~

Section Corner to Sections ^{R6W} S36|S31 ^{R5W} T20S
S 1 S 6 T21S #137 29

Found-Orig. 30", now 54" Cedar N.36°E. 69.3 ft. I do not open.
Orig. 20", now 40" Stump N.87°W. 79.2 ft. Good scribing visible "S".
Orig. 20", now 42" Stump S.82°W. Shows scar, I do not open.
Orig. S. E. BT. would be in Roadway.

Set Brass Cap at Corner Mkd: Doug. Co. Surv. ^{R6W} S36|S31 ^{R5W} T20S.
Office, 1958 S 1 S 6 T21S.

Note: Corner on South edge of Logging Road.

New BT's: 18" Laurel N.18°W. 105.0 ft. scribed S36 T20S R6W CS BT.
11" R. Fir S.78°E. 24.5 ft. scribed S 6 T21S R5W CS BT.
19" Cedar S.75°W. 97.0 ft. scribed S 1 T21S R6W CS BT.
14" R. Fir N.45°E. 32.4 ft. scribed S31 T20S R5W CS BT.

RE-RENEWED SEE CORNER NO. 34

James W. Byron, Deputy County Surveyor
M. Godfrey
S. Blaw
June 18, 1958
C. S. File No. 49/89

1/4 Section Corner to Sec. 1, T21S, R6W, & Sec. 6, T21S, R5W. 30

Found - Rotted Snag S.83°E. 5.3 ft., now approx. 15" diam. Found FDOCKEE GEISLER
old scard & after chopping in, find evidence of old faces, definitely made by axe, but no sign of any scribing.
Fir Tree, now 22" diam. N.37°W. 7.3 ft. This tree had been chopped open previously (upper blaze), & the face burned so badly that nothing could be seen on it. Cut open lower blaze - found old face, definitely made by axe, but only one straight scribe mark. Cut open top of upper blaze & found partial scribe marks above burned portion. Ring count shows face to have been made approx. 100 yrs. ago.

Set Iron Pipe with Brass Cap at Corner Mkd: 1/4 S1/S6 T21S County Surveyor's Office, 1958 R6W R5W

New BT's: 4" D. Fir bears S.54 1/2°E. 16 ft.
22" D. Fir bears N.32°W. 17 ft.

Closing Corner to Secs. 1 & 2, T21S, R6W, & Sec. 36, T20S, R6W. 31

Found - Two Original BT's:

Orig. 10", now 36" Stump shows good scar & part of old face, N.59°W. 9.9 ft.

Orig. 10", Now 26" Fir previously opened, shows good scribing, "S2 BT" S.80°W. 15.8 ft.

Also find 1 one inch angle iron set by Haines with 1" disk on top stamped survey point 239 Haines.

Set Brass Cap at Corner Mkd: CC S36 T20S R6W County Surveyor's Office, 1958 S2 S1 T21S

New BT's: 16" R. Fir bears N.16 1/2°W. 27.9 ft. scribed S36 T20S R6W CS BT.
26" R. Fir bears S.80°W. 15.8 ft. scribed CC S2 T21S R6W CS BT.
30" R. Fir bears East 9.0 ft. scribed CC S1 T21S R6W CS BT.

Corner to Secs. 35 & 36, T20S R6W, & Sec. 2, T21S R6W. 32

Found - Orig. 24", now 48" Fir Snag. I open & find good scribing, "BT", S.45°E. 25.1 ft.

All other BT's gone as recorded in 1884.

Also find Haines' Marker at Corner.

Set Brass Cap at Corner Mkd: S35|S36 T20S R6W County Surveyor's Office, 1958 S2 T21S

New BT's: 16" R. Fir bears N.68 1/2°W. 12.0 ft. scribed S35 T20S R6W CS BT.
12" R. Fir bears N.54°E. 45.5 ft. scribed S36 T20S R6W CS BT.

See Note in file for location of these corners in relation to one another.

1/4 Section Corner to Sections 3 & 4. 32-A

Found Rock with X and both old BT's, dead.

Set 1"x 1"x 36" T Iron attached cap 1 1/16" diam., inscribed "Survey Point - Wilford N. Haines #239, Drain, Oregon"

Scribed New B.T's: 48" Fir S.53°E. 50.9 ft.
26" Fir N.49°22'E. 185.3 ft.

Wilford N. Haines #239
C.S. File No. 51/27

JUNE 1959