

Douglas County Surveyor's Record of
Government Corners Renewed

21 T. S. 6 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

63

Sec. Cor. to Secs. 31 & 32, T21-6W. & Secs. 5 & 6, T22-6W.
Found - 40" Fir S.33°E. 33.0 ft. with faint but unmistakable
bark scribing "S5" recognized.
80" Fir Stump N.56°E. 12.5 ft. with traces of old bark scrib.
Stump Hole S. 4°W. 27.7 ft.
Stump Hole N.30°W. 14.5 ft. T21S
Set - Iron Pipe with Brass Cap Mkd: $\frac{S31}{S6} | \frac{S32}{S5}$ T22S R6W
County Surveyor's Off. 1961.
New BT's: 32" R.Cedar N.70°W. 17.0 ft. Mkd T21S R6W S31 CS BT.
6" Hemlock N.19½°E. 20.2 ft. Mkd: T21S R6W S32 CSBT.
16" Hemlock S.48°W. 28.8 ft. Mkd: T22S R6W S6 CS BT.
Rescribe(in wood) 40" Fir S.33°E. 35.0 ft.(to center)
Mkd: T22S R6W S5 CS BT.

Milo E. Godfrey
V. Tracy
C. Putnam
Sept. 11, 1961
C.S. 49/143

FDot
LCS Roberts
12/94 M/21-27

64

Sec. Cor. to Secs. 32 & 33, T21S R6W. & Secs. 5 & 4, T22S R6W.
Found - Rock(Top 4" x 8") with "X" on top & 4 notches on W. face.
Rotted remains of Fir Tree N.52°E. 31.0 ft. No scars or
scribing found, Wright's BT., probably.
Rotted Ring of Fir Stump S.75°W. 22.4 ft.(Gordon & Gardner).
Haines found fragments of reverse scribing on this #127
stump, pieces fastened by wire to our new N.W. BT.
Old remnants of Cedar Stump S.40°E. 11.2 ft., no scribing,G.&G.
No trace found of any ~~to~~ other BT's.
Along side Rock set Iron Pipe with Brass Cap Mkd: County Surveyor's
Office, 1961
T21S $\frac{S32}{S5} | \frac{S33}{S4}$
T22S R6W
New BT's: 8" D.Fir N.85½°W. 14.2 ft. Mkd: T21S R6W S32 CS BT.
12" D.Fir N.6½°E. 23.4 ft. Mkd: T21S R6W S33 CS BT.
19" D.Fir S.21½°W. 22.7 ft. Mkd: T22S R6W S 5 CS BT.
17" D.Fir S.20°E. 20.6 ft. Mkd: T22S R6W S 4 CS BT.

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy and Clete Putnam
November & October 1961
C. S. File No. 49/143

65

¼ Cor. to Sec.32, T21-6W. & Sec. 5, T22-6W.
Found - Fir Tree, 36", N.47°W. 15.2 ft., uprooted & down., shows
good axe scar at bottom. Wilford Haines says he found scribing
about 6 years ago. From position this is lying impossible
to chop open now.
Badly burned Fir Stump bears S.27°E. 13.2 ft. Too much gone to
find scars or scribing.
Set - Iron Pipe with Brass Cap Mkd: County Surveyor's $\frac{1}{4} \frac{S32}{S5} | \frac{T21S}{T22S}$
Office, 1961
New BT's: 38" Fir S.23°E. 45.4 ft.Mkd: $\frac{1}{4} S5$ CS BT., all in one blaze.
30" Fir S.42°W. 47.7 ft. Mkd: $\frac{1}{4} S5$ CS BT, all in one blaze.
No trees near North of Line.

66

¾ Corner to Sec. 30, T21-5 and Sec. 25, T21-6.
Found - Found Haines' "T" Iron & cap at fence corner, Fences E-W & S.
Badly burned old Fir Stump bears S.60°E. 13.2 ft. No scars
or scribing, probably Wright's B.T.
From Monument set by Haines: 24" Fir, bark scribed "½S"(scar below)
bears N.47°W. 27.8 ft.
8" Fir with scar nearly closed bears N.25°E. 9.0 ft.

67

SEC. Cor. to Secs. 24-25, T21-6W. & Secs. 19-30, T21-5W.
Found - Fir Snag, now 20", N.41°W. 4.0 ft., cut open & fd. good scribing.
Fir Snag, now 48", S.15°W. 13.9 ft. No scars or scribing found.
No trace found of N.E. or S.E. Bearing Trees.
Set - Brass Cap Mkd: County Surveyor's T21S R6W $\frac{S24}{S25} | \frac{S19}{S30}$ R5W
Office, 1961
New BT's: 6" D.Fir N.2½°E. 34.0 ft. Mkd: T21S R5W S19 CS BT.
18" D.Fir S. 3°W. 41.3 ft. Mkd: T21S R6W S25 CS BT.
20" R.Cedar S.78°E. 68.6 ft. Mkd: T21S R5W S30 CS BT.
No suitable trees near to N.W.
"T" Iron & Cap set by Haines bears N. 4°W. 13.6 ft.