

Douglas County Surveyor's Record of  
Government Corners Renewed

T 21 S. T. S. R 6 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21891

Section Corner to Sections 23 - 24 - 25 - 26. 73  
 Found - Haines "T" Iron at corner, no cap.  
 Cedar Tree, now 36", N.42°W. 42.2 ft. This tree opened previously, unmistakable but illegible traces of old scribing plainly visible on old face. Recent rescribing found, "T21 R6W". Haines metal disc nailed to old face.  
 Cedar tree, now 27", S.32°E. 18.0 ft., instead of 16.5 ft. Shows axe scar. Did not open. Rescribe this tree, "T21S R6W S25 CS BT."  
 Rotten remains of Cedar Stump N.50°E. 11.2 ft. Too far gone to find scar or scribing. No trace of S.W. BT.

Do not Set Brass Cap.

New BT's: 27" R.Cedar N.54°E. 26.6 ft. Mkd: T21S R6W S24 CS BT.  
 30" R.Cedar S.55½°W. 51.2 ft. Mkd: T21S R6W S26 CS BT.  
 SEE REFERENCE POINTS SET DEC. 1967 BY HAINES - C.S. 49/143

Section Corner to Sections 16 - 17 - 20 - 21. 74  
 Found - Rotten Fir Snag, N.15°W. 44 ft., instead of 47.5 ft., good bark scribing visible "T21S R6W S17".  
 Fir Tree, now 68", N.14°E. 22.4 ft. to face. Traces of faint bark scribing visible. "S" is all I can recognize. Blaze & rescribe this tree "T21SR6W S16 CS BT."  
 Hemlock, now 42", S.69°E. 10.6 ft. (to face) Blaze & Rescribe "T21S R6W S21 CS BT", No trace of S.W. BT.  
 Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1961 

S17	S16	T21S
S20	S21	R6W

  
 New BT's: 11" Hemlock N.68°W. 101.5 ft. Mkd: T21S R6W S17 CS BT.  
 17" Hemlock S.67½°W. 73.0 ft. Mkd: T21S R6W S20 CS BT.

Section Corner to Sections 34 and 35 only, T20S R6W. 75  
 Found - Brass Cap, Co. Surveyor's Office, set by Irving, 1954.  
 20" Cedar N.41°W. 67.0 ft., not 78.0 ft., scribing visible.  
 10" Cedar S.83°E., not N.83°E. 48.5 ft., scribing visible.  
 Blaze & Scribe 10" Fir N.31½°E. 57.9 ft. Mkd: T20S R6W S35 CS BT.  
 Corner in fence corner. Fences run North & West from Corner.  
 Original Bearing Trees all dead or dying.

Closing Corner Sections 3 and 2. 76  
 Found - Remnant of Fir Stump N.59°W. 31.7 ft., part of old face showing, portion of scribed "B" still intact.  
 Remnant of old Fir Stump S.60°E. 62.0 ft., no markings found. No trace of S.W. BT. found.  
 Set - Brass Cap Mkd: County Surveyor's Office, 1961 

S35	T20S R6W
CC S3 / S2	T21S R6W

  
 New BT's: 42" Cedar S.72½°W. 152.7 ft. Mkd: T21S R6W CC S 3 CS BT.  
 10" D.Fir S.20½°E. 109.7 ft. Mkd: T21S R6W CC S 2 CS BT.  
 Haines "T" Iron bears S.66°E. 2.7 ft. - Haines BT. an 18" Fir bears N.70°E. 106.9 ft., pitched over, scribing not visible.  
 Note - Corner Sections 34 and 35, T20S R6W bears West 238.4 ft., record 233.6 ft.

Section Corner to Section 1 - 2 - 11 - 12. 77  
 Found - Haines "T" Iron at Corner - Fir Stump, now 26" S.11°E. 18.5 ft., slope dist., had been previously opened. Good scribing "BT" visible.  
 Rotted remains of Fir Stump N.74°E. 11.2 ft., slope.  
 Rotted remains of Fir Stump S.41°W. 25.1 ft., slope.  
 Rotted remains of Fir Stump N.18°W. 17.8 ft., slope.  
 Last 3 stumps too far gone, no scribing found.  
 Alongside "T" Iron Set Brass Cap Mkd: County Surveyor's Office, 1961 

S 2	S 1
S11	S12

 T21S R6W  
 New BT's: 7" Fir S.67°W. 33.5 ft. Mkd: T21S R6W S11 CS BT.  
 26" Fir S.13½°E. 33.0 ft. Mkd: T21S R6W S12 CS BT.  
 7" Fir N.56°W. 20.2 ft. Mkd: T21S R6W S 2 CS BT.  
 9" Laurel N.17°E. 23.1 ft. Mkd: T21S R6W S 1 CS BT.

Milo E. Godfrey, Deputy County Surveyor  
 Vernon Tracy  
 Cleve Putnam  
 November and December  
 C. S. File No. 49/143

Milo E. Godfrey & Co.  
 V.T. & C.P.  
 December 1961  
 C.S. File No. 49/143

See 1983-84  
 Blm. Resurvey

December 1961  
 C.S. 49/143

POSSIBLE  
 BT. MENTIONED  
 IN F.B.H-75