

Douglas County Surveyor's Record of  
Government Corners Renewed

T 21 S T.S. R 6 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

C.S. 49/143

1/4 Corner to Sections 2 and 11.

Found - Hemlock, now 36", S.50°E. 10.6 ft., scribing visible thru old opening to face, "1/4 S".

Cedar Tree, now 33", N.72°W. 19.8 ft., shows old scars, has been opened previously. Old face rotted away, entire center gone.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1961 T21S R6W 1/4 S 2 S11

New BT's: 8" Hemlock N.59 1/2°W. 22.4 ft. Mkd: 1/4 S 2 CS BT.

11" Hemlock S.69 1/2°E. 32.5 ft. Mkd: 1/4 S11 CS BT.

This corner lies about 40 ft. south of Peterson Creek.

78

FD. OK 12/92  
L. R. OBCATS  
M116-43  
C.S. 49/143

Sec. Cor. to Secs. 13 & 24, R6W and Secs. 18 & 19, R5W.

Found - Cedar Tree, now 30", S.60°W. 33.0 ft., previously opened, scribing "S24 T21S R6" visible on old face, tree nearly dead, whole inside, including face, rotting badly

Cedar Tree, down & dead, N.40°W. 49.5 ft., no scars or scribing found. One whole side burned away.

No trace of N.E. or S.E. Bearing Trees.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1961 T21S R6W S13/S18 S24/S19 R5W

New BT's: 13" D.Fir N.69 1/2°E. 38.7 ft. Mkd: T21S R5W S18 CSBT.

10" Hemlock S.11°E. 18.4 ft. Mkd: T21S R5W S19 CS BT.

22" R.Cedar S.54°W. 57.0 ft. Mkd: T21S R6W S24 CS BT.

52" D.Fir N.63°W. 31.0 ft. Mkd: T21S R6 W S13 CS BT.

79

1/4 Corner to Sec. 12, R6W. & Sec. 7, R5W.

Found - 8" Fir, down & nearly rotted away, N.25°E. 6.6 ft., cut open pitchy scar & fd. good reverse scribing "1/4 S".

No trace of N.W. Bearing Tree.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1961 T21S R6W 1/4 S12/S 7 R5W NOT RENEWED

Old scribed stake bears N.25°E. 2.6 ft. from Corner as Set marked:

"1/4 S" on N.; "S8" on E.; "S12" on W.; & "1/4 S" on S.

New BT's: 16" Hemlock S.87°E. 19.2 ft. Mkd: 1/4 S7 CS BT.

32" Hemlock S.71°W. 18.2 ft. Mkd: 1/4 S12 CSBT.

80

Sec. Cor. to Secs. 12 & 13, R6W. & Secs. 18 & 7, R5W.

Found - Cedar Tree, now 24", N.75°W. 23.1 ft., scribing visible on badly burned & rotted old face "T2-S".

Fir Stump, now 40", N.47°E. 5.3 ft., no scribing, but old axe marks give appearance of having been smoothed off for bark scribing.

Fir Stump, now 34", S.54°E. 9.4 ft., not 10.6 ft. scribing visible on old face which has been previously opened S18 T21S R5W".

No trace of S. W. Bearing Tree.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1961 T21S R6W S12/S 7 R5W S13/S18

New BT's: 36" D.Fir S.65°W. 30.2 ft. Mkd: "T21S R6W S13 CS BT.

24" D.Fir West 42.9 ft. Mkd: T21S R6W S12 CS BT.

16" D.Fir S.19°E. 47.1 ft. Mkd: T21S R5W S18 CS BT.

No trees available in N.E. quad.

81

114

Sec. Cor. to Secs. 18 & 19, R6W. & Secs. 13 & 24, R7W.

Found - Old Mound of Rock at Corner.

Fir Tree, now 40", N.13°E. 30.0 ft., not 37.0 ft. Traces of old bark scribing visible "1 S", legible. Tree in good condition.

Fir Tree, uprooted & down, S.23°E. 49.5, dist., not checked, shows good scars. Did not open.

Mound of Rock N.50°W. 25 lks. not found, area shows evidence of slide. Stub of S.W. not found.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1961 T21S R7W S13/S18 R6W S24/S19

New BT's: 18" Fir S.27°E. 28.5 ft. S19 - 24" Fir S.27°W. 58.0 ft. S24

30" Fir S.84°W. 59.4 ft. S24 - Corner is on very steep slope (45°) on top of vertical Rock Bluff 20 ft. high. (Check notes in file for markings for corner.)

82

Milo E. Godfrey, Deputy County Surveyor  
Vernon Tracy  
Catherine Putnam  
December 1961 - C.S. File No. 49/89