

Douglas County Surveyor's Record of
Government Corners Renewed

21 T. S. 7 R. W. W. M.

KONE-CHAPMAN CO., EUGENE, ORE. 97196

29

Section Corner to Sections 7, 8, 17, & 18.
Found - Orig. 8", now 30" Fir N.19°W. 16.5 ft. I open & find good scribe marks "S".
I find no Oaks in this vicinity.
I do find Chinquapin which are not old enough to be Orig., that check good for record Dist. & Bearing for other BT's.
Set Brass Cap at Corner Mkd: $\begin{array}{c|c} S & 7 | S & 8 \\ \hline S18 & S17 \end{array}$ T21S R7W County Surveyor's Office, 1958
New BT's: 10" R.Fir bears N. 7 $\frac{1}{2}$ °E. 17.3 ft. scribed S 8 T21S R7W CS BT.
12" R.Fir bears S.64 $\frac{1}{2}$ °W. 23.0 ft. scribed S18 T21S R7W.
8" R.Fir bears N.40°W. 34.4 ft. scribed S 7 CS BT.
8" ~~18"~~ Chinquapin bears S.78°E. 23.0 ft. scribed S17 T21S R7W CS BT. #105

James W. Byron, Deputy
M. Godfrey
S. Bilow
August 5, 1958
C.S. File No. 49/20

10/29/75
PER: FASLO
CCKW

30

Section Corner to Sections 8, 9, 16, 17.
Found - Orig. 40", now 50" Fir S.35°E. 5.3 ft., shows good bark scribing.
Orig. 24", now 40" N.30°E. 51.5 ft., shows good bark scribing.
No trace of Orig. S. W. Or N. W. BT.
Set Brass Cap under 48" Log which is 5' above ground. Mkd. Brass Cap $\begin{array}{c|c} S8 & S9 \\ \hline S17 & S16 \end{array}$ T21S R7W County Surveyor's Office, 1958
New BT's: 14" Hemlock bears S.74°E. 5.3 ft. scribed S16 T21S R7W CS BT.
24" R.Fir bears N.58 $\frac{1}{2}$ °E. 42.0 ft. scribed S 9 T21S R7W CS BT.
16" Maple bears N.41°W. 31.9 ft. scribed S 8 T21S R7W CS BT.
No trees near to S. W.

James W. Byron
M. Godfrey
S. Bilow
August 7, 1958
C.S. File No. 49/20

31

Section Corner to Sections 15, 16, 21 & 22.
Found - Hemlock Snag, now 20", N. 8°E. 13.9 ft. Scribe Mks. "21SR", plainly visible in formerly chopped open scar. Ring Count shows this to have been scribed approx. 70 to 75 yrs. ago. (Orig. Survey, 1883).
Old Rotten Stumps to S.E. & S.W. that fit notes of Orig. BT's. (Distances measured on slope) No scribing found on these Stumps.
No trace found of N.W. Bearing Tree.
At Corner Set Iron Pipe with Brass Cap Mkd: "County Surveyor's Office, 1959"
" $\begin{array}{c|c} S16 & S15 \\ \hline S21 & S22 \end{array}$ T21S R7W
Blaze & Scribe New Trees:
20" Hemlock N.80 $\frac{1}{2}$ °W. 18.3 ft. Mkd. "T21S R7W S16 CS BT."
14" R.Cedar S.63° E. 8.2 ft. Mkd. "T21S R7W S22 CS BT."
8" Hemlock N.38°E. 20.0 ft. Mkd. "T21S R7W S15 CS BT."
10" Cedar S.72° W. 38.8 ft. Mkd. "T21S R7W S21 CS BT."

James W. Byron, Deputy
Milo Godfrey
C. Putnam
July 9, 1959
C. S. File No. 49/20

32

$\frac{1}{4}$ Section Corner to Sections 21 & 22.
Found - Fir Tree, now 67", S.37°W. 13.9 ft. (slope dist.), showing bark scribing "B.T. $\frac{1}{4}$ S".
Clump of Small Maples N.25°E. 10.6 ft. (slope dist.)
At Corner Set Iron Pipe with Brass Cap Mkd. "County Surveyor's Office, 1959 T21S R7W $\frac{1}{4}$ S21/S22."
Blaze & Scribe New BT's:
15" Hemlock S.82 $\frac{1}{2}$ °E. 29.0 ft. Mkd. " $\frac{1}{4}$ S22 CS BT."
9" D. Fir N.48° W. 31.7 ft. Mkd. " $\frac{1}{4}$ S21 CS BT."

33

$\frac{1}{4}$ Section Corner to Sections 9 & 16.
Found - 48" Fir Snag N.45°W. 19.8 ft., bark scribed " $\frac{1}{4}$ S BT".
Fir Tree, 64" now, S.44°E. 50.8 ft., showing scars, evidently marked in wood. Did not cut open.
At Corner Set Iron Pipe with Brass Cap Mkd: "County Surveyor's Office, 1959" #55
 $\begin{array}{c|c} S & 9 \\ \hline S16 \end{array}$
Blazed & Scribed New Trees:
28" Hemlock S.15 $\frac{1}{2}$ °W. 85.5 ft. mkd. " $\frac{1}{4}$ S16 CS BT."
24" Maple N.39 $\frac{1}{2}$ °W. 52.0 ft. mkd. " $\frac{1}{4}$ S 9 CS BT."

RENEWED, SEE CORNER NO. 55