

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 21 S. T. S. R. 7 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

86

Township Corner:

Found - Haines' "T" Iron, See Ren. #45, under a 16" Log, set from Orig. BT., as follows:

Orig. 20", now 28" Fir Snag, N. 59° E. 37.6 ft. Open & find "B1 T21 6W" scribe.

All other BT's destroyed.

Set - Brass Cap, 6" South of "T" Iron, alongside Log & Mkd:

County Surveyor's	T21S	R7W	S 36	S 31	R6W
Office, 1966	T22S		S 1	S 6	

New BT's: 7" Hemlock N. 26° W. 13.2 ft. mkd. T21S R7W S36 CS BT.

9" Hemlock N. 80° E. 24.9 ft. Mkd: T21S R6W S31 CS BT.

26" R.Cedar S. 61° E. 29.9 ft. mkd. T22S R6W S 6 CS BT.

No suitable tree close to S.W.

Corner lies on steep, N.W. Slope.

Vernon "Ray" Tracy  
Joe Brady & Jack Heritage  
Sept. 1, 1966  
C. S. File No. 54/14

87

Section Corner to Sections 14 - 15 - 22 - 23.

Found - Orig. 20", now 36" fir, N.25°W. 19.8 ft, alive, shows "2" scribe on prev. opened blaze.

Large hole where S.E. BT. stood. No trace of other BT's.

Ren.#7- Haines' "T" Iron is set from present outside edge of bark.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1967

T21S	R7W
S 15	S 14
S 22	S 23

("T" Iron bears S.25°E. 2.0 ft.)

New BT's: 24" D.Fir N. 81° W. 12.7 ft. mkd: T21S R7W S15 CS BT.

30" D.Fir S. 78° E. 32.2 ft. mkd. T21S R7W S23 CS BT.

10" Hemlock N. 62° E. 13.4 ft. mkd. T21S R7W S14 CS BT.

No suitable tree to S.W.

This corner lies on S.W. side of top of spur, sloping south.

Vernon "Ray" Tracy & Crew  
5/24/67  
C.S. File No. 49/20

MICROFILM TO HERE 10/67

88

Witness Corner to  $\frac{1}{4}$  Corner Sections 11 and 14.

Found - Orig. 24", now 34" Fir Snag Corner Tree, mkd: " $\frac{1}{4}$ " on S. Side, not north as in field notes.

Orig. 20" Fir, N.25°E. 13.2 ft., now only decayed stump and slab with "BT  $\frac{1}{4}$ S" scribe on base of stump hole at locus of other Orig. BT. to S.W.

Set - Brass Cap 5.0 ft. W. of center of old corner tree for W.C.

Witness Corner & Mkd. County Surveyor's Office (Wit. Cor.  $\frac{1}{4}$  S 11 1969 (5' E. to Cor. S 14

New BT's: 34" D.Fir N.65°W. 7.8 ft. mkd: W.C. " $\frac{1}{4}$  S11 CS BT".

36" D.Fir S. 6°W. 52.6 ft. mkd: W.C. " $\frac{1}{4}$  S14 CS BT".

This corner lies on very steep, east slope about 140 ft. East of top of N - S ridge.

8/22/69

Vernon R. Tracy  
J. Heritage & V. Perron  
8/22/69  
C.S. File No. 49/20

89

Witness Corner to  $\frac{1}{4}$  Corner Sections 7 and 18.

Found - B. L. M. 1967 Brass Cap, plus 2 good BT's.

(Our office doesn't have notes for this corner (unapproved) at this time, we used the Brass Cap & tags on each BT.)

8" Alder S.47°W. 47.5 ft., found bark scribing, tagged in 1967.

36" Cedar N.33°E. 27.7 ft., (1954 Tag said N.4OE) Found

scribing to be 33 yrs. old (ring count) on opened face.

Note - We were asked to move this corner as it falls in proposed logging road, No. 21-7-15-1). We set Witness Corner 145 ft.

N. of  $\frac{1}{4}$  Corner. Removed Brass Cap & Reset & Remarkd.

In place where  $\frac{1}{4}$  Corner, Set 5/8" Iron Rod.

Reset Brass Cap at Wit. Cor. Mkd: U.S. Dept. of the Interior

T 21 S	R 7 W	$\frac{1}{4}$	S 7
			S 18

W. C. 145.0 ft. South to 1967

New BT's: 12" Hemlock S.18 $\frac{1}{2}$ °W. 15.2 ft. mkd: "W.C.  $\frac{1}{4}$  S 7 CS BT".

40" Hemlock N.76°W. 27.2 ft. mkd: "W.C.  $\frac{1}{4}$  S 7 CS BT".

Note - Found no stationing good enough to tie Wit. Cor. to at this time as they have set everything other than old P.Line stakes & R/W markers years before.

1/7/70

Franklin W. Jones  
Willie Penley  
1/7/70 C.S. File 56/12