

Douglas County Surveyor's Record of
Government Corners Renewed

21 T. S. 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner, Sections 30, 29, 31, 32. 96
 Found - 1964 HLM Brass cap out of ground.
 Orig. BT. 38" D. Fir, N.27°E., 38.3 ft. As noted no mks. remain.
 10" D. Fir, now 12", N.35°E., 6.6 ft. Shows good scar.
 16" D. Fir, now 19", S.47°E., (Rec. S.53°E.) 19.4 ft. (Rec. 21.8 ft.)
 This tree has undoubtedly slid down hill.
 SW and NW BT's gone.
 Renewal - Using orig. BT and the NE BT, I reset 1964 HLM Brass cap at
 Cor. which is at the top of slide.
 Set - Witness Cor. mkd. County Surveyor's Wit. Cor. 36' W. to
 Office T 21 S R 7 W
 1973 S30 S29
 S31 S32
 New BT's - 25" D. Fir, N.48°E., 22.7 ft. Scribed T21S R7W S29 WC CS BT.
 8" Chinquapin, N.4°E., 14.1 ft. Scribed T21S R7W S29 WC
 CS BT.
 5/10/73

John M. Powell, County Surveyor's Office
G. Commons
May 10, 1973
C.S. 56/25

East 1/16 Corner, Sections 20 and 29. 97
 Found - HLM Brass Cap out of ground.
 11" D. Fir, now 13", S.74°E., 23.8 ft. Shows good scar.
 NW tree down.
 Renewal - Reset HLM Brass cap at E 1/16 Corner.
 New BT - 10" D. Fir, N.70°W., 19.3 ft. Scribed E 1/16 S20 CS BT.
 5/10/73

1/2 Cor. for Sec. 12 and 13. 98
 Found - 1" x 1" T-Iron in place and bent. Ren. No. 60
 16" now 20" D. Fir, bears S.53°E., 50.4 ft. (rec. S.53°E., 50.7 ft.)
 I open and find good scribing "3"
 Record 12" D. Fir, now down and burned, bears N.71°E., 72.6 ft.
 (rec. N.51 1/2°E., 75.7 ft.) Blaze burnt out. This tree may not
 be in its record position due to logging activity.
 Set - Brass cap alongside T-Iron mkd. COUNTY SURVEYORS T 21 S
 (set flush with ground) OFFICE 1/4 S 12
 1974 S 13
 R 7 W
 New BT's - 20" D. Fir bears N.11°E., 115.6 ft. scribed 1/4 S12 CS BT.
 Note - This corner lies on steep north slope in recent logged-over area.
 (4/24/74-Set steel fence post alongside brass cap.) 1/14/74

Gary Langlitz, Surveyor's Office
P. Earle
Jan. 14, 1974
C.S. 56/43

S 1/4 Corner for Sec. 34 only of T20-7 99
 Found - "X" chiseled on large sandstone boulder.
 1" x 1" T-iron bears north 1.1 ft. Ren. No. 81
 Rec. 28", now 30" D. Fir bears N.77°W., 99.5 ft. Shows well-
 healed scar.
 New BT - 30" D. Fir, bears N.19°W., 99.6 ft. scribed 1/4 S34 CS BT"

Gary Langlitz
P. Earle
C.S. 56/43
2/5/74

Section corner for Secs. 4 and 3 only. -100
 Found - 1" x 1" T-iron with copper washer mkd. Wilford N. Haines 239, Survey
 Point Drain, Oregon. Ren. No. 23
 12" Red cedar, bears S.55°W., 31.3 ft. scribed "T21S R7W S4 CC BT"
 in open blaze.
 14" Fir, now dead bears S.51°E., 22.8 ft. (rec. S.46°E., 22.8 ft.)
 with visible blaze.
 Orig. BT to the NW is now a shattered stump with blazed portion
 missing.
 Set - Brass cap alongside T-iron mkd. COUNTY SURVEYORS T 20 S
 OFFICE S4 | S3
 1974 CC
 T21S R7W
 New BT's - No suitable trees near, I mark
 14" Red cedar stump, bears S.11°E., 26.8 ft. scribed "CS BT"
 Note - Corner lies at lower edge of old cat road.
 2/12/74

Gary Langlitz, Surveyors Office
P. Earle
C.S. 56/43
Feb. 12, 1974