

Douglas County Surveyor's Record of
Government Corners Renewed

T 21 S T. S. R 7 W R.W.W.M.

KORE-CHAPMAN CO., EUGENE, ORE. 21891

101

Gary Langlitz, Surveyors Office
P. Earle
C.S. 56/43
Feb. 11, 1974

Section Cor. for Secs. 33 and 34 only, T20-7
Found - Orig. 36", now 38" D. Fir with scribing "20S R7W S33"
showing on previously opened blze. Ren. No. 22
A tagged fir to the NE does not fit proper bearing & distance.
Set - Brass cap at record bearing & distance from OBT mkd:
COUNTY SURVEYORS T 20 S R 7 W
OFFICE S 33 | S 34
1974 T21S

from which
orig 36" now 38" D. Fir bears ~~N. 32° W.~~ ^{N. 57° W.}, 9.9 ft.
A 1" x 1" T-iron with copper washer attached mkd. Wilfird N.
Haines 239 Survey Point Drain, Oregon, bears S. 25 1/2° W., 3.6 ft.
New BT's - An 8" Red cedar bears N. 65 1/2° E., 11.8 ft. scribed "T20S R7W
S34 CS BT"
A 6" Red cedar bears N. 47° W., 22.0 ft. scribed "T20S R7W S33
CS BT"

2/11/74

102

Gary Langlitz, Surveyors Office
John E. Nordling
Jan. 16, 1975
C.S. 57/17

1/4 corner for Secs. 10 and 15.
Found - "T" Iron set by Haines in 1965, firmly set from which the
only remaining bearing tree marked by Haines, An 11" Hemlock
now a stump bears S. 72° W., 11.2 ft. with scribing "1/4S BT"
visible on unhealed blazes. Ren. No. 83
Haines NE BT has been completely removed.
At the corner point we set: A 1"x30" Iron pipe with brass cap attached, mkd.
COUNTY SURVEYORS T 21 S
OFFICE 1/4 S 10
1975 S 15
R 7 W

We deposit the "T" Iron alongside the brass cap and mark the following BT's
A 10" Hemlock bears S. 66° W., 55.1 ft. scribed "1/4 S15 CS BT."
An 11" Hemlock bears N. 9° W., 37.0 ft. scribed "1/4 S10 CS BT."
This corner is located in a clearcut unit near the top of a small ridge
sloping steeply to the northeast.
Compass declination setting: 20° East.

1/16/75

103

Gary C. Commons,
Peter L. Earle
Surveyors Office
Jan. 29, 1975
C.S. 57/17

Closing Corner for Secs. 4 and 3, T22-7.
Found - Haines "T" iron and cap. Ren. #64
A 12" Red Cedar now 18", S. 17° E., 41.8 ft. scribe visible.
D. Fir, 64", S. 20° E., 37.6 ft. Is now blown down.
Set - 1" x 30" Iron pipe with brass cap marked:
COUNTY SURVEYORS T 21 S R 7 W
OFFICE S 33
1975 S 4 | S 3
T 22 S R 7 W
CC

New BT - A 6" Hemlock, S. 48° E., 43.2 ft. mkd. CC T22S R7W S3 CS BT.
Se set Haines "T" iron along side the cap. Corner lies in bottom of draw
center line north-south.
Compass declination: 20° east.

1/29/75

104

L E Monrean
P.L Earle
C.S. 57/36
10/29/75

Sec. Corner For Sec. 7&18 T21-7 and Sec. 12 & 13 T 21 S, R8W.
Found: G.L.O. 1954 Brass Cap properly marked.
13 " now 15" diameter Hemlock stump, bears N 48° E., 19.0 ft. (Record 19.8ft)
has good blaze.
10" now 11" diameter Hemlock stump, bears S 58° E., 24.2 ft. (Record 25.1 ft.)
has good blaze.
38" Fir stump bears S 56 1/2 ° W., 13.9 ft. Has good blaze.
8" now 12" Hemlock stump bears N 59 1/2° W., 19.7 ft. (Record 19.1 ft.)
I open portion of blaze and find good scribing "S 12 BT"..
NOTE: Bark has been removed from all bearing tree stumps and a preservative has
been applied. Stumps have been capped with aluminium sheet metal and are
tagged.
Renewal: A cedar, 7 1/2" Dia. bears S27 1/2° W., 45.6 ft. Scribed "T 21 S R8W S13
CS BT" Tree is growing out from the N NE side of 52" dia. Fir stump
Large blaze is 5 ft. above ground, bearing and distance were recorded
from the height described.
No other B.T.'s were scribed as corner lies in clear cut area 10-29-75