

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 21 S. T.S. R. 8 W. R.W.W.M.

FOKE-CHAPMAN CO., EUGENE, ORE. 91881

DOUGLAS COUNTY  
SURVEYORS OFFICE  
RANDALL SMITH &  
STEPHEN FLAUSE  
MAR. 17, 1997  
C.S. 64/74-1

see previous ren. #52

South Sec. Cor. to 33 & 34 ONLY

56

Mon. Fd.- BC/IP not found (1945) metal fence post found out of ground.  
Alum. nail per M124-44  
Bt's Fd.- 26" now rotted down Hemlock, indeterminable size no scribing  
visible, bears N.46 3/4°W., 57.4' (agrees with rec.) 1945  
8" now 10" dia. Red Alder, with a partially healed double blaze  
illegible scribing visible, bears N.55°W., 34.7' (agrees with  
rec.) 1975  
7" now 16" dia. D.Fir, with a fully healed double blaze, bears  
N.51°E., 22.3' (rec. N.51°E., 23.6' dist. fits a slope  
measurement) 1975  
Mon. Set- Position of Aluminum nail is referenced, a small ledge is  
chisled out and a 2" dia. brass disk is cemented onto sand  
stone ledge at position of referenced nail.  
New Bt's- 16" dia. D.Fir double blazed and scribed T21S R8W S34 CS BT",  
bears N.2 1/2°E., 35.3'.  
11" dia. D.Fir double blazed and scribed T21S R8W S33 CS BT",  
bears N.76°W., 8.3'.  
Corner lies on a steep north slope (sand stone shallow soil)

NW COR. SEC. 18

57

Mon. Fd. - 1945 GLO IPBC  
BT's Fd. - 20" Fir, N.18°E., 29.7', down and rotten.  
30" Fir, S.57°E., 102.3', down and rotten.  
12" Fir, S.35°E., 34 lks., snag.  
13" Fir, N.74 1/2°, 16 lks., good-healed face  
6" Fir, S.87°E., 74 lks., snag  
New Accessories -  
13" Fir, S.11°E., 20' scribed "S 18 BT".  
16" Fir, S.18°W., 18.8' scribed "SC BT".  
11" Fir, N.4°W., 18.3' scribed "SC BT".  
-----

SE Closing COR. SEC. 12 T21-9

58

Mon. Fd. - 1945 GLO IPBC  
Bt's Fd. - 50" Cedar stump, S.28°W., 70' burnt stump.  
18" Fir stob, N.34°W., 165.7' scribed visible.  
13" Fir, S.18°W., 44 lks. good healed face.  
New Accessories -  
10" Fir, N.33°W., 16.5' scribed "S 12 BT".  
12" Fir, S.14°E., 16.5' scribed "SC BT".  
14" Fir, S.76°E., 21.7' scribed "SC BT".

WEST 1/4 COR SEC. 18 ONLY

59

Mon. Fd.- 1945 GLO IPBC  
Bt's Fd.- 15" Fir, S.80°E., 17 lks., good - healed face  
14" Fir, N.31 1/2°E., 47 lks., good - healed face - tag 7 1/2' up tree  
Root hole N.85 1/2°E., 217 lks. - remains of 1945 BT  
New Accessories -  
11" Fir, N.4°W., 17.3' scribed "1/4 BT"  
6" Fir, S.12°E., scribed "1/4 BT" 13.0 5+

1/4 Cor. secs. 33 & 34, T21-8

60

Found - 1945 brass cap.  
BTs & corner tree gone down the hill.  
New BTs - 9" Fir scribed: 1/4 S34 BT bears N.17°E., 16.2 ft  
5" Fir scribed: 1/4 S34 BT bears N.50°E., 11.7 ft  
28" Fir scribed: 1/4 S34 BT bears S.38°E., 22.5 ft  
A Steel post bears North 15.45 ft.

Mark F. Smalley  
Roseburg Forest Products  
Mar. 13, 1997  
C.S. 65/13-9A&B

MARK SMALLEY  
ROSEBURG FOREST  
PRODUCTS  
Mar. 18, 1997  
C.S. 65/15-9

David Edwards  
5/7/1999  
C.S. File 65/23-9