

Douglas County Surveyor's Record of  
Government Corners Renewed

21 T. S. 9 R. W. W. M.

KOBE-CHAPMAN CO., EUGENE, ORE. 97106

Claude Kerr  
No. 2125  
July 23, 1951  
C. S. File No. 40/574

1/4 CORNER OF SECS. 28 & 33.

Found the two small Fir original BTs. Found the old scribe #19 reading 1/4 S BT on both of them. These BTs are both small snags now and would not last long.

Set a 4"x4" stake at the corner and marked two new BTs.

A Fir 12" in diameter bears S39° E for 24 feet, marked 1/4 S 33 BT  
A Hemlock 14" in Diameter Bears N 23°30'E for 18 ft, marked 1/4 S 28 BT.

M.E. Godfrey, Deputy C.S.  
Wm. Stoffel & Mike Stone  
Sept. 25, 1963  
C. S. File No. 52/14

TOWNSHIP CORNER

	T21S		
R9W	S 36	S 31	R8W
	S 1	S 6	
	T22S		

FD OK  
V. McLind  
M127-77  
10/97

Found - Brass Cap set by Cadastral Survey of 1945, bulldozed out & buried in ground, lying across corner position.

38" Fir Stump N.12 1/2°W. 12.5 ft.

48" Fir Stump S.18 1/2°W. 163.0 ft., axe marks in bark "S1 BT".

Burned remnants of big Fir Stump S.21 1/2°E. 18.5 ft.

38" Fir Stump N.36°E. 107.6 ft.

36" Fir Stump N.37°E. 34.3 ft.

No scribe marks found - No trace of other old BT's.

Reset - Gov't. Brass Cap in proper position.

Rescribe - 38" Fir Stump N.12 1/2°W., 12.5 ft., "T21S R9W S36" (broke scribe)  
No live trees available.

Mile E.  
Godfrey &  
Crew  
Oct. 7, 1964  
C. S. File  
No. 52/14

1/4 Corner to Sections 29 and 28.

Found - Hemlock Snag (not Fir) N.77 1/2°E. 15.2 ft., good reverse scribing "1/4" & "BT" on badly rotted face.

Did not find Corner Tree nor N. W. BT.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964

T21S R9W 1/4 S29 / S28

New BT's: 30" Hemlock S.48°W. 59.0 ft. Mkd: 1/4 S29 CS BT.

21" D. Fir N.53°E. 33.2 ft. Mkd: 1/4 S28 CS BT.

Note - Corner is in draw sloping East, approx. 10 ft. N. of bottom.

Mile E.  
Godfrey &  
Crew  
C. S. File  
No. 52/14

Section Corner to Secs. 16 - 17 - 20 - 21.

Found - Rock at Corner, marked as described.

45" Fir N.40°W. 5.9 ft., shows good scar.

44" Fir N.19°E. 17.8 ft., shows good scar.

24" Fir S.49°E. 60.7 ft., very plain scar.

46" Fir S.59°W. 56.1 ft., scar has been destroyed by injury.

Set - Brass Cap at Cor. Mkd; County Surveyor's Office, 1964  
(alongside Rock) T21S R9W S 17 / S 16  
S 20 / S 21

New BT: 14" Hemlock S.58 1/2°W. 49.5 ft. Mkd: T21S R9W S20 CS BT.

Oct. 20, 1964

MICROFILM TO HERE 10/67

John M. Powell  
Frank Jones & W. Penley  
Sept., 1969 = C.S. 53/66

1/4 Corner to Sec. 6, T21-9W. and Sec. 31, T20-9W.

Found - GLO Brass cap properly marked in 1953.

Brass Cap in Fence Row North 203.3 ft.

1 1/2" Iron Pipe in Bedrock bears N.86°E. 351.8 ft.

25" Cedar, now 36", S. 86°W. 91.7 feet. No trace of N. E. BT.

New BT: 19" Cedar N.73°E. 255.2 ft. mkd: "1/4 S31 CS BT.

Reblzd. & Rescbd: 36" Cedar S.86°W. 91.7 ft. mkd: "1/4 S 6 CS BT".

Section Corner Thus: T 20 S  
R10W S 36 / S 31 R9W T21S  
S 1

Found - GLO Brass Cap properly marked in 1951

16", now 27" Cedar, N.66 1/2°E. 17.2 ft., shows good scar. (See #1, 7.20-9)

16", now 19" Cedar, N.57°W. 34.3 ft., scribe visible. "S".

New BT: 24" Maple S.24°E. 29.8 ft. mkd: "T21S R10W S1 CS BT".

Also tagged other Bearing Trees.

FD 2193  
BY ward  
M116-61