

Douglas County Surveyor's Record of  
Government Corners Renewed

21 T. S. 9 R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 21881

$\frac{1}{4}$  Corner to Sections 29 and 32. 13  
Found - 40" D. Fir, now 60", S.69°W., 30.4 ft. Opened for scribind  $\frac{1}{4}$ S.  
No trace of NE BT.  
Set: Brass Cap at  $\frac{1}{4}$  Cor. Mkd: County Surveyor's Office 1971  
T 21 S  
 $\frac{1}{4}$  S 29  
S 32  
R 9 W  
New BT's: 22" D. Fir, S.15°W., 17.5 ft. scribed  $\frac{1}{4}$ S32 CS BT.  
14" D. Fir, N.87°W., 18.3 ft. scribed  $\frac{1}{4}$ S29 CS BT.  
9/28/71

Section Corner to 31, 32 T21-9 14  
Found - 8" Fir, N.17 $\frac{1}{2}$ °E., 103.6 ft. This tree opened years ago & rotten.  
30" Fir, S.73°E., 128.7 ft. This tree destroyed in 1894.  
I do not find NW BT.  
Using these two trees, call on top of ridge of 42.9 ft. and coming 207.2 ft.  
east from closing corner of  $\frac{31}{615}$  I

Set: Brass Cap at sec. cor. mkd: County Surveyor's Office 1971  
T 21 S R 9 W  
S 31 | S 32  
S 5  
T 22 S  
New BT's: 22" D. Fir, N.83°E., 22.1 ft. Scribed T21S R9W S32 CS BT.  
22" D. Fir, N.13°W., 24.7 ft. Scribed T21S R9W S31 CS BT.  
10" D. Fir., S.21°E., 15.0 ft. Scribed S5 CS BT.  
9/29/71

Closing Corner to Sections 6 and 5 T22-9 15  
Found - Splintered Stump, N.17°W., 42.9 ft. Scribed found "BT".  
Possible BT, rotten and down, S.27 $\frac{1}{2}$ ° W., 59.4 ft.  
I did not find SE BT.  
Call on creek (draw) of 313.5 ft. from  $\frac{31}{615}$  | 32 or 106 ft. from  $\frac{31}{615}$  hits good.  
Set: Brass Cap at C.C. mkd: County Surveyor's Office 1971  
T 21 S R 9 W  
S 31  
S 6 | S 5  
C.C.  
T 22 S  
New BT's: 18" D. Fir, S.61°W., 10.6 ft. Scribed T22S R9W S6 CC CS BT.  
10" D. Fir, S.26°E., 17.6 ft. Scribed T22S R9W S5 CC CS BT.  
9/29/71

Sec. Corner to Sections 33 and 34, T21-9W only. 16  
Found - 1" I.Pipe at Sec. Cor., unrecorded.  
24" D.Fir, now 46" Stump, N.88°W. 38.9 ft., opened  
for scribe "9W & other marks.  
24" D.Fir, now 40" Stump, S.76 1/2°W. 42.9 ft.,  
shows axe work.  
No trace of S. E. Bearing Tree.  
New BT's: 6" D.Fir N.53°W. 4.0 ft. scribed S33 CS BT.  
6" Maple N.24°E. 12.9ft. scribed S34 CS BT.  
6" D.Fir S.80°E. 7.0 ft. scribed S 3 CS BT.  
This corner lies approx. 80.0 ft. E. of sküd road on ridge top.  
10/5/71

S.W. Corner Section 19. 17  
Corner obliterated by slide from the newly constructed road.  
Found - Orig. BT. 1894 Survey by Alonzo Gesner who re-established  
Sec. Corner from this BT: 34" Fir bears N.49°45'W.  
for 72 lks. to face of tree. Find axe marks & a grown-  
over face.  
Set - 1/2" x 18" reinforcing rod 8" into solid sandstone on  
West facing slope.  
Marked: 30" Fir bears N.45°00'W. for 84 ft. to centerline.  
Tree faced and scribed "Sec.Cor."  
36" Fir bears N.9°00'E. for 62 ft. to centerline tree.  
Tree faced and scribed "Sec. 19 Cor."

John M. Powell  
W. Penley  
J. Heritage  
September, 1971  
C.S. File 53/66

G. Wylie Smith III  
For: ELM  
Dec. 30, 1971  
C.S. File No. 55/230

Jan. 1972