

Douglas County Surveyor's Record of
Government Corners Renewed

T. 21 T. S. R. 9 R. W. W. M.

KOBE-CHAPMAN CO. EUGENE, ORE. 21881

25

Gary Langlitz, Surveyors Office
Pete Earle
C.S. 56/49
March 6, 1974

Section corner, Secs. 29, 28, 32 and 33.

Found - 1966 BLM brass cap, out of the ground, laying at the base of the orig. NW bearing tree.

BT's - 88" D.Fir bears N.33 3/4°W., 37.6 ft. (to the face of the tree) an orig. BT being previously opened, no marks visible.

The remains of an orig. BT, a 20" decayed fir stump bears N.18°E., 52.8 ft. (to the face) no marks remaining.

35" now 36" big leaf maple, bears S.36°W., 40.3 ft. (rec. S.33°W., 40.3 ft.) with a healed blaze.

All remaining orig. and 1966 resurvey corner accessories have been displaced or destroyed due to recent road building and a subsequent landslide. Since the corner location is in the slide area,

I set - A brass cap as a witness corner 55' west of the true corner mkd:

COUNTY SURVEYORS T 21 S R 9 W
OFFICE Wit. Cor.
1974 S 29 | S 28

S 32 | S 33
55' east to cor.

RE-RENEWED OFF CORNER NO. 58

From which I mark the following bearing trees:

18" hemlock bears N.10°W., 21.0 ft. scribed "WC T21S R9W S29 CS BT."

24" big leaf maple bears S.32 1/2°W., 52.2 ft. scribed "WC T21S R9W S 32 CS BT".

No trees suitable to the NE and SE.

This witness corner lies approx. 70 ft. west of a newly constructed dirt road.
3/6/74

26

Section Corner for 21, 22, 28 and 27.

Found - An orig. bearing tree, a 24" Maple, now a well-rotted stump.

We find good scribe marks on the reverse face.

The orig. NE and SW bearing trees are missing.

We find a 34" Cedar stump in the record position of the orig.

SE bearing tree. It is covered by logging debris and we cannot identify it as an orig. BT.

We find no trace of the orig. corner monument.

At the corner point as determined at record bearing and distance from the one remaining orig. BT, a 24" Maple, now a stump which bears N. 80 1/4°W., 11.2 ft. we set a 1"x30" Iron pipe with brass cap attached marked:

COUNTY SURVEYORS T 21 S
OFFICE S 21 | S 22
1975 S 28 | S 27
R 9 W

and mark the following bearing tree:

A 13" Hemlock bears N.16°E., 54.5 ft. scribed "T21S R9W S22 CS BT.

There are no other trees near.

Compass declination setting: 20° East.
1/15/75

Witness Corner to Closing Clorner Sec.1 T21-10 Sec 6 T21-9

Found- A cedar 40" now 52" in diameter bears S 42°E., 44.5 ft. (rec. 46.2 ft. blazed.

A cedar 45" now 55" in dia. bears N 38°W., 21.8 ft. scribed "WCC T21S R 9 & 10 W"

Maple bearing tree not found, bearing distance recorded falls in large growth of maples in slide area.

Set: Brass cap at witness cor. to closing cor. stamped:

COUNTY SURVEYOR'S OFFICE T20 S R9W
1975 - CC

S 1 | S 6
R10W | R9W

Note: Corner lies near south bank of Smith River, nearly directly across river from fence running North & South at East end of Fawn Creek Park
11/5/75

Gary L. Langlitz, Surveyors Office
John E. Nordling
Jan. 15, 1975
C.S. 57/17

L.E. Monrean
P.L.E.
D.L.S
CS 57/39
11/5/75