

Douglas County Surveyor's Record of
Government Corners Renewed

T 21

T. S.

R 10

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97501

100

Section corner for Secs. 17 and 20 only.
Found - 2" iron pipe with cap broken off. Concrete stem is all that remains.
36" hemlock bears N.29°W., 23.8 ft. (Orig. BT 30")
16" hemlock bears S.64°W., 36.5 ft. (Orig. BT 10" Rec. S.67°W., 48.8 ft.) with healed face.
Set - 2 1/2" x 30" alum. pipe, 20" in the ground with 3 1/4" alum. cap mkd. "US Dep of Agri-Forest Service T21S R10W S17 S20 RLS 1651 1983 Unlawful to disturb".

101

Section corner for Secs. 16 and 21 only.
Found - 2" iron pipe with concrete stem. Brass cap missing.
10" maple bears N.23°E., 16.5 ft. (Orig. 7" BT, Rec. N.25°E., 15.4' with healed face.
14" fir snag bears S.73°E., 27.7 ft. (Orig. BT) (Rec. 27.5 ft.) with healed face.
Set - 2 1/2" x 30" alum. pipe, 18" in the ground with 3 1/4" alum. cap mkd. "US Dep of Agri-Forest Service T21S R10W S16 S21 RLS 1651 1983 Unlawful to Disturb".
New BT - 8" D. fir bears S.18°E., 3.2 ft. scribed "T21S R10W S21 BT". Tree is on top of rock bluff 8 ft. above corner.

102

Witness corner for the 1/4 corner for Secs. 16 and 21.
Found - 1" iron pipe filled with concrete. No cap. Found charcoal in hole.
20" alder bears N.46°W., 25.1 ft. (Orig. BT., Rec. N.48°W.)
24" cedar bears S.40°E., 45.5 ft. (Orig. BT., Rec. S.41°E.)
Set - 2 1/2" x 30" alum. pipe, 22" in the ground with 3 1/4" alum. cap mkd. "US Dep of Agri-Forest Service 33.0 ft. T21S R10W WC 1/4 S16 S21 RLS 1651 1983 Unlawful to Disturb".

103

1/4 Corner for Sections 7 and 8
Found - 1" concrete filled iron pipe with 1919 GLO brass cap.
48" D. fir bears N.86°E., 11.9 ft. Good scar.
20" cedar bears N.63°W., 22.9 ft. (Rec. 27.7 ft.) Good scar.
Set - 2 1/2" x 30" alum. pipe at corner location, with 3 1/4" alum. cap mkd. "USDA Forest Service T21S R10W 1/4 S7 S8 RLS 1651 1984 Unlawful to disturb".
Buried found cap alongside set monument.

104

Center 1/4 Corner Section 8
Set - 17" D. fir, for corner, scribed "C 1/4 S8" on south side. Attached 2 land survey tags and brass washer mkd. "RLS 1651" to tree. Reference monument, a 2 1/2" x 30" alum. pipe, 18" in the ground with mound of stone, with 3 1/3" alum. cap mkd. "USDA Forest Service T21S R10W S83°E 10.3 ft C 1/4 S8 RM RLS 1651 1984 Unlawful to disturb", bears N.83°W., 10.27 ft.
New BT - 24" D. fir bears N.1°W., 12.5 ft. scribed "C 1/4 S8 BT".

105

Southwest corner Section 8
Found - 2" I.P. with 1919 GLO 2 1/2" brass cap properly mkd., rusted and broken.
39" D. fir windfall bears S.88°E., 45.6 ft. to approx. position of root hole. Tree slid downhill. Orig. BT.
Set - 2 1/2" x 30" alum. pipe, 6" above ground with 3 1/4" alum. cap mkd "USDA Forest Service T21S R10W S7 S8 S17 RLS 1651 1983 Unlawful to Disturb". Buried brass cap alongside.
New BTs - 64" D. fir bears N.80°E., 33.1 ft. blazed and scribed "T21S R10W S8 BT".
13" Bigleaf maple bears S.80°E., 45.1 ft. blazed & scribed "T21S R10W S17 BT".

Herman Pieske
L.S. 1651
For: U.S. Forest
Service
Cooked Wassen
Cadastral Survey
August, 1984
M 97 - 33 A&B

Herman Pieske RLS #1651
AA Surveying Company
For: U. S. Forest Service
November 1984
M 97 - 74 A & B