

Douglas County Surveyor's Record of
Government Corners Renewed

T 21

T. S.

R 10

R. W. W. M.

FORE-CHAPMAN CO., EUGENE, ORE. 21881

113

Section corner for Sections 7 and 18; and Secs. 13 and 12 of T.21-11.
Found - Original 60" cedar corner tree, now down. See Ren. #72
49" cedar (orig) bears S.35°W., 34.3 ft. healed blaze.
Set - 5/8" x 30" iron rod with plastic cap mkd "AA Surveying Service
Inc" in root wad at corner.
New BTs - 10" alder bears S.32°20'E., 19.5 ft. bark scribed "T21S R10W
S18 BT".
8" alder bears N.20°30'E., 21.4 ft. bark scribed "T21S R10W S7 BT"
17" alder bears N.47°W., 19.2 ft. bark scribed "T21S R11W S12 BT".
Set - Reference monument, a 2 1/2" x 30" alum. pipe with 3 1/4" alum.
cap mkd. USDA Forest Service T21S RM R11W N4°E 27.9 ft.
S13 RLS 1651 1983 Unlawful to Disturb".

114

North 1/4 Corner for Section 18 only
Set - 2 1/2" x 30" alum pipe 12" in the ground to bedrock with mound
of stone, with 3 1/4" alum. cap mkd "USDA Forest Service T21S
R10W 1/4 S18 RLS 1651 1984 Unlawful to Disturb"
New BTs - 18" D. fir bears S.20°W., 21.2 ft. blazed and scribed "1/4 S18 BT"
8" D. fir bears S.76°E., 8.6 ft. blazed and scribed "1/4 S18 BT".

115

South 1/4 Corner for Section 7 only.
Set - 2 1/2" x 30" alum pipe with 3" alum cap mkd "US Dep of Agri-
Forest Service T21S R10W S7 1/4 RLS 1651 1984 Unlawful to
Disturb".
New BTs - 24" D. fir bears N.24°W., 49.7 ft. blazed and scribed "1/4 S7 BT"
18" D. fir bears N.8°E., 96.4 ft. blazed and scribed "X BT".

116

Northwest corner for section 17
Found - 2" iron pipe well rusted & filled with concrete, 1919 brass cap
broken off, not found.
66" cedar bears S.60°W., 18.5 ft. good scar
Set - 2 1/2" x 30" alum pipe over iron pipe, 24" in ground with 3 1/4"
alum cap mkd "US Dep of Agri-Forest Service T21S R10W S7 S18
S17 RLS 1651 1983 Unlawful to Disturb". Buried pipe alongside.
New BT - 16" hemlock bears S.61°E., 154.2 ft. blazed & scribed "T21S
R10W S17 BT".

~~117~~

~~Southeast corner Section 7
Found - 2" I.P. with 1919 GLO brass cap properly marked.
46" D. fir bears N.47°W., 38.9 ft. Good scar
New BT - 40" maple bears S15°E., 20.8 ft. blazed & scribed "T21S R10W
S17 BT".~~

118

West 1/4 Corner for Section 18 only.
Found - 1 1/2" I.P. with brass cap broken off. (GLO 1919)
Set - 2 1/2" x 30" alum pipe, 5" above ground with 2 ft. mound of
stone with 3 1/4" alum cap mkd "USDA Forest Service T21S R10W
1/4 R11W S18 RLS 1651 1984 Unlawful to Disturb". Buried brass
cap and pipe alongside.
Found - 32" cedar bears S.23°E., 5.3 ft. healed face
24" hemlock bears N.62°E., 19.8 ft. healed blaze.

119

East 1/4 Corner for Section 13 only of T21-11
Found - 1 1/2" iron pipe with brass cap (1919 GLO)
Set - 2 1/2" x 30" alum pipe 3" above ground with mound of stone, with
3 1/4" alum. cap mkd "USDA Forest Service T21S R10W R11W 1/4 S13
RLS 1651 1984 Unlawful to Disturb". Brass cap buried alongside.
Found - 12" hemlock bears S.70°W., 7.8 ft. visible scribe "S: in partially
healed face.
14" hemlock bears N. 2 1/2°W., 31.7 ft. chopped open face
visible BT.
Fir snag, now badly rotted bears N.65°W., 4.0 ft.

Herman Pieske, RLS #1651
AA Surveying Services, Inc.
For: U. S. Forest Service
November 1984
M 97 - 77 A & B

RE-PECTED

#108

#124