

Douglas County Surveyor's Record of
Government Corners Renewed

T 21

T. S.

R 10

R.W.W.M.

KORE-CHAPMAN CO., EUGENE, ORE. 97501

120

Herman Pieske
RLS #1651
AA Surveying Service
For: U.S. Forest
Service
November 1984
M 97 = 77 A & B

Section corner for Sections 18 and 19 only.
Found - 1919 GLO brass cap properly marked
Set - 2 1/2" x 30" alum pipe flush in 18" mound of stone, with 3 1/4" alum cap mkd. "USDA Forest Service T21S R10W R11W S18 S19 RLS 1651 1984 Unlawful to Disturb". Buried brass cap alongside.
Found - 60" D. fir bears N.27°E., 50.2 ft. healed face.
30" hemlock bears S.75°E., 13.9 ft. healed face (rec. S.83°E.)

Section corner for Sections 13 and 24 only of T.21-11 #125 121
Found - 50" D. fir corner tree, healed faces on north and south sides
Bark scribes "R11W S24" visible on south side; "S 1" visible on NW side.
46" Obl. D. fir bears S.64°E., 41.0 ft. Axe work on bark (tag reads obliterated N.55°W., 63.41 ft.) (Rec. S.55°E 63.4 ft.)
54" D. fir bears S.22°W., 25.2 ft. with healed face.
30" D. fir bears N.89°W., 17.9 ft. healed burly face.
50" Obl. D. fir bears N.73°E., 18.5 ft. small healed face.
Set - Reference monument, a 2 1/2" x 30" alum pipe 25" in ground with 3 1/4" alum cap mkd. "USDA Forest Service T21S R11W S19 RM N 89° 44' W 6.0 ft. RLS 1651 1984 Unlawful to Disturb"., bears S.89°44'E., 6.0 ft.

RE-RECORDED CORNER NO.

122

South 1/4 Corner for Section 31 Only.
Found - 1" iron pipe, set by GLO, in 1919.
BT's - 56" Hemlock, bears N.2°E., 29.0 ft., rotten face. (Orig)
50" D. Fir stump, bears N.60°W., 19.1 ft., visible scribe. (Orig)
Set - A U.S. Dept. of Agriculture brass cap, mkd. T21S R10W 1/4 S31 T22S R10W PLS 1305 1985.

123

West 1/4 Corner for Section 31 Only.
Found - A 1" x 30" iron post set by GLO in 1919 at corner position. Cap has been broken off. Buried pipe.
BT's - 38" Maple, bears N.80°E., 33 ft., no marks.
Set - A U.S. Forest Service 3 1/4" aluminum cap with magnet on a 2 1/2" x 30" aluminum flared pipe. Mkd. T21S R11W R10W 1/4 S31 1985 PLS 1305. Rockmound.
New BT's-12" Maple, bears N.67°E., 88.5 ft., scribed 1/4 S31 BT.
18" Maple, bears S.19°E., 49.1 ft., scribed 1/4 S31 BT.

124

East 1/4 Corner Section 13 Only. T21S R11W
Found - 3-1/4" USDA-FS Aluminum cap properly marked Ren #119
BT's -
Found - 12" Hemlock bears S70°W, 7.8' (rec.7.9'), partially closed face visible "S".
18" D. Fir snag bears N65°W, 4.0'.
14" Hemlock bears N2 1/2°W, 31.7', open face, visible "BT"
Set - 2 1/2" x 30" Aluminum pipe with 3 1/4" USDA-FS Aluminum cap marked " R M T21S R10W S1°26'W, 40.7', S18, 1986, P.L.S. 497.

125

Section Corner for sections 13 & 24 T21-11 Ren #121
Found - 36" D Fir Corner Tree. Healed faces on North and South sides bark scribed "R11W S24" visible on South "S 1" visible on the N.W. side.
Set - 2 1/2" x 30" Aluminum pipe with a 3-1/4" USDA-FS Aluminum cap marked "T21S R11W S19 RM N89°44'W, 6.0', R.L.S. 1651 1984.
BT's
Found - 46" Obliterated D. fir bears S64°E, 41.0', (rec. S55°E, 63.4')
Axe work on bark.
54" D. Fir bears S22°W, 25.2' (rec. S21°W, 29.7'), with healed face.
30" D. fir bears N89°W, 17.9' (rec. N89 1/2°W, 9.9'). With healed face.
50" Obliterated D. fir bears N73°E, 18.5', with healed face.

James W. Prochnau
PLS #1305
For: U.S. Forest
Service
August, 1985
M 99 - 21 A&B

Richard Hintz LS #497
For Siuslaw National Forest
July 1986
M 102 - 19