

Douglas County Surveyor's Record of  
Government Corners Renewed

T 21

T. S. R 10

R. W. W. M.

FOX-CHAPMAN CO., EUGENE, ORE. 9181

126

William L. Shull L.S. 909  
For. U. S. Forest Service  
October 24, 1986  
C.S. 62/30

East 1/4 Corner for Section 20 only  
Found - A weathered sandstone, 20" x 8" x 12", 12" out of ground, no marks visible, but stone had clearly been set, and was not just a natural rock. (1918 Mensch GLO survey)  
34" Douglas Fir windfall, slid down the hill, the roothole of which is approx. S.63°W., 61 links.  
29" Hemlock, a Forest Service reference tree, no marks, with signs attached and painted, S.46°E., 14.9 ft. (no record)  
Set - I replaced the stone with an alum. Forest Service monument 2½" x 30" with ¾" alum. cap marked "T21S R10W 1/4 S20 1986 LS 909", set 22" deep, using the orig. stone and its remnants as a collar.  
New BTs - I marked an 8" Hemlock, bears S.25°W., 20.1 ft. scribed "1/4 S 20 BT", with brass washer (LS 909) Land Survey Monument sign, BT sign, and red paint.  
I marked an 18" Cedar, bears S.88½°W., 30.4 ft. scribed "1/4 S 20 BT" with brass washer (LS 909), Land Survey Monument sign, BT sign, and red paint.  
Corner is on a steep (45°) North-facing slope in sparse old growth timber, about 300 ft. west of FS road #4111-144.

10/24/86

Section Corner for Sections 27 and 28 only. (north) - - - - - 127  
Found - A weathered sandstone, lying loose on the ground, no marks its position too uncertain to be considered the corner. (1918 Mensch GLO survey)  
33" D. Fir, S.64°W., 31 links (20.5 ft.) bark scribed "T21S R10..S28 CS", probably about 1968. (Ren. No. 26) A lower blaze has been cut into, with axe marks visible on the old face, but date of marks uncertain. I believe this to be the GLO BT.

Possible alder roots, rotten, S35°E., 20 links.

Set - From the standing BT, I set an alum. Forest Service monument, 2½" x 30" with ¾" alum. cap, set 25" deep, using the found stone and other sandstones as a small collar.

New BT - I marked a 20" D. Fir, bears S.33°W., 28.1 ft. scribed "T21S R10W S28 BT" with brass washer (LS 909), Land Survey Monument sign, BT sign, and red paint.

The corner is on a steep (45°) North-westerly facing slope in old growth timber and brush, about 75 ft. west of FS road #4100-147.

10/24/86

Section Corner for Secs. 25 and 36 only. 128

Found - 1919 GLO brass cap with pipe broken off.  
38" fir, N.65°W., 58.5 ft. scar vis. (1919 BT rec. N.65°W, 58.1 ft 20" hemlock, N.81°W., 20.8 ft. scribe vis. No record.

Set - 3/4" x 36" alu. rod with a ¾" alum. cap beside broken pipe.  
Buried purple magnetic marker beside 36" alum. rod. Set 72" alum. post, with land survey monument sign bolted to, beside alum. cap.

New BTs - 16" hemlock, S.42°E., 41.5 ft. scribed/painted red.  
19" hemlock, S.69°W., 6.7 ft. scribed/painted red.

Corner falls on NE slope about 125 ft. north of ridge. Ridge bears N.35°W., and S. 35°E.

12/21/89

129

East 1/4 Corner for Section 36 only.

Found - 1" iron pipe with 2½" brass cap. I.P. had rusted in two at ground level. (1919 GLO Brass cap)

48" Fir stump with old face and visible scribe bears N.79°W., 50.02 ft. to center of stump.

Set - 2" alum. cap on a 3/4" x 30" iron rod along side old monument.  
Cap stamped: Stuntzner Eng. T21S R10W E1/4 | 1990 LS 2244  
S36

New BTs - 24" Hemlock with face scribed E 1/4 S36 BT and tag bears N.68°E., 38.5 ft. to spike in side center.

A 14" Fir with face scribed E 1/4 S36 BT and tag bears S.41°E., 11.7 ft. to a spike in side center.

A 10½" Fir with face scribed E 1/4 S36 BT and tag bears s.40°W., 23.5 ft. to a spke in side center.

About 2 miles up Wells Creek take spur to the West about 1 mile to point where road crosses line between Secs. 36 and 31.

Les Roberts  
L.S. #1039  
For: I. P. Co.  
December, 1989  
M 109-42  
C.S. 63/102

Harvey Wilcox  
L.S. #2244  
For: Stuntzner Eng.  
Sept. 5, 1990  
C.S. 63/104