

**Douglas County Surveyor's Record of
Government Corners Renewed**

21 T. S. 10 R. W. W. M.

KOKE-CHAPMAN CO. EUGENE, ORE. 21881

L.E. Monrean
P.L.E.
D.L.S.
CS 57/39
11/5/75

Witness Corner to Closing corner Sec.1 T21-10. Sec.6 T21-9 43
Found A Cedar 40" now 52" in dia. bears S42°E., 44.5 ft (rec. 46.2ft) Blazed
A cedar 45" now 55" in dia. bears N38°W., 21.8 ft. scribed "WCC T21S R9 & 10W"
Maple bearing tree not found, bearing and distance recorded falls in large
growth of maples in slide area.
Set: Brass cap at witness corner to closing corner stamped,

COUNTY SURVEYOR'S OFFICE
1975

T 20 S R 9 W
CC
S 1 | S 6
R 10 W | R 9 W

Note: Corner lies near south bank of Smith River, Nearly directly across
river from fence running North & South at East end of Fawn Creek Park
11/5/75

Section Corner between 35 & 36 only T20-10 44

Found: U.S. GLO Brass cap (1951) properly marked:
The 1892 bearing trees noted during the 1951 resurvey are both down.
We find them to be in their record positions.

BT's- A 31" D Fir bears west 30.2 ft. scribed "T 20S R10W S35 CS BT" on a
double blaze. A 25" Hemlock N 37°W., 31.9 ft scribed "T20S R10W S-35 CS BT"
on a double blaze.

Note: The NE Corner of Sec.2 T21S R10W A brass cap bears S89°15'E., 86.5 ft.
This corner is located on top of a ridge at the SW corner of a clear cut unit.
Compass declination setting: 20° East. 11/12/75

1/4 Corner for Secs. 10 and 15 45

Found - 1919 GLO brass cap, broken off, 1" I.P. filled with concrete.
From which:

An orig 40" now 49" D. Fir bears S.35°W., 6.6 ft. (call S.29°W. 6.6 ft.)
alive with well healed blaze.

A rotted alder stump bears N.2°E., 13.2 ft. (call N.6°E., 13.2 ft.)

Set - At true corner point: A 1 1/2 x 30" I.P. with brass cap stamped:
Douglas County Surveyor T21S R10W
1976 1/4 S10
S15

Put 1" I.P. on south side of brass cap .

New BT - A 18" Hemlock bears N.56°E., 55.8 ft. scribed "1/4 S10 CS BT" in
double blaze.

Note: Fd. BLM BT tag on 12" Hemlock which bears N.44°E., 11.0 ft. from cor.
Cut into scar, fd. no trace of scribing. Tree would have been 2" when line
was surveyed in 1919. Took BLM tag off. Tree is not a BT.

4/12/76

Center 1/4 Corner for Sec. 10 46

Set - 5/8" Iron Rod from which I scribe:

72" Fir, N.58°E., 52 feet.
58" Fir, S.34°E., 49 feet.

Section corner to sections 9, 10, 15, and 16 47

Found - Orig, stone, a sandstone, firmly set, extending 10" above ground
with 4 notches on the south edge, and 3 notches on the east edge.

Also found badly rusted 2" I. pipe, loosely set, extending 16"
above ground, with brass cap attached, marked U.S. General Land
Office Survey T21S R10W S9 S10 S16 S15 1918 (Record, 1919)

Orig. 12" hemlock, now 38 " bears S. 73° E., 12.5 ft. (Record,
S33°E 12.5 ft.) and (Rec. 1919 Resurvey S. 73° E., 12.5 ft.)
with illegible 1919 rescribe marks visible on partially healed
blaze which faces approx. N. 30° W.

From 1919 resurvey, a rotting alder root shell bears N. 68° E., 52.8
ft.

A 24" hemlock, now 38" bears N. 23° W., 23.8 ft. with illegible
scribe marks on a partially healed blaze.

Set - A 1" x 30" I. pipe, 26 " in the ground, with brass cap , marked
DOUGLAS COUNTY SURVEYOR T21S S9 S10 S 16 S 15 R 10 W 1977
GLO brass cap and stone alongside.

New BT's A 12" hemlock bears S. 18° W. 19.4 ft. with double blaze and
scribe "T21S R10W S16 CS BT"

9-13-77

Lenora Ladig
Gary Langlitz
Clell Goodwin
A Vic. Cangle
11/12/75
CS 57/39

JAN 76

M. Lenora Ladig
P. Earle
D. Stewart
4/12/76
C.S. 59/8

Ronald E. Stuntzner
For: International
Paper Company
Jan. 12, 1977
M 62 - 78

Gary Langlitz
Stephen J. Flause
C.S. file 59/40
9-13-77

RE-REVIEWED SET CORNER NO. #82