

Douglas County Surveyor's Record of  
Government Corners Renewed

T 21

T. S.

R 10

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97401

Karen Reed, Deputy, Douglas County Surveyors Office  
Witness: John Powell  
August 17-18, 1983  
C.S. 62/1

62

North 1/4 corner, Section 10 only.

Found - 1919 GLO brass cap properly marked on a 1" diam. concrete filled iron pipe. Top 1 foot of pipe broken off, remaining portion firmly set in ground. Condition of pipe is badly rusted. An orig. 12" Alder, now 17" bears S.28°W., 9.2 ft. (Rec. S.15°W.) with well healed single blaze. (This tree is leaning in a NW direction.

A 12" hemlock, now 15" bears S.83°E., 22.8 ft. scribed "S10 1/4" in a single blaze per survey M 62 - 78 DCSO survey records.

A 10" hemlock now 13" bears N.36°E., 16.3 ft. scribed "1/4 S10" in a single blaze per survey M 62 - 78 DCSO survey records.

Set - Although the orig. BT was off bearing, the iron pipe was firmly set and appeared undisturbed. Therefore I drive a 1 1/2" x 30" iron pipe with brass cap stamped "Douglas Co. Surveyors Office" T21S R10W 1/4 S10 1982. in the position of the pipe. I drive orig. pipe along the west side of brass cap and bury the top 1 ft. of orig. pipe with cap along southerly side of new brass cap.

No new BTs, Corner falls on steep north slope. Land south of corner to be logged.

8/18/82

63

1/4 Corner for Secs. 4 and 9

Found - 1919 GLO Iron pipe with properly marked brass cap rusted off. I.P. is firmly set with with brass cap lying alongside. (notes call for date on cap to be 1919 but I find 1918.)

Orig. 30" fir now 42" with good scar bears S.20°E., 12.7 ft. (rec. S.25°E., 8.6 ft.)

Orig. 18" fir now 26" rotted snag 10 ft. tall. No scribing or face visible, bears N.48°W., 12.4 ft. (rec. N.42°W., 13.9 ft.)

Set - At the location of the found I.P. I set a 1" x 30" I.P. with brass cap attached Cap marked "Douglas Co Surveyor T21S 1/4 S4 S9 R10W 1982". I place remains of old pipe along west side of new pipe and bury old brass cap along east side.

New BTs - 15" fir scribed "1/4 S9 CS BT" in double blaze bears S.3°W., 11.7 ft.

5" hemlock scribed "1/4 S4 CS BT" in double blaze bears N.30°W., 25.2 ft.

8/18/82

64

East 1/4 Corner, Section 4 only.

Found - 1919 GLO 1" I.P. with brass cap, properly marked, rusted off. Iron pipe is firmly set with brass cap lying alongside.

Possible orig. 12" alder now 16" leaning to the SW with well healed scar bears S.59°W., 28.5 ft. (Rec. S.60°W. 27.7 ft.)

I add bark scribing "CS BT" below scar.

Set - At the location of found 1" I.P., I set a 1" x 30" I.P. with brass cap attached marked "Douglas Co Surveyor T21S 1/4 S4 R10W 1982". I place remains of old I.P. along west side of new pipe and I bury found brass cap along east side.

New BT's - 11" alder bark scribed "1/4 S CS BT" bears S.17°E., 24.2 ft.

1/2" Iron rod protruding 3 ft. out of ground with an International Paper Company property line sign, bears S.3°W., 3.0 ft.

Note - 1/4 Section 3 only, bears N.3°E., 69.7 ft.

8/17/82

65

West 1/4 Corner, Section 3 only.

Found - 1919 GLO 1" I.P. with brass cap properly marked, rusted off. I.P. is firmly set and brass cap is lying alongside.

Orig. 40" double fir, now 65" (at base) with good scar, bears N.10°E., 39.6 ft.

Orig. 30" fir, now 36" windfall with good scar, bears S.5°E., 35.6 ft. to broken off stump.

Set - At the location of the found 1" I.P. I set a 1" x 30" I.P. with brass cap attached marked "Douglas Co. Surveyor T21S 1/4 S3 R10W 1982". I place remains of old pipe along west side of new pipe and bury old brass cap along south side.

New BT's - 7" alder bark scribed "1/4 S CS BT" bears S.42 1/2°W., 15.8 ft.

1/2" Iron rod protruding 3 ft. out of ground with International Paper Company property line sign bears N.10°E., 3.0 ft.

Note - 1/4 corner Section 4 bears S.3°W., 69.7 ft.

8/17/82