

Douglas County Surveyor's Record of
Government Corners Renewed

T 21 T. S. R 10 R.W.W.M.

HOKE-CHAPMAN CO., EUGENE, ORE. 97401

66

Karen Reed, Deputy
Douglas Co.
Surveyors Office
John Powell
Aug. 17, 1982
C.S. 62/1

Section corner for Secs. 3, 4, 9 and 10
Found - A 1" diam. concrete filled iron pipe badly rusted protruding .9 ft. above ground. No evidence of 1919 brass cap.
An orig. 36" diam. fir now 60" bears N.10°E., 9.9 ft. dist. with a well healed single blaze. (1919 RESURVEY) 10/25/82 J.R.
An orig. 7" diam., hemlock, now 26" bears S.45°W., 45.5 ft. (rec. S.42°W.) with a well healed single blaze. (1919 RESURVEY) J.R.
An orig. 60" diam. fir, now 62" bears N.40°W., 31.2 ft. dist. (rec. 30.4 ft.) with a well healed single blaze. (1919 RESURVEY) J.R.
Set - I reference out iron pipe and replace said pipe with a 1" x 30" iron pipe with brass cap marked "Douglas Co. Surveyor Office: T21S R10W S4 S3 S9 S10 1982". protruding 6" above ground in a 1.5 ft. diam. mound of stone. I lay rusted pipe along east side of brass cap.
New BT - A 17" maple the center trunk of a triple trunk tree, scribed "T21S R10W S10 CS BT" in a double blaze bears S.27°E., 18.9 ft. dist. Bearing and dist. taken to center of root crown.
Corner falls on a moderately steep west slope.

8/17/82

Section corner for Secs. 4, 5, 8 and 9. #80 67
Found - 1919 GLO I.P. with brass cap broken off and lying on rock mound. 34" cedar stump bears N.34°00'W., 26.4 ft. (Rec. N.32°W., 27.1 ft.) 1919 BT.
24" uprooted cedar bears S.36°W., 32.0 ft. 1919 BT.
No trace of the NE & SE 1919 BTs. See Ren. #59
New BTs - 30" alder bears S.48°45'E., 39.5 ft. scribed S9 BT.
12" maple bears S.39°00'W., 12.9 ft. scribed S8 BT.
Tie my iron pipe, M 91 - 24, S.7°19'W., 15.07 ft. and then remove.

1/4 Corner for secs. 8 and 9. 68
Found - 1919 GLO iron pipe with brass cap, broken off & lying at the base of the I.P.
18" alder bears N.43°00'W., 27.0 ft. (Rec. 26.4 ft.) 1919 BT, bark scribing plainly visible.
No trace of the NE alder 1919 BT.
Set - 1 1/4" x 36" I.P. with brass cap stamped "PLS 497 1/4 S8 . S9 1983 T21S R10W" over the remains of the GLO I.P.
New BT - 20" alder bears N.23°45'E., 43.1 ft. scribed 1/4 S9 BT.

Section corner for Secs. 8, 9, 16 and 17. #91 69
Found - 1919 GLO I.P. with properly mkt. Brass cap and stone alongside.
16" maple bears N.73°00'E., 8.0 ft. (Rec. N.61°E., 8.6 ft.) 1919 BT
24" fir bears S.89°15'E., 27.4 ft. (Rec. S.71°E., 27.7 ft.) 1919 BT.
SW alder BT is gone.
NW fir BT is down.
New BTs - 28" fir bears S.57°30'W., 21.8 ft scribed S17 BT.
20" fir bears N.12°45'W., 42.5 ft. scribed S8 BT.

Center 1/4 For section 9. 70
Set - 1 1/4" x 36" I.P. with brass cap stamped PLS 497 C 1/4 . S9 1983 T21S R10W.
New BTs - 20" alder bears N.47°15'E., 18.1 ft. scribed C 1/4 S9 BT.
30" alder bears N.70°45'W., 20.0 ft. scribed C 1/4 S9 BT.

1/4 Corner for Secs. 9 and 16. 71
Found - Unrecorded 1918 GLO iron pipe with brass cap attached to upper 12" of pipe and broken off at the ground line.
28" cedar bears N.40°30'E., 8.5 ft. with healed face.
46" fir bears S.16°00'E., 30.6 ft. with healed face.
Set - 1 1/4" x 36" I.P. with brass cap stamped "PLS 497 1/4 S9 . S16 1983 T21S R10W" over the remains of the GLO I.P.

8/83

Richard J. Hintz, P.L.S. #497
For: International Paper Co. and U.S. Forest Service
August 1983
M 95 - 4