

Douglas County Surveyor's Record of  
Government Corners Renewed

T 21

T. S. R 10

R. W. W. M.

KOKE-CHAPMAN CO., EUBENE, ORE. 21051

78

C O N T - -

- New BTs - 10" D. fir bears S.48 1/2°W., 9.1 ft. blazed and scribed "T21S R10W S7 BT".
- 16" D. fir bears N.44°W., 24.3 ft. blazed and scribed "T21S R10W S6 BT".
- 8" D. fir bears N.44 1/2°E., 44.2 ft. blazed and scribed "T21S R10W S5 BT".
- 10" D. fir bears S.41°E., 18.6 ft. blazed and scribed "T21S R10W S8 BT".

79

1/4 Corner for Sections 5 and 8.

- Found - 2 1/2" iron pipe rusted through and broken off with 2 1/2" GLO brass cap next
- 28" cedar bears N.2°W., 21.8 ft. partially healed face.
- 14" big leaf maple root hole bears S.5°W., 27.1 ft. (tree is downhill).
- 38" D. fir bears N.19°E., 33.7 ft. Shows good scar. **#134**
- Set - 2 1/2" x 30" alum. pipe in position of found pipe, with large mound of stone, with 3 1/4" alum. cap mkd. "USDA Forest Service T21S R10W S5 1/4 S8 1983 RLS 1651 Unlawful to Disturb". Buried old pipe and cap.
- New BT - 7" big leaf maple bears S.69°W., 37.7

80

Section corner for Sections 4, 5, 8 and 9.

- Found - 1 1/2" iron pipe filled with concrete and rusted through with 2 1/2" brass cap next to. Found rock mound around pipe. Cap is 1918 GLO cap. Ren. #67
- 30" alder bears S.50°E., 40.3 ft. shows bark scribing "S9 BT"
- 10" maple bears S.34°W., 13.6 ft. show scribing "S8 BT" on open face.
- 30" ± cedar stump bears N.32°W., 24.8 ft. very rotten, shows axe marks.
- Set - 2 1/2" x 30" alum. pipe at position of found pipe, with 3 1/4" alum. cap mkd. US Forest Service T21S R10W S5 S4 S8 S9 RLS 1651 1983 Unlawful to Disturb".
- New BTs - 13" alder bears N.87°W., 21.1 ft. bark scribed "T21S R10W S5 BT".
- 29" alder bears N.34°E., 233.2 ft. bark scribed "T21S R10W S4 BT".

81

South 1/4 corner for section 3.

- Found - iron pipe with 1919 GLO brass cap, pipe rusted and broken off and laying next to it.
- 12" hemlock stob, very decayed, bears N.14°W., 9.9 ft.
- Set - 2" alum. pipe, 26" in the ground, over rusted iron pipe & brass cap mkd. "USDA Forest Service T21S R10W 1/4 S3 RLS 1651 1983 Unlawful to disturb". Buried iron pipe & brass cap alongside alum. pipe.
- New BTs - 15" hemlock bears N.67°W., 27.9 ft. blazed and scribed "1/4 S3 BT".
- 7" cedar bears N.5°W., 35.4 ft. blazed and scribed "1/4 S3 BT".

82

Center 1/4, Section 10

- Found - 5/8" iron rod with 1" plastic cap mkd "C 1/4 S10 PE 6245". Ren.46
- 74" D. fir bears N.57°E., 55.5 ft. bark scribes "BT C 1/4".
- 55" D. fir bears S.37°E., 51.3 ft. healed face. Ren. #46
- Set - 2 1/2" x 30" alum. pipe in the ground with 3 1/4" alum. cap mkd. "USDA Forest Service T21S R10W C 1/4 S10 RLS 1651 1983 Unlawful to Disturb". Buried 5/8" iron rod alongside.
- BT - Rescribed: 74" D. fir bears N.57°E., 55.5 ft. bark scribes "BT C 1/4" visible. Added "S10" marks.

Herman Pieske, LS 1651  
 AA Surveying Service, Inc.  
 For: US Dept. of Agriculture, Forest Service  
 November 1983  
 M 95 - 59 A and B.

Herman Pieske  
 L.S. 1651  
 For. US Forest  
 Service  
 December 1983  
 M 95 - 79 A&B