

Douglas County Surveyor's Record of
Government Corners Renewed

M.W.W.M. T 21 T.S. R 10 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97501

83

West 1/4 Corner Section 11

- Found - 1" iron pipe with 2 1/2" brass cap, loose and sloping mkd.
County Surveyors Office T21S 1/4 11 R10W 1968. Ren. #4
- Set - Reset pipe in original position and constructed large mound of
stones.
- BTs - 16" hemlock bears S.26°E., 19.4 ft. blazed and scribed "1/4 S11 BT"
6" alder bears S.74°E., 48.3 ft. bark scribed "1/4 S11 BT".

Herman Pieske
L.S. #1651
For: U.S. Forest
Service
Dec. 1983
M 95 - 79 A&B

84

Section corner for Sections 11 and 14 only.

- Set - 2 1/2" x 30" alum. pipe, 20" in the ground with stone mound.
with alum. cap mkd. "US Dep of Agri. Forest Service
S11 S14 RLS 1651 1983 Unlawful to Disturb".
- New BTs - 16" cedar bears S.22°E., 16.3 ft. faced and scribed "T21S
R10W S14 BT".
30" hemlock bears N.12°40'E., 179.0 ft. faced and scribed
"T21S R10W S11 BT".

85

1/4 Corner for Sections 15 and 16

- Found - 1919 GLO brass cap, badly rusted 1" iron pipe filled with
concrete, properly marked. (No record of this cap mentioned
in Collier and Mensch's 1919 notes).
- Set - Corner replaced with 2 1/2" x 30" alum. pipe, 24" in the ground
with 3" alum. cap mkd "US Dep of Agri-Forest Service T21S
R10W 1/4 S16 S15 RLS 1651 1983 Unlawful to Disturb". Buried
GLO monument North of new pipe.
- New BTs - 17" cedar bears S.50°W., 34.6 ft. faced and scribed "1/4 S16 BT".
30" cedar bears S.80°E., 3.7 ft. faced and scribed "1/4 S15 BT".

86

West 1/4 Corner for Section 14

- Set - 2 1/2" x 30" alum. pipe 28" in the ground, with 3 1/4" alum.
cap mkd. "USDA Forest Service 1/4 T21S R10W S14 RLS 1651 1983
Unlawful to Disturb" with rock mound.
- BTs - 36" cedar bears N.35°E., 103.4 ft. scribed "1/4 S14 BT".
27" alder bears S.12°E., 44.4 ft. bark scribed "1/4 S14 BT".

87

East 1/4 corner for Section 15 only.

- Found - Badly usted iron pipe filled with concrete (1") No cap found.
20" D. fir bears S.25°W., 14.9 ft. healed face.
30" D. fir, uprooted and slid downhill, bears S.74°W., 15.0 ft.
(to root wad).
- Set - 2 1/2" x 30" alum. pipe, 10" above ground, with 3 1/4" alum. cap
marked "USDA Forest Service T21S R10W 1/4 S15 RLS 1651 1983
Unlawful to Disturb".
- New BT - 28" D. fir bears N.28°W., 37.0 ft. scribed "1/4 S15 BT" on
double blaze.

88

Section corner for Secs. 15, 16, 21 and 22.

- Found - Badly rusted pipe with 1918 GLO brass cap, properly marked.
15" alder, growing out of old stump, bears N.50°W., 57.6 ft.
Possible original BT.
55" hemlock bears N.73°E., 23.3 ft. visible scar and some axe
marks.
- Set - 2 1/2" x 30" alum. pipe, 24" in the ground with 3 1/4" alum.
cap mkd. "US Dep of Agri-Forest Service T21S R10W S16 S15
S21 S22 RLS 1651 1983 Unlawful to Disturb".
- New BTs - 33" alder bears S.59°W., 95.2 ft. bark scribed "T21S R10W S21 BT".
52" Cedar bears S.12°E., 56.0 ft. faced and scribed "T21S R10W
S22 BT".

Herman A. Pieske, RLS #1651
For: Siuslaw National Forest, USDA
December, 1983
M 95 - 80 A & B